

**Repair Estimate**

Date : 06/01/2021

Reference: SJQ 5017L

To Whom It May Concern

Make: Toyota  
Mark X

Dear Sir,

TP ALG

**RE: VEHICLE .: SJQ 5017L****CHASSIS NO.: GRX1203061863****ENGINE NO.: 4GR0472436**

Juspes.

Name of insured .: Tan Heong Cheng

Date of accident.: 28/12/2020

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

**Parts**

| <u>No.</u> | <u>Qty</u> | <u>Part Description</u>                       | <u>Price (SGD)</u> |
|------------|------------|-----------------------------------------------|--------------------|
| 1          | 1          | FRT BUMPER <i>Regr</i>                        | 650.00 +           |
| 2          | 1          | FRT BUMPER SIDE RETAINER RH - UPP <i>Regr</i> | 67.00 +            |
| 3          | 1          | FRT BUMPER BRACKET RH <i>Regr</i>             | 70.00 +            |
| 4          | 1          | LH HEADLAMP <i>Regr</i>                       | 730.00 +           |
| 5          | 1          | FRT FENDER RH <i>Dented</i>                   | 760.00 ✓           |
| 6          | 1          | FRT FENDER BRACKET RH <i>Regr</i>             | 70.00 +            |
| 7          | 1          | FRT FENDER SIGNAL LAMP RH <i>Regr</i>         | 68.00 +            |
| 8          | 1          | FRT FENDER QUARTER GARNISH RH <i>Regr</i>     | 70.00 +            |
| 9          | 1          | FRT FENDER INNERSHIELD RH <i>Dented</i>       | 280.00 ✓           |
| 10         | 1          | FRT DOOR RH <i>Dented</i>                     | 1250.00 ✓          |
| 11         | 1          | FRT DOOR WEATHER STRIP RH <i>Regr</i>         | 189.00 +           |
| 12         | 1          | FRT DOOR GLASS OUTER MLDG RH <i>Regr</i>      | 130.00 +           |
| 13         | 1          | RR DOOR RH <i>Dented</i>                      | 1200.00 ✓          |
| 14         | 1          | REAR DOOR WEATHER STRIP RH <i>Regr</i>        | 189.00 +           |
| 15         | 1          | REAR DOOR GLASS OUTER MLDG RH <i>Regr</i>     | 130.00 +           |
| 16         | 1          | REAR FENDER RH <i>Dented</i>                  | 890.00 ✓           |
| 17         | 1          | REAR BUMPER <i>Regr</i>                       | 700.00 +           |

Parts Total: 7,443.00

Less 25%: 1,860.75

Total : 5,582.25

**Labour**

| <u>No.</u>            | <u>Labour Description</u>                                                                                                                                | <u>Price (SGD)</u>      |
|-----------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|
| 1                     | To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. Per day \$ 200 | 1500.00 <del>1000</del> |
| 2                     | Carry out spray painting on accident affected area. ( Frt Bumper, RHF & RHR Door & fender , Rear bumper, ) Per Panel \$200                               | 1400.00 <del>1200</del> |
| 3                     | To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair                           | 80.00 <del>30</del>     |
| 4                     | Transfer of internal mechanism from old door panel to new door panel x2                                                                                  | 200.00 <del>160</del>   |
| 5                     | To remove and refix rear windscreen                                                                                                                      | 120.00 ✓                |
| 6                     | To remove and refix reverse sensor and conduct test                                                                                                      | 80.00 <del>50</del>     |
| <b>Labour Total :</b> |                                                                                                                                                          | <b>3,380.00</b>         |

**Other**

| <u>No.</u>           | <u>Other Description</u> | <u>Price (SGD)</u> |
|----------------------|--------------------------|--------------------|
| 1                    | Sealant                  | 50.00 ✓            |
| 2                    |                          |                    |
| <b>Other Total :</b> |                          | <b>50.00</b>       |

Total : \$9,012.25  
 Gst (7%) : \$630.86  
**GRAND TOTAL: \$9,643.11**

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully



Service Advisor  
 Ronnie Tan Hp 94577916  
 DID: 6844 1985 Fax: 6844 5185

Adrian L  
 L/S 07/01/21  
 07 Days.

total: 5895  
 L/S: A7K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: