

N51**2 Kaki Bukit Ave 2, #01-17 & 18,
Singapore 417921****Insurer Reference:****Repairer Reference: 038894****Date calculated: 18/01/2021 4:24 PM**TPAXA.
Jasper.**Full Report****Registration: SLZ3908H****Printed: 18/01/2021 4:24 PM****Summary Information****Claim**

Location: Singapore (SG)

Printed by: N51 User01

Claim Reference:

Estimated Repair Time: 4

Actual Repair Days:

Work Provider:

Currency:

Date of Incident:

Hire Car Start:

Hire Car End:

AXA Insurance Pte Ltd

SGD

05/01/21

Vehicle Details**Vehicle**

Manufacturer:

Model:

Sub Model:

Model Sheet Number:

Registration:

VIN number:

Odometer:

Model Specs

FROM 03/2018

TOYOTA

PRIUS +

BASE MODEL

70 A4 54

SLZ3908H


TWO COAT METALLIC

PREPARE OFF VEHICLE

Vehicle Condition**Vehicle Status**

Pre-Accident Damage:

Date of Inspection:

Damage AreasAll ☐Underbody ☐**Labour**

Time Base 10 WU/h

Price = 50.00 SGD/h

Code	Description	WU	Price SGD
1900 11)	DETACH + REFIT BATTERY CABLE INCLUDES: R + R BOOT STORAGE BOX AND NECESSARY ATTACHED PARTS	2.0	10.00
B410)	R + R REAR BUMPER	4.0	20.00
B420)	RENEW REAR BUMPER (REMOVED)	1.0	5.00
NO NUMBER	R + R REAR BUMPER REINFORCEMENT	2.0	10.00
7439 21	R + R END PANEL TRIM	2.0	10.00
NO NUMBER	R + R R/BOOT FLOOR COVER	2.0	10.00
2711	REAR PANEL REPAIR	30.0*	150.00 <i>50</i>
Labour Cost		Hrs	WU
Panel / Mechanical Labour		4.30	43.0
Total of Labour			215.00

Paint

Paint Work		Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD
3860	REAR BUMPER N- PART PAINT ST K1G	22.0	110.00
3790	REAR PANEL REPAIR PAINT ST III	11.0	55.00
3010	L/R SIDE PANEL SURFACE PAINT ST 2	6.0	30.00 <i>x</i>
3010	R/R SIDE PANEL SURFACE PAINT ST 2	6.0	30.00 <i>+</i>
NO NUMBER	PREPARE FOR PAINTING	21.0	105.00
NO NUMBER	PAINT PREPARATION FOR PLASTIC PARTS (COMPOSITE WORK)	8.0	40.00
Total Paint		Hrs 7.40	WU 74.0
			Price SGD 370.00

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Part Source	Price SGD
2619	L/R BUMPER BRACKET	52156 47010	Original <i>not xler</i>	139.60 <i>x</i>
3339	L/R REFLECTOR	81920 47010	Original	58.00 <i>x</i>
3904	R/LOAD FLOOR COVER	57627 47020	Original <i>Deformed</i>	179.00 <i>✓</i>
2620	R/R BUMPER BRACKET	52155 47010	Original <i>xc</i>	139.60 <i>✓</i>
3340	R/R REFLECTOR	81910 47010	Original <i>xc</i>	58.00 <i>+</i>
2583	REAR BUMPER	52159 47912	Original <i>Deformed</i>	523.90 <i>✓</i>
2640	REAR BUMPER REINF	52023 02140	Original <i>Deformed</i>	205.70 <i>✓</i>
2587	REAR BUMPER SPOILER	76891 47040	Original <i>Deformed</i>	325.00 <i>✓</i>
Savings				0.00
Subtotal				1,628.80
Subtotal Discount(+50.00%)				-814.40
Total				814.40

f: OEM Parts
n: Non-OEM Parts
u: Used parts

Extras

Code	Description	Price SGD
------	-------------	-----------

Code	Description	Price SGD
1000	RR Bumper Clips <i>mm</i>	50.00* <i>30</i>
1001	RR Reverse Sensor <i>mm</i>	250.00* <i>20</i>
1002	Anti-Rust Coating	80.00* <i>30</i>
1003	RR Bumper Spoiler Clips <i>mm</i>	50.00* <i>30</i>
Total Extras		430.00

Final Calculation

	SGD	SGD
Parts	1,628.80	
Total Discount(+50.00%)	-814.40	
Total Parts		814.40
Labour Time Base 10 WU/h		
Total 43.0 WU X 50.00 SGD/h	215.00	<i>115.00</i>
Total of Labour		215.00
Total Of Extras	<i>260.00</i>	430.00
Paint Work Time Base 10 WU/h		
Labour Cost 74.0 WU X 50.00 SGD/h	370.00	<i>310.00</i>
Total Paint Including Material		370.00
Repair Cost Excludes GST		1,829.40
GST (+7.0%)		128.06
Repair Cost Included GST		1,957.46

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Adrian Lj
h/s 18/01/21
03 days