

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV13651/TAN KIAN SIONG (CHEN JIANXIONG)
	Reg No/Reg Date	SMX1126J / 28/12/202
	Date In/Mileage	/ 0
	Chassis No	KNARH81BVM5066376
	Engine No	D4HELH262447
	Make/Model	KIA/SORENTO 2.2 A D SX SR G898
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	08/01/2021/ 09:27	QUK	282 / Kevin Leong	26959			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1600.00
REPLACE REAR RH DOOR, REAR BUMPER LOWER & AFFECTED AREA								
REPAIR ON REAR BUMPER & REAR RH FENDER								
E PNT98000								1050.00
PAINT WORK ON REAR BUMPER, REAR RH FENDER & REAR RH DOOR								
E PNT98000								1050.00
PAINT WORK ON REAR BUMPER, REAR RH FENDER & REAR RH DOOR								
E PNT88000								120.00
REMOVE & INSTALL REAR PARKING ASSIST								
M SUNDRY								80.00
PERFORM RUST PREVENTION								
E PNT88000								120.00
TO TRANSFER REAR RH DOOR ATTACHMENT TO NEW PANEL								
A 54900099								30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
A WHEELALIGNMENTBP								120.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								30.00
TO TRANSFER REAR RH RIM INCLUDING BALANCING								
M SUNDRY								50.00
SUNRIES								
M COVER-RR BUMPER LWR					1.00	565.00	20.00	452.00
M GARNISH ASSY-QTR SIDE,RH					1.00	38.00	20.00	30.40
M GARNISH ASSY-RR DR SIDE,RH					1.00	210.00	20.00	168.00
M PANEL ASSY-REAR DOOR,RH					1.00	1290.00	20.00	1032.00
M W/STRIP ASSY-RR DR SIDE RH					1.00	76.00	20.00	60.80
M W/STRIP-RR DR BELT I/S RH					1.00	24.00	20.00	19.20
M W/STRIP ASSY-RR DR BELT O/S RH					1.00	88.00	20.00	70.40
M MOULDING ASSY-RR DR FRAME,RH					1.00	38.00	20.00	30.40
M GARNISH ASSY-RR DR RR FRAME,RH					1.00	48.00	20.00	38.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV13651/TAN KIAN SIONG (CHEN JIANXIONG)
	Reg No/Reg Date	SMX1126J / 28/12/202
	Date In/Mileage	/ 0
	Chassis No	KNARH81BVM5066376
	Engine No	D4HELH262447
	Make/Model	KIA/SORENTO 2.2 A D SX SR G898
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
LAX00000	Credit	08/01/2021/ 09:27	QUK	282 / Kevin Leong	26959	
Description of Goods / Services					Qty	Unit Price Disc% Amount
M	GARNISH ASSY-RR DR FR FRAME,RH				1.00	49.00 20.00 39.20
M	WHEEL ASSY-ALUMINIUM				1.00	799.00 20.00 639.20

Estimate

Confirm & accepted by

	Nett	6,950.00
7% GST on	6950.00	486.50
Total Payable		7,436.50

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.