



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2103082

INV Date 03/05/2021

Reference CC4/LPC21000368/Apa3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SJV 1405A
Insured Veh. GBF 6580Y
Claim No. 20/21/21/VC00/024107
Policy No. Z/20/VC00/106057
Accident Date 08/01/2021
Inspection Date 08/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21000368/Apa3q2 Date: 03/05/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 6580Y	Veh. Inspected	SJV 1405A	
Policy No.	Z/20/VC00/106057	Coverage (\$)	0.00	
Claim No.	20/21/21/VC00/024107	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	08/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI TUCSON	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	KMHJU81BMBU021859	Colour	BLACK	
Odometer	90893 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/65 R17	HABILEAD	6 mm	
L/H Front Tyre	225/65 R17	HABILEAD	6 mm	
R/H Rear Tyre	225/65 R17	HABILEAD	6 mm	
L/H Rear Tyre	225/65 R17	HABILEAD	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	08/01/2021	Inspection Date	08/01/2021	
Survey held at	CN MOTORS PTE LTD 1 KAKI BUKIT AVENUE 6 BLK C #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		16 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 1405A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	NOT NECESSARY	1,389.60	-
2	FRONT BONNET HINGE @\$38.50	NOT NECESSARY	77.00	-
1	FRONT BONNET INNER RUBBER	NOT NECESSARY	65.80	-
1	FRONT BONNET INNER LOCK	NOT NECESSARY	72.80	-
1	FRONT GRILLE	CUT	262.80	262.80
1	FRONT GRILLE EMBLEM LOGO	NECESSARY	22.00	22.00
2	FRONT HEAD LAMP @\$392.00	NOT NECESSARY	784.00	-
2	FRONT HEAD LAMP BRACKET @\$32.00	NOT NECESSARY	64.00	-
1	FRONT BUMPER	DEFORMED	537.80	537.80
10	FRONT BUMPER CLIPS @\$6.50	NECESSARY	65.00	30.00
2	FRONT BUMPER SIDE RETAINER @\$32.00	NECESSARY	64.00	64.00
1	FRONT BUMPER NUMBER PLATE	BENT	50.00	50.00
2	FRONT BUMPER FOG LAMP @\$156.80	NOT NECESSARY	313.60	-
2	FRONT BUMPER FOG LAMP CHROME @\$68.00	CUT	136.00	136.00
1	FRONT BUMPER NUMBER PLATE	REPEATED	50.00	-
1	FRONT BUMPER LOWER GARNISH	DEFORMED	88.00	88.00
8	FRONT BUMPER LOWER GARNISH CLIPS @\$6.80	NECESSARY	54.40	20.00
1	FRONT BUMPER LOWER COVER	NOT NECESSARY	128.00	-
1	FRONT BUMPER INNER SPONGE	NOT NECESSARY	125.80	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	251.80	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	786.80	-
1	FRONT AIR CON CONDENSER	NOT NECESSARY	825.00	-
1	FRONT RADIATOR	NOT NECESSARY	684.00	-
1	FRONT RADIATOR FAN MOTOR ASSY	NOT NECESSARY	574.00	-
1	REAR BOOT LID	DISTORTED	1,362.00	1,362.00
2	REAR BOOT LID HINGE	NOT NECESSARY	47.56	-
1	REAR BOOT LID SPOILER	NOT NECESSARY	330.00	-
1	REAR BOOT LID SPOILER LAMP	NOT NECESSARY	180.00	-
2	REAR BOOT LID SHOCK ABSORBER @\$72.80	DAMAGED	145.60	145.60
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	28.00	28.00
1	REAR BOOT LID HYUNDAI LOGO	NECESSARY	32.00	32.00

Report Ref No. CC4/LPC21000368/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOT LID TUCSON LOGO	NECESSARY	33.80	33.80
2	REAR BOOT LID SIDE REFLECTOR @\$218.30	CRACKED	436.60	436.60
1	REAR BOOT LID CENTER CHROME MOLDING (IX)	CRACKED	255.80	255.80
1	REAR BOOT LID NUMBER PLATE	BENT	50.00	50.00
2	REAR BOOT LID NUMBER PLATE LAMP @\$45.80	CRACKED	91.60	91.60
1	REAR BOOT LID INNER RUBBER	CUT	102.60	102.60
1	REAR BOOT LID INNER LOCK	DAMAGED	154.80	154.80
1	REAR BOOT LID INNER TRIM BOARD	CRACKED	162.80	162.80
10	REAR BOOT LID INNER TRIM BOARD CLIPS @\$6.50	NECESSARY	65.00	30.00
1	REAR BOOT LID WINDSCREEN	SHATTERED	1,255.00	1,255.00
1	REAR BOOT LID WINDSCREEN SEAL	NECESSARY	128.00	128.00
2	REAR TAIL LAMP @\$382.80	CRACKED	765.60	765.60
2	REAR TAIL LAMP PANEL @\$582.80	BUCKLED	1,165.60	350.00
4	REAR TAIL LAMP CLIPS @\$8.00	NECESSARY	32.00	32.00
1	REAR BUMPER	DISTORTED	418.70	418.70
10	REAR BUMPER CLIPS @\$6.50	NECESSARY	65.00	30.00
2	REAR BUMPER SIDE RETAINER @\$36.40	NECESSARY	72.80	72.80
1	REAR BUMPER LOWER LID	DISTORTED	210.40	210.40
2	REAR BUMPER SIDE REFLECTOR @\$225.80	CRACKED	451.60	451.60
2	REAR BUMPER SIDE REFLECTOR CHROME GARNISH @ \$106.30	DISTORTED	212.60	212.60
1	REAR BUMPER REINFORCEMENT	DISTORTED	236.80	236.80
2	REAR BUMPER REINFORCEMENT BRACKET @\$28.00	NOT NECESSARY	56.00	-
1	REAR BUMPER INNER SPONGE	CRACKED	96.80	96.80
2	REAR BUMPER MUD SHIELD @\$42.00	TORN	84.00	84.00
10	REAR BUMPER MUD SHIELD CLIPS	NECESSARY	6.30	6.30
1	REAR BUMPER INNER SPONGE	REPEATED	138.00	-
1	REAR BUMPER TOWING COVER	DISTORTED	22.00	22.00
2	REAR DOOR @\$920.60	O/S BUCKLED	1,841.20	920.60
4	REAR DOOR HINGE @\$108.80	NOT NECESSARY	435.20	-
2	FRONT L/H DOOR FRAME STICKER @\$32.00	NOT NECESSARY	64.00	-
2	REAR R/H DOOR FRAME STICKER @\$32.00	NOT NECESSARY	64.00	-
2	REAR FENDER @\$1253.80	BUCKLED	2,507.60	2,507.60

Report Ref No. CC4/LPC21000368/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER GLASS ASSY @\$379.80	NOT NECESSARY	759.60	-
2	REAR FENDER AIR -DUCT LOWER COVER @\$52.80	NOT NECESSARY	105.60	-
8	REAR FENDER AIR-DUCT LOWER COVER CLIPS @\$6.50	NOT NECESSARY	52.00	-
1	REAR R/H FENDER COWLING	TORN	215.00	215.00
8	REAR R/H FENDER COWLING CLIP @\$6.50	NECESSARY	52.00	30.00
2	REAR FENDER INNER PANEL @\$1100.00	TO REPAIR SEE LABOUR	2,200.00	-
2	REAR FENDER INNER TRIM BOARD @\$356.80	DEFORMED	713.60	713.60
2	REAR FENDER TOP INNER TRIM BOARD @\$148.50	DEFORMED	297.00	297.00
12	REAR FENDER INNER TRIM BOARD CLIPS @\$6.50	NECESSARY	78.00	60.00
1	REAR END PANEL	DISTORTED	582.80	582.80
1	REAR END PANEL TOP GARNISH	DISTORTED	65.80	65.80
8	REAR END PANEL TOP GARNISH CLIPS @\$6.50	NECESSARY	52.00	10.00
1	REAR SPARE TYRE PANEL	DISTORTED	650.00	650.00
1	REAR SPARE TYRE PANEL TOP COVER	DEFORMED	220.00	220.00
1	REAR R/H RIM	NOT NECESSARY	950.00	-
1	REAR R/H LOWER ARM	NOT NECESSARY	120.60	-
1	REAR R/H KNUCKLE ARM	NOT NECESSARY	350.00	-
1	REAR R/H KNUCKLE ARM BEARING	NOT NECESSARY	280.00	-
1	REAR R/H TRADING ARM	NOT NECESSARY	142.00	-
1	REAR R/H SHOCK ABSORBER	NOT NECESSARY	225.00	-
1	REAR EXHAUST ALUMINIUM COVER	CRACKED	120.00	120.00
1	REAR EXHAUST	BENT	1,180.60	1,180.60
	LESS 20% DISCOUNT		-	-3,208.36
			30,691.16	12,833.44
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BOOT LID REVERSE CAMERA (SN)	DAMAGED	680.00	380.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	350.00	200.00
1	REAR SPARE TYRE PANEL SEALANT (SN)	NECESSARY	450.00	200.00
			1,480.00	780.00
	<u>LABOUR</u>			
	TO REMOVE & REFIT REAR CUSHION & TRIM BOARD .		280.00	200.00
	TO REMOVE & REFIT REVERSE CAMERA.		180.00	50.00

Report Ref No. CC4/LPC21000368/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT REVERSE SENSOR .		100.00	50.00
	TO REMOVE & REFIT REAR BOOT LID SPOILER .	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT AIR-CON CONDENSER ,RADIATOR ,FAN MOTOR & TOP UP GAS.	NOT NECESSARY	280.00	-
	TO REMOVE & REFIT REAR FENDER GLASS .		240.00	120.00
	TO REMOVE & REFIT REAR WINDSCREEN .		120.00	120.00
	GUM .		50.00	50.00
	TO REMOVE & RE APPLY REAR SPARE TYRE SEALANT .	NOT NECESSARY	200.00	-
	TO REMOVE & REFIT REAR EXHAUST .		150.00	80.00
	TO REMOVE & REFIT REAR R/H UNDERCARRIAGE .	NOT NECESSARY	450.00	-
	TO CHECK WHEEL ALIGNMENT .	NOT NECESSARY	150.00	-
	TO CHECK WIRING .		300.00	60.00
	TUFF KOTE.		150.00	150.00
	PANEL BEATING .INCLUSIVE OF THE REPAIR OF REAR FENDER INNER PANEL .		3,500.00	2,400.00
	SPRAY PAINTING .		3,000.00	2,000.00
	TO REMOVE REAR SEAT .		300.00	180.00
			9,570.00	5,460.00
GRAND TOTAL			41,741.16	19,073.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,000.00

Report Ref No. CC4/LPC21000368/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJV 1405A

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJV 1405A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJV 1405A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJV 1405A

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJV 1405A

RE-INSPECTION

