

Certification for Bus Repairs



CBR REF NO. : BN20210285

Depot : BN
 Driver's Co no. & Name : 60693 Yang Jun
 Accident Date : 04/01/2021

Report No.: E00092021 BUS VEHICLE NO. : SBS3651C

Date in : 15/01/2021

Date Out : 18/01/2021

Yr Of Reg	Make / Model	Chassis No.
2013	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P92XDA162214

Stock Code	Description	Quantity	Total Material cost(S\$)
30311711	NUMBER PLATE RECESS PAN;EXT.RR	1	\$151.00
30750142	REAR ENGINE COMPARTMENT DOOR	1	\$2,782.00
30750210	BOTTOM BOOT DOOR ASSY;RR ENG DR	1	\$709.00
30750006	DOOR RETAINER;EXTERIOR DOOR	3	\$23.00
42311205	PLATE;2MX1M;SOUND ABSORBER	1	\$474.00
TOTAL FOR PARTS			S\$ 4139.00
S/N	Labour / Spray Painting / Contractor Cost	Amount	
1	(2) Workshop Labour	S\$	192.00
2	Contractor's repair charges	S\$	900.00
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST			S\$ 1092.00
Repair cost of Advertisement / Livery			S\$ -
TOTAL DAMAGE			S\$ 5231.00

Certification for Bus Repairs



CBR REF NO. : BN20210285

Depot : BN
Driver's Co no. & Name : 60693 Yang Jun
Accident Date : 04/01/2021

Report No.: E00092021 BUS VEHICLE NO. : SBS3651C

Date in : 15/01/2021

Date Out : 18/01/2021

Yr Of Reg	Make / Model	Chassis No.
2013	Volvo B9TL Eu5, DD, AC, 3 Axle	YV3S4P92XDA162214
TOTAL DAMAGE		S\$ 5231.00
Overheads		S\$ 1569.30
Towing Charges		S\$ -
Repair Period : 3 day(s)	Loss of Use	S\$ 1282.92
TOTAL LOSS		S\$ 8083.22

Prepared By : Lenin Prabaagaran

Date : 19/01/2021

Approved By
Workshop Mgr : Gary Chong Kim Seng

Date : 19/01/2021

	Survey Fee	refer to Group Claims
TOTAL DUE		S\$ 8083.22

Acknowledged By
Depot Safety : Seah Hai Hua

Date : 20/01/2021

* This is computer generated document and does not require signature