



# TRANS EUROKARS PTE LTD



## ESTIMATE COST OF REPAIRS

<b>AIG ASIA PACIFIC INSURANCE P/L</b> 78 SHENTON WAY #07-16 CHARTIS BUILDING SINGAPORE 079120 <b>ATTN. :</b> MOTOR CLAIMS <b>FAX :</b>		<b>NAME :</b> Mr Lio Zhi Sen <b>ADDRESS :</b> Blk 102B Bidadari Park Drive #04-209 Singapore 342102 <b>TEL :</b> 91110112	<b>WIP :</b> 44625 <b>EXCESS :</b> <b>DATE:</b> 4-Jan-21
---	--	---	--

<b>VEH NO :</b>	<b>SMW607A</b>	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	Ronald 63957875
<b>CHASSIS NO :</b>	JM6BP2SAAK1103388	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	OWN DAMAGED CLAIM
<b>MODEL :</b>	MAZDA 3	<b>DATE REG.:</b>	30-Oct-20	<b>POLICY NO. :</b>	

### NATURE OF WORKS

#### Parts Description

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1	SIDE SKIRT LHS	MBCJH-51-P50D53	1				\$ 757.70
2	REAR DOOR LHS	MBCY0-73-02XE	1				\$ 954.10
3	HINGE UPPER LHS, REAR DOOR	MKD53-73-210A	1				\$ 48.30
4	HINGE LOWER LHS, REAR DOOR	MKD53-73-240A	1				\$ 44.80
5	WEATHERSTRIP LHS, REAR DOOR	MBCJH-73-760C	1				\$ 70.70
6	GROMMET, REAR DOOR	MBF67-51-261	1				\$ 2.40
7	GROMMET, REAR DOOR	MBCJH-58-975B	3				\$ 7.20
8	GROMMET, REAR DOOR	M9991-00-503	1				\$ 3.80
9	TAPE PROTECTOR, REAR DOOR	MGHP9-72-864	1				\$ 2.70
10	CLIP, REAR DOOR	MBCKA-72-604	2				\$ 5.60
11	CLIP,GARNISH-DOOR	MBCJH-50-M38	2				\$ 27.40
12	CLIP,GARNISH-DOOR	MKD53-50-M38	6				\$ 73.80
13	PILLAR(L),FRONT-OUT. BP	MBCYB-71-221	1				\$ -
<b>TOTAL PARTS</b>							\$ 1,998.50
<b>LESS 20%</b>							\$ 399.70
<b>TOTAL PARTS COST</b>							\$ 1,598.80

### SUPPLEMENTARY

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1							
2							
3							
4							
5							
6							
7							
8							
<b>TOTAL PARTS</b>							\$ -

			LESS 20%		\$ -
			TOTAL PARTS COST		\$ -
<b>Labour Description</b>					
1		TO REMOVE ROCKER PANEL LH INCLUDING : FRONT DOOR AND FRONT SEAT, REAR DOOR AND REAR SEAT, FRONT FENDER AND FRONT BUMPER.		NETT	\$ 945.00
2		TO RESPRAY ROCKER PANEL LH.		NETT	\$ 600.00
3		TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 1,260.00
4		TO RESPRAY ALL AREAS AFFECTED BY THE ACCIDENT.			\$ 1,200.00
5	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.			\$ 315.00
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$ 250.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOUC)			\$ 250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			\$ 350.00
9	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.		NETT	\$ 100.00
10	MZ-BR-SUNDRI	SUNDRIES.		NETT	\$ 100.00
			TOTAL LABOUR	\$ -	\$ 5,370.00
			TOTAL PARTS	\$ -	\$ 1,598.80
			TOTAL	\$ -	\$ 6,968.80
			LESS EXCESS	\$ -	\$ -
			TOTAL AFTER EXCESS	\$ -	
			GST 7%	\$ -	\$ -
			GRAND TOTAL	\$ -	\$ -
<b>SUPPLEMENTARY LABOUR DESCRIPTION</b>					
1		#N/A			
2		#N/A			
			TOTAL LABOUR	\$ -	\$ -
			TOTAL PARTS	\$ -	\$ -
			TOTAL	\$ -	\$ -
			LESS EXCESS	\$ -	\$ -
			TOTAL AFTER EXCESS	\$ -	
			GST 7%	\$ -	\$ -

GRAND TOTAL	\$	-	\$	-
-------------	----	---	----	---

TRANS EUROKARS PTE LTD

**REMARKS:**

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

---

Authorised Signature

