



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

Not Authorized

AIG ASIA PACIFIC INSURANCE P/L 78 SHENTON WAY #07-16 CHARTIS BUILDING SINGAPORE 079120 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Lio Zhi Sen ADDRESS : Blk 102B Bidadari Park Drive #04-209 Singapore 342102 TEL : 91110112		WIP : 44625 EXCESS : DATE: 4-Jan-21 <i>Excess \$? 5 days. 11/12</i>	
VEH NO :	SMW607A	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6BP2SAAK1103388	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	MAZDA 3	DATE REG.:	30-Oct-20	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1	SIDE SKIRT LHS	MBCJH-51-P50D53	1			For ✓	\$ 757.70
2	REAR DOOR LHS	MBCY0-73-02XE	1			Body ✓	\$ 954.10
3	HINGE UPPER LHS, REAR DOOR	MKD53-73-210A	1			1 X	\$ 48.30
4	HINGE LOWER LHS, REAR DOOR	MKD53-73-240A	1			1 X	\$ 44.80
5	WEATHERSTRIP LHS, REAR DOOR	MBCJH-73-760C	1			1 X	\$ 70.70
6	GROMMET, REAR DOOR	MBF67-51-261	1			1 ✓	\$ 2.40
7	GROMMET, REAR DOOR	MBCJH-58-975B	3			1 ✓	\$ 7.20
8	GROMMET, REAR DOOR	M9991-00-503	1			1 ✓	\$ 3.80
9	TAPE PROTECTOR, REAR DOOR	MGHP9-72-864	1			1 ✓	\$ 2.70
10	CLIP, REAR DOOR	MBCKA-72-604	2			1 ✓	\$ 5.60
11	CLIP, GARNISH-DOOR	MBCJH-50-M38	2			1 ✓	\$ 27.40
12	CLIP, GARNISH-DOOR	MKD53-50-M38	6			1 ✓	\$ 73.80
13	PILLAR(L), FRONT-OUT. BP <i>Rocker panel LH</i>	MBCYB-71-221	1		1 ✓	1 X	\$ 1296.60
	<i>LHR FENDER</i>	<i>MBCYA-71-410</i>	1		1 X		\$ 1649.60
TOTAL PARTS							\$ 1,998.50
LESS 20%							\$ 399.70
TOTAL PARTS COST							\$ 1,598.80

SUPPLEMENTARY

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1							
2							
3							
4							
5							
6							
7							
8							
TOTAL PARTS							\$ -

		LESS 20%		\$ -
		TOTAL PARTS COST		\$ -
Labour Description				
		per hrs 78.75 x 2 hrs = 157.50		
1		TO REMOVE ROCKER PANEL LH INCLUDING : FRONT DOOR AND FRONT SEAT, REAR DOOR AND REAR SEAT, FRONT FENDER AND FRONT BUMPER.	NETT	\$ 945.00
2		TO RESPRAY ROCKER PANEL LH. 600	NETT	\$ 600.00
3	*	TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. 78.75 x 12 hrs = 945		\$ 1,260.00
4		TO RESPRAY ALL AREAS AFFECTED BY THE ACCIDENT. Rear door & fender		\$ 1,200.00
5	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM. 78.75 x 2 hrs 157.50		\$ 315.00
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOUIC)	120	\$ 250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
9	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. 111 X	NETT	\$ 100.00
10	MZ-BR-SUNDRI	SUNDRIES. all 20	NETT	\$ 100.00
		TOTAL LABOUR	\$ -	\$ 5,370.00
		TOTAL PARTS	\$ -	\$ 1,598.80
		TOTAL	\$ -	\$ 6,968.80
		LESS EXCESS	\$ -	\$ -
		TOTAL AFTER EXCESS	\$ -	
		GST 7%	\$ -	\$ -
		GRAND TOTAL	\$ -	\$ -

SUPPLEMENTARY LABOUR DESCRIPTION

1	#N/A	LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:		
2	#N/A			
		TOTAL LABOUR	\$ -	\$ -
		TOTAL PARTS	\$ -	\$ -
		TOTAL	\$ -	\$ -
		LESS EXCESS	\$ -	\$ -
		TOTAL AFTER EXCESS	\$ -	
		GST 7%	\$ -	\$ -