

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 12 Jan 2021

**Preliminary Advice**

Vehicle No	: SMW607A	Accident Date	: 02/01/2021
Make	: MAZDA 3	Policy No.	: 2070149213
Assignment Date	: 11/01/2021	Excess	: S\$600.00
Date of Inspection	: 11/01/2021	Est. Duration of Repair	: 5
Inspection At	: TRANS EUROKARS PTE LTD (UBI) 5 UBI CLOSE SINGAPORE 408605		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,968.80
Revised Amount	:S\$	4,967.76
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,967.76
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	90,000.00
COE / PARF Rebate	:S\$	49,215.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,785.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :