

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 18 January 2021 9:43 AM
To: Ronald Yap
Cc: Jess Francis Carlos; SUR
Subject: RE: AIG-OD SMW 607A DOA: 02/01/2021

Dear Ronald,

Please proceed repair for the ROCKER PANEL \$1,296.60.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ronald Yap <ronald.yap@eurokars.com.sg>
Sent: Friday, 15 January 2021 1:59 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: Jess Francis Carlos <jess.carlos@eurokars.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: AIG-OD SMW 607A DOA: 02/01/2021

Dear Shiau Chan,

Further to my email below, the price is \$1296.60 for that rocker panel, same part number.

Thank You,

Ronald Yap
5 Ubi Close
S408605
Eurokars Group

From: Ronald Yap
Sent: 15 January 2021 13:52
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: Jess Francis Carlos <jess.carlos@eurokars.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: AIG-OD SMW 607A DOA: 02/01/2021

Dear Shiau Chan,

I refer to the attached estimate.

Item # 13, we have keyed a misleading description.

It should be 'Rocker Panel', and its beyond repair and needs replacement.

For your submission to AIG for the mandate please.

Thank You,

Ronald Yap
5 Ubi Close
S408605
Eurokars Group

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: 12 January 2021 16:50
To: Ronald Yap <ronald.yap@eurokars.com.sg>
Cc: Jess Francis Carlos <jess.carlos@eurokars.com.sg>; SUR <sur@lkkauto.com>
Subject: AIG-OD SMW 607A DOA: 02/01/2021

Dear Ronald,

As instructed by our client, please proceed to repair the insured vehicle **SMW 607A (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Note: Kindly arrange our surveyor to conduct resurvey of before paint for all panels and parts.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)