

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMW 607A

at Workshop m/s

Trens Eurokers

of

Insured:

930349284759

Policy No.

2070149213

Claims No.

Sum Insured:

Excess:


\$600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$90k.

IDAC Accident Rpt:

Consistent? : Yes or No

C/A / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

1.31

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

LTA 49215

Date / Time

Action / Instruction

2 stroke. Not done yet.

rep \$800

12/01/21 @ 9.39am revert to AG via Meimian.

12/01/21 @ 10.24am Kek Chorp informed C/A via Meimian.

12/01/21 @ 4.50pm Informed Ronald C/A & Exr \$600 by email.

3/3/21 P/P \$6004.96 confirmed phone check with Jen (Red B3316, 362.)

Veh No:

SMW 607A

Yr Regn:

30/10/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CAI

Make:

Mazda 3M-Hybrid c.c 1496

Colour

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

3845

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JM6BP25AAK-1103388

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215-45-R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

2/1/21

D.O.I.

1/1/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

MER-00

Lump Sum / I.B.I. (\$

6004.96)



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

NOT AUTHORIZED

AIG ASIA PACIFIC INSURANCE P/L 78 SHENTON WAY #07-16 CHARTIS BUILDING SINGAPORE 079120 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Lio Zhi Sen ADDRESS : Blk 102B Bidadari Park Drive #04-209 Singapore 342102 TEL : 91110112		WIP : 44625 EXCESS : 4-Jan-21 <i>Excess \$?</i> <i>5 days. 11/1/24</i>	
VEH NO :	SMW607A	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6BP2SAAK1103388	MILEAGE :		TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	MAZDA 3	DATE REG.:	30-Oct-20	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1	SIDE SKIRT LHS	MBCJH-51-P50D53	1			Torn ✓	\$ 757.70 ✓
2	REAR DOOR LHS	MBCY0-73-02XE	1			Body 2D ✓	\$ 954.10 ✓
3	HINGE UPPER LHS, REAR DOOR	MKD53-73-210A	1			1 X	\$ 48.30
4	HINGE LOWER LHS, REAR DOOR	MKD53-73-240A	1			1 X	\$ 44.80
5	WEATHERSTRIP LHS, REAR DOOR	MBCJH-73-760C	1			1 X	\$ 70.70
6	GROMMET, REAR DOOR	MBF67-51-261	1			1 ✓	\$ 2.40 ✓
7	GROMMET, REAR DOOR	MBCJH-58-975B	3			1 ✓	\$ 7.20 ✓
8	GROMMET, REAR DOOR	M9991-00-503	1			1 ✓	\$ 3.80 ✓
9	TAPE PROTECTOR, REAR DOOR	MGHP9-72-864	1			1 ✓	\$ 2.70 ✓
10	CLIP, REAR DOOR	MBCKA-72-604	2			1 ✓	\$ 5.60 ✓
11	CLIP, GARNISH-DOOR	MBCJH-50-M38	2			1 ✓	\$ 27.40 ✓
12	CLIP, GARNISH-DOOR	MKD53-50-M38	6			1 ✓	\$ 73.80 ✓
13	PILLAR(L), FRONT-OUT. BP <i>Rocker panel LH</i>	MBCYB-71-221 <i>1296.90</i>	1		<i>Body 2D ✓</i>	1 X	\$ 1296.90 ✓
	<i>LHR FENDER</i>	<i>MBCYA-71-410</i>	1		<i>1 X</i>		\$ 1643.60 X
TOTAL PARTS							\$ 1,998.50
LESS 20%							\$ 399.70
TOTAL PARTS COST							\$ 1,598.80

SUPPLEMENTARY

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1							
2							
3							
4							
5							
6							
7							
8							
TOTAL PARTS							\$ -

		LESS 20%		\$ -
		TOTAL PARTS COST		\$ -
Labour Description				
		per hrs 78.75 x 2 hrs = 157.50		
1		TO REMOVE ROCKER PANEL LH INCLUDING : FRONT DOOR AND FRONT SEAT, REAR DOOR AND REAR SEAT, FRONT FENDER AND FRONT BUMPER.	NETT	\$ 945.00
2		TO RESPRAY ROCKER PANEL LH. 600	NETT	\$ 600.00
3	*	TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. 78.75 x 12 hrs = 945	945	\$ 1,260.00
4		TO RESPRAY ALL AREAS AFFECTED BY THE ACCIDENT. Rear door & fender		\$ 1,200.00
5	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM. 78.75 x 2 hrs 157.50		\$ 315.00
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU)	120	\$ 250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
9	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP. 111 X	NETT	\$ 100.00
10	MZ-BR-SUNDRI	SUNDRIES. All 20	NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 5,370.00
TOTAL PARTS	\$ -	\$ 1,598.80
TOTAL	\$ -	\$ 6,968.80
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

SUPPLEMENTARY LABOUR DESCRIPTION

1	#N/A			
2	#N/A			
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
			TOTAL LABOUR	\$ - \$ -
			TOTAL PARTS	\$ - \$ -
			TOTAL	\$ - \$ -
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -

9320.96



TRANS EUROKARS PTE LTD



FINALIZATION COST OF REPAIRS

AIG ASIA PACIFIC INSURANCE P/L		NAME :	WIP :	44625
78 SHENTON WAY		ADDRESS :	EXCESS :	\$ 600.00
#07-16 CHARTIS BUILDING			DATE:	4-Jan-21
SINGAPORE 079120				
ATTN. :	MOTOR CLAIMS	TEL :		
FAX :				
VEH NO :	SMW607A	DATE IN :	CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6BP2SAAK1103388	MILEAGE :	TYPE OF CLAIM :	OWN DAMAGED CLAIM
MODEL :	MAZDA 3	DATE REG.:	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1	SIDE SKIRT LHS	MBCJH-51-P50D53	1			\$ 757.70	\$ 757.70
2	REAR DOOR LHS	MBCY0-73-02XE	1			\$ 954.10	\$ 954.10
3	HINGE UPPER LHS, REAR DOOR	MKD53-73-210A	1			\$ -	\$ 48.30
4	HINGE LOWER LHS, REAR DOOR	MKD53-73-240A	1			\$ -	\$ 44.80
5	WEATHERSTRIP LHS, REAR DOOR	MBCJH-73-760C	1			\$ -	\$ 70.70
6	GROMMET, REAR DOOR	MBF67-51-261	1			\$ 2.40	\$ 2.40
7	GROMMET, REAR DOOR	MBCJH-58-975B	3			\$ 7.20	\$ 7.20
8	GROMMET, REAR DOOR	M9991-00-503	1			\$ 3.80	\$ 3.80
9	TAPE PROTECTOR, REAR DOOR	MGHP9-72-864	1			\$ 2.70	\$ 2.70
10	CLIP, REAR DOOR	MBCKA-72-604	2			\$ 5.60	\$ 5.60
11	CLIP,GARNISH-DOOR	MBCJH-50-M38	2			\$ 27.40	\$ 27.40
12	CLIP,GARNISH-DOOR	MKD53-50-M38	6			\$ 73.80	\$ 73.80
13	PILLAR(L),FRONT-OUT. BP	MBCYB-71-221	1			\$ 1,296.50	\$ 1,296.50
TOTAL PARTS						\$ 3,131.20	\$ 3,295.00
LESS 20%						\$ 626.24	\$ 659.00
TOTAL PARTS COST						\$ 2,504.96	\$ 2,636.00

Labour Description

1	TO REMOVE ROCKER PANEL LH INCLUDING : FRONT DOOR AND FRONT SEAT, REAR DOOR AND REAR SEAT, FRONT FENDER AND FRONT BUMPER.	\$ 157.50	\$ 945.00
2	TO RESPRAY ROCKER PANEL LH.	\$ 600.00	\$ 600.00
3	TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 945.00	\$ 1,260.00
4	TO RESPRAY ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,200.00	\$ 1,200.00

5	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	\$ 157.50	\$ 315.00
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOUC)	\$ 120.00	\$ 250.00
8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00
9	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	\$ -	\$ 100.00
10	MZ-BR-SUNDRI	SUNDRIES.	\$ 20.00	\$ 100.00
			TOTAL LABOUR	\$ 3,500.00 \$ 5,370.00
			TOTAL PARTS	\$ 2,504.96 \$ 2,636.00
			TOTAL	\$ 6,004.96 \$ 8,006.00
			LESS EXCESS	\$ 600.00 \$ -
			TOTAL AFTER EXCESS	\$ 5,404.96
			GST 7%	\$ 378.35 \$ -
			GRAND TOTAL	\$ 5,783.31 \$ -

REMARKS:

5 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)