

Ching Hsuan (JL)

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 31.12.2020
Time: 09:10:10
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305445435
REGN NO : SHD7186K
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 17.11.2016
DATE/TIME IN : 30.12.2020 16:35
ACCIDENT DATE : 30.12.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-1150-A	I40VC PROTECTOR MAT	1	50.00	0.00	50.00	rel
0002 04-01-0101-0111-G	I40VC BUMPER COVER CLIP R	1 L	22 220	20.00	17.60 1.76	all
0003 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	1,106.00	20.00	884.80	ang
0004 04-01-0103-0739-G	I40VC ABSORBER-RR BUMPER	1	119.50	20.00	95.60	X un
0005 04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1	228.00	20.00	182.40	Ry
0006 04-01-0103-0783-G	I40VC BRKT ASSY-RR BUMPER	1	35.60	20.00	28.48	X un
0007 04-01-0103-0852-G	I40VC REFLECTOR/REFLEX AS	1	32.00	20.00	25.60	ms

SUB-TOTAL : 1,268.64

JOB NATURE

0000 PB	PANEL BEATING - Repair fender Rh	560.00	280
0001 SP	SPRAYPAINT CHARGE	500.00	200
0002 17-01	CHECK ALL LIGHTING	50.00	30
0003 L	REMOVE/REFIX REVERSE SENSOR	80.00	30

Tamplin 97475749
4/1/20 10am
2 days
clb Pasbury after repair
Tamplin C Lkhantawon

1518
4591200*

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: