

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200714616M  
 GST Registration No. : 200714616M

IVAN TAN CHIN KEONG  
 27 FEENVALE ROAD #23-26  
 SINGAPORE 797415

Contact : 81258019

TP Chin.  
 Xiao Chen.

## ESTIMATE

Repair Code : CLM15147

Date in : 08/01/2021

Vehicle Num. : SKQ7767E

Model : MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT

Chassis/Eng# : JM6GJ1071F0146698/PE20577075

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Replaced</i>	1	1114.00	✓ 1,114.00
REAR BOOTLID 'LOGO' EMBLEM	1	49.00	✓ 49.00
REAR BOOTLID 'MAZDA 6' EMBLEM	1	45.00	✓ 45.00
REAR BOOTLID 'SKYACTIV' EMBLEM	1	74.00	✓ 74.00
REAR BOOTLID HINGES L/R <i>new</i>	2	258.00	+ 516.00
REAR BOOTLID INNER TRIM BOARD <i>new</i>	1	181.00	+ 181.00
REAR BOOTLID LOCK STRIKER <i>new</i>	1	58.00	+ 58.00
REAR BOOTLID MECHANISM LOCK <i>new</i>	1	160.00	✓ 160.00
REAR BOOTLID REFLECTOR L/R <i>Replaced new</i>	2	367.00	+ 734.00
REAR BOOTLID WEATHER STRIP <i>at</i>	1	135.00	✓ 135.00
REAR BUMPER <i>Replaced</i>	1	1230.00	✓ 1,230.00
REAR BUMPER CENTER BRACKET <i>new</i>	1	53.00	✓ 53.00
REAR BUMPER REFLECTOR L/R <i>RA new</i>	2	54.00	54 <del>108.00</del>
REAR BUMPER REINFORCEMENT <i>Dented</i>	1	541.00	✓ 541.00
REAR BUMPER REVERSE SENSOR <i>2 pieces dented</i>	4	181.00	362 <del>724.00</del>
REAR BUMPER REVERSE SENSOR OUTER COVER <i>2 pieces dented</i>	4	42.00	84 <del>168.00</del>
REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>new</i>	1	167.00	+ 167.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	42.00	+ 84.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200714616M  
 GST Registration No. : 200714616M

IVAN TAN CHIN KEONG  
 27 FEENVALE ROAD #23-26  
 SINGAPORE 797415

Contact : 81258019

## ESTIMATE

Repair Code : CLM15147

Date in : 08/01/2021

Vehicle Num. : SKQ7767E

Model : MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT

Chassis/Eng# : JM6GJ1071F0146698/PE20577075

REAR BUMPER TOW HOO COVER L/R	<i>RH Missing</i>	2	24.80	<del>24.80</del>	49.60
REAR END PANEL	<i>Dented</i>	1	699.00	<del>699.00</del>	699.00
REAR END PANEL INNER TOP GARNISH	<i>cnld</i>	1	122.00	<del>122.00</del>	122.00
REAR TAILLAMP INNER BLACK GASKET L/R	<i>RH m</i>	2	38.00	<del>20</del>	<del>76.00</del>
REAR TAILLAMP L/R	<i>RH cnld</i>	2	762.00	<del>762</del>	<del>1524.00</del>
Subtotal before discount					8,611.60
Percentage discount 20%					1,722.32
<b>Sub-total 1</b>					<b>6,889.28</b>
REAR BOOTLID INNER TRIM BOARD CLIPS - SET	<i>mcu</i>	1	50.00	<del>50.00</del>	50.00
REAR BUMPER CLIPS - SET	<i>mcu</i>	1	80.00	<del>30</del>	<del>80.00</del>
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>mcu</i>	1	40.00	<del>10</del>	<del>40.00</del>
REAR TAILLAMP CLIPS L/R - SET	<i>mcu</i>	2	30.00	<del>4</del>	<del>60.00</del>
Subtotal before discount					230.00
Percentage discount 0%					0.00
<b>Sub-total 2</b>					<b>230.00</b>
<b>Parts-total</b>					<b>7,119.28</b>

## LABOUR

To Transfer Rear Bootlid Mechanism Lock Outer Handle Reflector

~~60~~ 80.00

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

~~70~~ 100.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

IVAN TAN CHIN KEONG  
27 FEENVALE ROAD #23-26  
SINGAPORE 797415

Contact : 81258019

## ESTIMATE

Repair Code : CLM15147  
Date in : 08/01/2021  
Vehicle Num. : SKQ7767E  
Model : MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT  
Chassis/Eng# : JM6GJ1071F0146698/PE20577075

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60	120.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	800	1,100.00
To remove and reinstall exhaust pipe.	X	100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1850	800
To apply anti-rust chemical on repaired and replaced panel.	60	120.00
		<hr/>
	<b>Labour Total</b>	<b>2,720.00</b>
	<b>Parts &amp; Labour Total</b>	<b>9,839.28</b>

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 3

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lij  
2/s 08/01/21  
0623p.

total: 6313.04

4/s: SK. ✓