

KARZ WORKS PTE LTD

53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK

SINGAPORE 408934

(TEL) 6 8 4 4 5 9 3 4 (FAX) 6 8 4 4 2 4 7 4 - (E-MAIL) KARZWORKSSG@GMAIL.COM

REPAIR PEFORMA INVOICE

SOMPO

Vehicle number	FA4045T
Make / Model	HONDA ADV150
Chassis number	MH1KF5114LK046249
Accident date	20/12/20
Reference	KK2012-41

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	FRONT LH MIDDLE FAIRING	250 350.00 cur
1	FRONT LH INNER FAIRING	180 280.00 de
1	FRONT LH UPPER FAIRING	300 400.00 cut
1	STAND	120.00 x nr
1 SET	FRONT FORK	R x 550.00 too different
		730 1700.00
		Less 10% 170.00
		Subtotal 657 1530.00
		Balance C/F 1530.00
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1 SET	GEAR SHIT SHAFT OIL SEAL	nr x 24.00 nr
2	FORK OIL SEAL	120.00 nr
1 BOT	FORK OIL	180 60.00 nr
		Subtotal 204.00
		Balance C/F 1734.00
LABOUR AND MISCELLANEOUS CHARGES		
1	TO CHECK FRONT FORK ALIGNMENT	200.00 100.
2	TO REALIGN BODY FRAME	350.00 X nr
3	TO R&R SUSPENSION, HANDLE BAR, HEADLAMP & FAIRING	400.00 100
4	TO SPRAY FENDER, SIDE FAIRINGS AND AFFECTED AREAS	400 500.00 200
		Subtotal 1450.00
		Grand total 3184.00

1030
- 10%
927

204

400

Tan Kah 97495784
WP
4/5 Repair after repair.
03 days

927
204
400
1531
- 20%
1224.80
657
180
400
1237
4/5 1000
1250 03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: