

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0003/2021/NS
DATE : 5-Jan-21
WIP : 65417

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Hi Adrian

5 days - ok - jb - 19 Mar 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR CHEONG HENG LIM
ADDRESS : 60 WILKINSON ROAD
SINGAPORE 436717
TELEPHONE : HP +65 93397811
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100431329-05
VEHICLE NO : **SKV 6958 B**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 29/9/2015
ENGINE NO : CZC 267121
CHASSIS NO : WAUZZZ8V3G1005440
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Jan-21
PLACE OF ACCIDENT : STADIUM BLVD ROUNDABOUT EXIT TO STADIUM DR

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKV 6958 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	
2	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY.	S/N \$ 350.00	\$ 280.00
3	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00	\$ 280.00
4	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR. TO RENEW LHS FRONT FENDER AND LHS FRONT DOOR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00	\$ 1,500.00
SUB TOTAL LABOUR CHARGES		: \$ 3,710.00	\$ 2,060.00



TEL : 6366 2323 FAX : 6841 1183

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKV 6958 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 2,060.00
5	TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, LHS WING MIRROR COVER AND LHS SILL PANEL.		\$ 3,400.00	\$ 1,100.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N	\$ 280.00	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	\$ 192.00
	TOTAL LABOUR CHARGES	:	\$ 7,582.00	\$ 3,352.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKV 6958 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT FENDER - LH		\$ 841.00	\$ 672.80
2	FRONT FENDER ATTACHMENT PARTS		\$ 71.00	
3	FRONT FENDER BRACKET - LH		\$ 27.00	
4	WHEEL HOUSING LINER - LH		\$ 167.00	
5	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 88.00	
6	FRONT DOOR - LH		\$ 2,494.00	\$ 1,995.20
7	FRONT DOOR OUTER SEAL - LH	NEC	\$ 159.00	\$ 127.20
8	BONDING AGENT	NEC	\$ 47.00	
9	CLEANING SOLUTION	NEC	\$ 65.00	
10	FRONT DOOR ATTACHMENT PARTS		\$ 238.00	
11	FRONT DOOR CATCH		\$ 104.00	
12	EXTERIOR MIRROR MOUNTING - LH		\$ 1,013.00	
13	MIRROR CAP - LH		\$ 148.00	
14	FRONT ALUMINIUM RIM - LH		\$ 699.00	
15	SUNDRIES		\$ 250.00	\$ 20.96
TOTAL SPARE PARTS		:	\$ 6,411.00	\$ 2,816.16
TOTAL LABOUR CHARGES		:	\$ 7,582.00	\$ 3,352.00
GRAND TOTAL		:	\$ 13,993.00	\$ 6,168.16

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-08/02/21



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT