

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0042/2021/GW
DATE : 13-Jan-21
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian

4 days - ok - jb - 24 Feb 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS. TAN SEOK CHIN
ADDRESS : 957 BUKIT TIMAH ROAD
#04-16
SINGAPORE 589653
TELEPHONE : HP +65 96384462
TYPE OF CLAIM : THIRD PARTY CLAIMS
POLICY NO : 1900190251
VEHICLE NO : **SMP 7942 Y**
MODEL CODE : AUDI A6 2.0 TFSI
MODEL YEAR : 15/10/2019
ENGINE NO : DLH054572
CHASSIS NO : WAUZZZF23KN123109
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Jan-21
PLACE OF ACCIDENT : Jurong Jalan Boon Lay About To go onto PIE

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 7942 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	\$ 360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,600.00	\$ 500.00
3	TO RESPRAY REAR BUMPER AND REAR LID.	\$ 2,400.00	\$ 1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 4,552.00	\$ 2,152.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 7942 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER		\$ 2,832.00	\$ 2,265.60
2	REAR BUMPER FIXING PARTS		\$ 236.00	
3	REAR BUMPER SPOILER		\$ 885.00	\$ 708.00
4	REAR BUMPER TRIM-LH/RH	2	\$ 490.00	
5	REAR BUMPER TRIM-CENTER		\$ 173.00	
6	REAR BUMPER SECURING STRIP		\$ 172.00	\$ 137.60
7	AERIEL KEY SENSOR		\$ 184.00	
8	REAR LIGHT REFLECTOR-LH/RH	2	\$ 82.00	
9	REAR LIGHT REFLECTOR INNER-LH/RH	2	\$ 60.00	
10	REAR SENSOR		TBC	
11	REAR SENSOR SEAL RING	4	\$ 14.00	
12	REAR PACKING ADHESIVE		\$ 19.00	\$ 14.88
13	REAR AUDI EMBLEM		\$ 138.00	\$ 110.00
14	REAR INSCRIPTION 'A6'		\$ 99.00	\$ 79.04
15	SUNDRIES		\$ 200.00	
TOTAL SPARE PARTS		:	\$ 5,584.00	\$ 3,315.12
TOTAL LABOUR CHARGES		:	\$ 4,552.00	\$ 2,152.00
GRAND TOTAL		:	\$ 10,136.00	\$ 5,467.12

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-10/02/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT