



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21000408/BKtf3e2	
			Date: 25/03/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBK 1832C	Veh. Inspected	SLH 8122U
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2003099/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	11/01/2021
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI ELANTRA (A)	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KMHD841CMHU309725	Colour	SILVER
	Odometer	84977 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
	L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	22/10/2020	Inspection Date	11/01/2021
	Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	