



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Ng Boon Chye Andrew @ Adhwa Ng Reg No/Reg Date SMA6469H / 26/04/201 Date In/Mileage / 0 Chassis No KNAHU815VJ7205410 Engine No D4FDJH551779 Make/Model KIA/CARENS 1.7 A D SX FL DY6 Colour/Trim 1D CLEAR WHITE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	08/01/2021/ 16:04	BLC	442 / CocoLu	27036			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000					479 x 65		2000	4000.00
RENW FRT BUMPER, FRT FENDER LH, FRT DOOR LH, REAR DOOR LH								
SIDE SILL LH, 2								
E PNT98000							1750	2100.00
SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH, FRT DOOR LH, REAR DOOR LH								
SIDE SILL LH, 1								
E PNT88000								160.00
REMOVE & INSTALL FRT DOOR TRIMS AND GLASS								
E PNT88000								160.00
REMOVE & INSTALL REAR DOOR TRIMS AND GLASS								
M SUNDRY							80	120.00
APPLY SEALANT FOR ACCIDENT PORTION								
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
A 90000001								400.00
RENEW FRT UNDERCARRIAGE								
M SUNDRY								30.00
TRANSFER FRT LEFT TYRE								
M SUNDRY								460.00
SUPPLY FRT LEFT TYRE								
M SUNDRY								20.00
Sundry								
M WHEEL ASSY-ALUMINIUM					1.00	704.00	20.00	563.20
M COVER-FR BUMPER					1.00	695.00	20.00	556.00
M EMBLEM-KIA					1.00	76.00	20.00	60.80
M BRACKET-FR BUMPER UPR SIDE MTG					1.00	12.00	20.00	9.60
M BRACKET-FR BUMPER SIDE, LH					1.00	12.00	20.00	9.60
M GUARD ASSY-FRONT WHEEL, LH					1.00	75.00	20.00	60.00

Estimate

CUT (net item)

500

BR

REC

7 x 11/1

BR

BR

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Ng Boon Chye Andrew @ Adhwa Ng Reg No/Reg Date SMA6469H / 26/04/201 Date In/Mileage / 0 Chassis No KNAHU815VJ7205410 Engine No D4FDJH551779 Make/Model KIA/CARENS 1.7 A D SX FL DY6 Colour/Trim 1D CLEAR WHITE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
LAX00000	Credit	08/01/2021/ 16:04	BLC	442 / CocoLu	27036				
Description of Goods / Services									
M PANEL-FENDER,LH						1.00	425.00	20.00	340.00
M INSULATOR-FENDER LH						1.00	48.00	20.00	38.40
M LAMP ASSY-HEAD,LH						1.00	1558.00	20.00	1246.40
M PANEL ASSY-FRONT DOOR,LH						1.00	1097.00	20.00	877.60
M PANEL ASSY-REAR DOOR,LH						1.00	977.00	20.00	781.60
M BLACK TAPE-FRT DOOR FRAME UPR,						1.00	13.00	20.00	10.40
M TAPE-FR DR BLACK FRAME RR LH						1.00	14.00	20.00	11.20
M TAPE-RR DR BLACK FRAME FR,LH						1.00	11.00	20.00	8.80
M TAPE-RR DR BLACK FRAME FR,LH						1.00	12.00	20.00	9.60
M TAPE-RR DR BLACK FRAME UPR,LH						1.00	9.00	20.00	7.20
M TAPE-RR DR BLACK RR,LH						1.00	1612.00	20.00	1289.60
M PANEL-SIDE SILL OUTRER,LH						1.00	1190.00	20.00	952.00
M CROSSMEMBER COMPL-FR AXLE						1.00	429.00	20.00	343.20
M ARM COMPLETE-FR LWR,LH						1.00	832.00	20.00	665.60
M GEAR ASSY-STEERING						1.00	251.00	20.00	200.80
M BEARING-FRONT WHEEL HUB						1.00	344.00	20.00	275.20
M KNUCKLE-FRONT AXLE,LH						1.00	335.00	20.00	268.00
M STRUT ASSY-FR,LH						1.00	42.00	20.00	33.60
M BUMPER-RUBBER						1.00	53.00	20.00	42.40
M BEARING-STRUT						1.00	47.00	20.00	37.60
M PAD-FRONT SPRING,UPR						1.00	104.00	20.00	83.20
M INSULATOR ASSY-STRUT						1.00	94.00	20.00	75.20
M LINK ASSY-FRONT STABILIZER,LH						1.00	274.00	20.00	219.20
M BAR ASSY-FR STABILIZER									

Steve (LKK) 00 - New Ant
8/1/21, 4.00pm EXAM - ?
12 dys
P/P
M Bel Spy

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before other spray painting
- Confirm the accuracy of (a) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

7% GST on 16,796.00
Total Payable 17,971.72

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.