

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Lim Chong Hung	Cust No/Name /Mr Lim Chong Hung
BLK 288C JURONG EAST ST 21	Reg No/Reg Date SLR8563C / 30/08/201
#08-400	Date In/Mileage / 0
SINGAPORE 603288	Chassis No KNAPH81BSH5376777
Contact No Mobile: 97317080	Engine No D4HBHH327437
	Make/Model KIA/SORENTO 2.2 A D GT SR 4WD CBF
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	09/01/2021/ 10:51	Bod	442 / CocoLu	27049			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1200.00
RENEW FRT BUMPER, BONNET,								
E PNT98000								700.00
SPRAY PAINT FOR FRT BUMPER, BONNET								
M SUNDRY								50.00
FRT NUMBER PLATE WITH FRAME								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
E PNT88000								60.00
REMOVE & INSTALL PARKING SENSOR								
M SUNDRY								40.00
APPLY SEALANT FOR ACCIDENT PORTION								
M SUNDRY								20.00
Sundry								
M COVER-FR BUMPER UPR					1.00	645.00	00.00	645.00
M COVER-FR BUMPER,LWR					1.00	645.00	00.00	645.00
M BRACKET-FR BPR SIDE REINF,RH					1.00	22.00	00.00	22.00
M GRILLE-FRONT BUMPER					1.00	178.00	00.00	178.00
M ABSORBER-FRONT BUMPER ENERGY					1.00	134.00	00.00	134.00
M GRILLE ASSY-RADIATOR					1.00	738.00	00.00	738.00
M MOUNTING ASSY-LICENCE PLATE					1.00	37.00	00.00	37.00
M BRACKET-FR BUMPER SIDE,RH					1.00	17.00	00.00	17.00
M GRILLE-FRONT BUMPER FOG LAMP,R					1.00	81.00	00.00	81.00
M ULTRASONIC SENSOR ASSY-BWS					1.00	187.00	00.00	187.00
M PANEL ASSY-HOOD					1.00	1654.00	00.00	1654.00
M LAMP ASSY-HEAD,RH					1.00	2210.00	00.00	2210.00
M BEAM COMPLETE-FR BUMPER					1.00	551.00	00.00	551.00

Confirm & accepted by

Nett	9,319.00
7% GST on	9319.00
Total Payable	9,971.33

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.