



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

*not Authorized
Haha merus
11/1/21
The photo before party
@ 9.30 am. 5 days*

ESTIMATE

Account Details			Account No.		Customer Details		
AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 (Before Mar 2017)			S1000033 / ICA3		Mr Razid Bin Saad 8 Miltonia Close Singapore 768190 Mobile: 92236370		
			Document No. 0				
			Document Date 08/01/2021				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	ASU60R	ANTMT E1	28/09/2020	SMV3418P	0	20623	67/TP/SMV3418P
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTEZB3GH00J005932		8ARZ211980	60	Sam San Joi	08/01/2021 16.05 --/--/----		0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-AI SUNDRIES TP CLAIM TP-SLZ635P ACC DATE:08/01/2021 DRIVE IN:08/01/2021 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00	
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON REAR ACCIDENT AREAS				183.18	
3	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				162.00	
4	B	BP-LAB2 LIGHTING & CONDUCT WATER LEAK TEST				162.00	
5	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET ,GARNISH AND TRIMMING TO ASSIST REPAIR				324.00	
6	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS				415.80	
7	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM				350.00	
8	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE				324.00	
9	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE CAMERA				162.00	
10	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				162.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Company Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details				
AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 (Before Mar 2017)		S1000033 / ICA3	Mr Razid Bin Saad				
		Document No. 0	8 Miltonia Close Singapore 768190				
		Document Date 08/01/2021	Mobile: 92236370				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	ASU60R	ANTMT E1	28/09/2020	SMV3418P	0	20623	67/TP/SMV3418P
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTEZB3GH00J005932	8ARZ211980	60	Sam San Joi	08/01/2021	16.05	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
11	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS 720 STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS			1296	2916.00	
12	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR 590 EAS			1062	2389.50	
13	1	T52159-48933 COVER, RR BUMPER DD	1.00	904.00	25.00	678.00	
14	2	T52156-48050 SUPPORT, RR BUMPER 11	1.00	82.70	25.00	62.02	
15	3	T52155-48050 SUPPORT, RR BUMPER 11	1.00	82.70	25.00	62.02	
16	4	T52169-48100 COVER, RR BUMPER, D 15	1.00	466.00	25.00	349.50	
17	5	S52161-0K040 CLIPS 11	10.00	4.10	25.00	30.70	
18	6	T52163-48050 PLATE, RR BUMPER, RH 11	1.00	98.20	25.00	73.65	
19	7	T52615-48230 ABSORBER, RR BUMPER 11	1.00	122.60	25.00	91.95	
20	8	T58307-48120 PANEL SUB-ASSY, BODY R	1.00	1006.40	25.00	754.80	
21	9	T48691-48030 DAMPER, SUSPENSION 11	1.00	1343.10	25.00	1007.32	
22	0	T64716-48020 CO COVER, DECK TRIM, RR 11	1.00	438.30	25.00	328.72	
23	1	T67005-48340 PANEL SUB-ASSY, BACK 3065m	1.00	2126.40	25.00	1594.80	
24	2	T67881-48070 WEATHERSTRIP, BACK 11	1.00	441.30	25.00	330.97	
25	3	T68105-48905 GLASS SUB-ASSY, BACK 11	1.00	1218.20	25.00	913.65	
26	4	T75575-48040 MOULDING, BACK 11	1.00	51.90	25.00	38.92	
27	5	T69350-48081 LOCK ASSY, BACK DOOR 11	1.00	565.20	25.00	423.90	
28	6	T90975-02071 EMBLEM,SYMBOL 11	1.00	57.30	25.00	42.97	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet		Amount Due		
			Lubrication/Fluid				
			Others				

Company Copy

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

17 UBI ROAD 4

SINGAPORE 408611, Tel no.: 6631 1188

**TOYOTA****ESTIMATE**

Account Details		Account No.	Customer Details				
AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 (Before Mar 2017)		S1000033 / ICA3	Mr Razid Bin Saad				
		Document No. 0	8 Miltonia Close				
		Document Date 08/01/2021	Singapore 768190 Mobile: 92236370				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	ASU60R	ANTMT E1	28/09/2020	SMV3418P	0	20623	67/TP/SMV3418P
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTEZB3GH00J005932		8ARZ211980	60	Sam San Joi	08/01/2021 16.05		--/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
29	7	T75442-48140 PLATE, BACK DOOR <i>ner</i>	1.00	73.70	25.00	55.27	
30	8	SPZQ31-13020 Badge Assy, Engine Mark RHS <i>ner</i>	1.00	17.52	25.00	13.14	
31	9	T89997-30100 ANTENNA, ELECTRICAL	1.00	72.00	25.00	54.00	
32	0	T89341-58060 A0 SENSOR, ULTRASONIC,	3.00	481.90	25.00	1084.26	
33	1	T89348-58070 A0 RETAINER, ULTRASONIC	3.00	21.30	25.00	47.91	
34	2	T89348-58120 RETAINER, ULTRASONIC <i>ner</i>	4.00	16.00	25.00	48.00	
35	3	T04562-12010 <i>ner</i> FRT W/SCREEN DAM KIT, <i>ner</i>	1.00	121.00	25.00	90.75	
36	4	T21000-20 SIKA 182010 SIKA TACK GO! (BLA <i>ner</i>	2.00	108.00	25.00	162.00	
37	5	T21000-22 SIKA 207. G+P ADHESIVE PRIMER <i>ner</i>	1.00	200.00	25.00	150.00	
For & on behalf of		Customer's Signature		Acknowledged by Repairer		Total	
Borneo Motors (Singapore) Pte Ltd		Signature: _____		Signature: _____		16,069.70	
		Date: _____		Charge Summary			
		Please acknowledge receipt of vehicle		Parts 8,489.22		GST 7.00% 1,124.88	
				Labour 6,885.30		Less 0.00	
				Sublet 695.18			
				Lubrication/Fluid 0.00			
				Others 0.00		Amount Due 17,194.58	

Company Copy