LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Our File No: CS/CTI21000420/KTF3E2

Singapore 079909 Date: 04/05/2021

REFERENCE

Insured/Claimant: Koh Wee Chuan Shawn Policy No: DMPCSNW00185992002

Date of Loss: 05/01/2021 Nature of Claim: OD Claim No: SNM21D200078/C01/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJG3282C

 Make & Model:
 TOYOTA AXIO, 1.5 (A)
 Engine No:
 1NZD059986

 Reg. Date:
 26/06/2008 (Man. Year: 2008)
 Chassis No:
 NZE1416083154

 Colour:
 Metallic Grey
 Odometer:
 135431 km

Engine Capacity: 1496 cc
Market Value/New Car Price: \$\$16,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
Front Left Side: Continental 7 mm Rear Left Side: Continental 7 mm
Front Right Side: Continental 7 mm
Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		10,913.00	7,980.00	2,933.00	26.88
Miscellaneous Items		448.00	293.00	155.00	34.60
Labour		1,297.80	1,003.80	294.00	22.65
Paintwork Labour		1,013.60	883.97	129.63	12.79
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	13,672.40	10,160.77	3,511.63	25.68
	Approved Total (Overridden) (S\$)		6,300.00		
	(S\$)	13,672.40	6,300.00	7,372.40	53.92
	+ GST 7.00/7.00% (S\$)	957.07	441.00	516.07	53.92
	Nett Amount (S\$)	14,629.47	6,741.00	7,888.47	53.92

INSPECTION

Date of Assignment: 11/01/2021 Present Location: S & H Motor Pte Ltd (Sin Ming)

S & H Motor Pte Ltd (Sin Ming)

Date Inspected: 11/01/2021 Inspected At: 160 Sin Ming Drive #07-02, Sin Ming AutoCity

Singapore 575722

Estimated Period of Repair: 10.0 days

Adjuster: KENNETH KONG Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 May 2021)

Parts: 143 TOYOTA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJG3282C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1 5-5	*Parts		10,913.00 F	*7,980.00 F
F=Franchise part.		Total Parts (S\$)	10,913.00	7,980.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 misc		448.00	293.00
	Sub Total (S\$)	448.00	293.00
Recommended Labour			

No	Particulars	Lab.Type	Repairer's	Amount
<u>Pair</u>	ntwork Labour			
1	Labour for paintwork	New	1,013.60	883.97
<u>Lab</u>	our Items			
2	Labour for panel/mechanical	New	1,297.80	1,003.80
		Gross Labour Cost (S\$)	2,311.40	1,887.77
	Re	port was unsubmitted during this print-out.		

< END OF ESTIMATES >