

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 41792

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

KNAF3416MKS017923

Veh# : SGV1082H

Accident Date : 8/1/2021

Location : AYE JURONG AFTER LOWER DELTA

TP ALG.
Cecilia

Model: KIA CERATO

Signature: (15/11/2018)

Date:

3P: SLB7473U (AIG)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed

Resurveyed and approved by insurance company

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear bumper <i>Repld</i>	825.60	✓	-
2	10 pcs	Rear bumper clips <i>mu</i>	-	50.00	30
3	1 pc	Rear end panel <i>Repld</i>	349.92	✓	-
4	1 pc	Rear end panel inner trim <i>Repld</i>	54.00	✓	-
5	1 pc	Rear bumper enforcement <i>Repld</i>	343.32	✓	-
6	2 pcs	Rear bumper o/s & n/s retainer <i>mu</i>	92.40	✓	-
7	1 pc	Rear bumper lower diffuser <i>Repld</i>	260.52	✓	-
8	4 pcs	Rear bumper reverse sensor <i>Repld</i>	-	280.00	200
9	1 pc	Rear boot cover <i>Repld</i>	1,557.24	✓	-
10	1 pc	Rear boot cover weatherstrip <i>Repld</i>	110.00	✓	-
11	1 pc	Rear boot cover emblem <i>Repld</i>	52.30	✓	-
12	1 pc	Rear boot cover Cerato emblem <i>Repld</i>	42.40	✓	-
13	1 pc	Rear boot cover C & C emblem <i>Repld</i>	51.20	✓	-
14	1 pc	Rear boot cover lock (upper) <i>Repld</i>	82.40	✓	-
15	1 pc	Rear <i>Tail lamp N/S. Repld</i>	609	✓	-
16	2 pcs	Rear o/s & n/s fog lamp <i>N/S Repld</i>	434.40	✓	217.20
17	2 pcs	Rear o/s & n/s fog lamp garnish <i>N/S Repld</i>	161.20	✓	80.60
18	1 pc	Rear n/s tail lamp <i>Repld</i>	-	✓	-
		<i>Repld n/s Star Best 95</i>			
		Sub-Total:	4,416.90	330.00	0.00
			10%	0%	0%
		After Less %:	3975.21	330.00	0.00
		Labour			
1		To dismantle rear damaged parts, straighten & welding.	1,000.00	600	
2		To spray painting.	800.00	600	
3		To remove and replace rear reverse sensor.	80.00	40	
4		To check wiring.	80.00	30	
5		To re-seal anti-rust.	80.00	40	
		Sub-Total:	2,040.00		
		Total:	6,345.21		
		After Less 20%:	5,076.17		

688

954

Chan

list 3622-34 S.N. 230
len 10/326010 Labur: 1320

Adrian Li
h/s 11/11/21

0 & Days

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)



bizSAFE 8778 1999
24 hr accident call
ST R SGV1082H ESTIMATEPg1

Mobil 1



PAYNOW

total: 4810.10

h/s: 3.8K

3810