

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

Our Job Ref No : 305447372  
Date : 16/01/21

## FINALIZATION FORM

To : LKK

Fax :

Attn : TAUFIKH

Vehicle Reg No. : SH 7727Z

Date of Accident : 09/01/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: MSIG --- SLU2619A
2. The finalized amount shall be:
  - (a) Spare Parts after List discount
  - (b) Labour Charges
  - Total for Part-By-Part Repair Cost**
  - (c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% \$6,600.00  
**Final Lumpsum Repair cost** \$6,600.00

3. Estimated normal period for repairs: 4 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and  
finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : TAUFIKH

Date : 25/1/21

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_

# COMFORT DELGRO ENGINEERING

VEHICLE : SH 7277Z TYPE OF CLAIM: TP

MODEL : HYUNDAI I40 SURVEY BY : LKK-TAUFIKH

JOB NO : 305447372 DATE : 11/01/21

## SUPPLEMENTARY OF PARTS AND LABOUR COSTS

S/No	DESCRIPTION	QTY	ESTIMATE \$	REMARKS
1	EXHAUST MUFFLER RH	1	967.70	bt ✓
2	EXHAUST CENTRE PIPE	1	730.10	bt ✓
3	SPARE TYRE FASTENER	1	41.80	de ✓
	* Last Entry *			
1	REAR BUMPER UNDER COVER	1	228.00	crossed item Xnn
	* Last Entry *			