

RICO 60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	41K

TO: China Taiping

Vehicle No : SLU 3639 K

Make & Model : BMW 216D

DATE:26/12/2020

WBA2B320X0V926231

Voron.

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	BONNET Dented	1	\$ 1,209.00	\$ ✓ 1,209.00
2	BONNET LOWER SIDE LOCK Dgd. RH	2	\$ 321.00	\$ 321 642.00
3	BONNET SIDE LOCK CATCH New	2	\$ 100.00	\$ + 200.00
4	BONNET STOPPER New	2	\$ 40.00	\$ x 80.00
5	BONNET INSULATOR New	1	\$ 654.00	\$ + 654.00
6	BONNET HINGE New	2	\$ 223.10	\$ x 446.20
7	BONNET DAMPER New	2	\$ 244.00	\$ + 488.00
8	FRONT BUMPER Disbld	1	\$ 995.00	\$ ✓ 995.00
9	FRONT BUMPER LOGO New	1	\$ 101.00	\$ - 101.00
10	FRONT BUMPER TOP RUBBER New cut	1	\$ 132.30	\$ ✓ 132.30
11	FRONT BUMPER TOP GARNISH New	1	\$ 287.90	\$ x 287.90
12	FRONT BUMPER LOWER GRILLE Dgd	1	\$ 218.00	\$ ✓ 218.00
13	FRONT BUMPER PARKING SENSOR Dgd.	2	\$ 298.00	\$ ✓ 596.00
14	FRONT BUMPER SIDE RETAINER RH cml	2	\$ 132.50	\$ 132.50 265.00
15	FRONT BUMPER REINFORCEMENT Bent.	1	\$ 488.60	\$ ✓ 488.60
16	FRONT BUMPER REINFORCEMENT BRACKET RH Bent	2	\$ 159.20	\$ 159.20 318.40
17	FRONT BUMPER LOWER REINFORCEMENT Bent	1	\$ 343.00	\$ ✓ 343.00
18	FRONT BUMPER LOWER REINFORCEMENT BRACKET Bent RH	2	\$ 126.00	\$ 126 252.00
19	FRONT BUMPER LOWER REINFORCEMENT SIDE RAIL New	2	\$ 90.00	\$ x 180.00
20	FRONT BUMPER SPONGE Cml	1	\$ 347.00	\$ ✓ 347.00
21	FRONT BUMPER SIDE GARNISH Disbld RH	2	\$ 224.00	\$ 224 448.00
22	FRONT BUMPER UNDER COVER Missing	1	\$ 458.00	\$ ✓ 458.00
23	FRONT FOG LAMP RH Missing	1	\$ 389.00	\$ ✓ 389.00
24	FRONT FOG LAMP COVER RH Missing	1	\$ 121.90	\$ ✓ 121.90
25	FRONT GRILLE RH cml, LH up	2	\$ 211.70	\$ 211.70 423.40
26	FRONT GRILLE CHROME Cml	2	\$ 112.00	\$ ✓ 224.00
27	FRONT GRILLE AIR VENT cml	1	\$ 435.00	\$ ✓ 435.00

28	WIPER WASHER TANK	Orshd	1	\$	358.00	\$	✓	358.00	152
29	WIPER WASHER TANK MOTOR	Brnd	1	\$	158.00	\$	✓	158.00	
30	WIPER WASHER TANK NECK	Neu	1	\$	132.70	\$	+	132.70	
31	HEADLAMP	Culld	2	\$	2,359.80	\$	✓	4,719.60	
32	HEADLAMP TOP PANEL RH	Neu	1	\$	253.50	\$	+	253.50	
33	HEADLAMP TOP RUBBER	At RH	2	\$	108.00	\$	108	216.00	
34	HEAD LAMP LOWER BRACKET	RH Best	2	\$	254.00	\$	254	508.00	
35	FRONT WIPER GARNISH	Culld	1	\$	521.00	\$	✓	521.00	
36	FRONT WIPER GARNISH SIDE COVER RH	Neu	1	\$	89.00	\$	+	89.00	
37	FRONT WIPER GARNISH TOP RUBBER	Neu	1	\$	177.30	\$	+	177.30	
38	FRONT SUPPORT PANEL	Best	1	\$	489.00	\$	✓	489.00	
39	SUPPORT PANEL LOWER SUPPORT	RH Best	2	\$	275.50	\$	275.50	551.00	
40	FRONT AIR DUCT	Culld	1	\$	371.50	\$	✓	371.50	
41	AIR CLEANER BOX	Culld	1	\$	547.00	\$	✓	547.00	
42	HORN	Neu RH Culld	2	\$	259.00	\$	259	518.00	
43	RADIATOR	Culld	1	\$	1,254.00	\$	✓	1,254.00	
44	AIR CON CONDENSER	Neu	1	\$	1,254.00	\$	x	1,254.00	
45	AIR CON PIPE	Best	1	\$	542.00	\$	✓	542.00	
46	AIR CON SUCTION PIPE	Neu	1	\$	322.50	\$	+	322.50	
47	AIR CON DISCHARGE PIPE		1	\$	364.20	\$	+	364.20	
48	RADIATOR FAN COWLING ASSY	Neu	1	\$	1,203.70	\$	+	1,203.70	
49	FRONT FENDER RH	Orshd	1	\$	720.30	\$	✓	720.30	
50	FRONT FENDER TOP GARNISH RH	Orshd	1	\$	179.00	\$	✓	179.00	
51	FRONT FENDER QUARTER GLASS CHROME RH	Neu	1	\$	321.00	\$	+	321.00	
52	FRONT FENDER INNER SIDE CIVER RH	Orshd	1	\$	185.40	\$	✓	185.40	
53	FRONT FENDER INNER HOUSING RH	Ryis	1	\$	890.00	\$	+	890.00	
54	FRONT FENDER INNER COWLING RH	Neu	1	\$	298.20	\$	✓	298.20	
55	SIDE SKIRT RH	Orshd	1	\$	1,685.20	\$	✓	1,685.20	685
56	FRONT ABSORBER RH	Best	1	\$	428.50	\$	✓	428.50	
57	FRONT KNUCKLE ARM RH	Brnd	1	\$	596.70	\$	✓	596.70	
58	FRONT KNUCKLE BEARING RH	Brnd	1	\$	591.30	\$	✓	591.30	
59	FRONT LOWER ARM RH	Best	1	\$	386.20	\$	✓	386.20	
60	FRONT STABILIZER LINK RH	Best	1	\$	282.90	\$	✓	282.90	
61	FRONT DRIVE SHAFT RH	Neu Brnd.	1	\$	2,075.30	\$	✓	2,075.30	1680
62	STEERING RACK & PILLION	Neu	1	\$	5,244.80	\$	✓	5,244.80	
63	FRONT RIM ORIGINAL RH	At	1	\$	864.50	\$	✓	864.50	
64	FRONT DOOR RH	Ryis	1	\$	2,000.00	\$	x	2,000.00	
65	FRONT DOOR OUTER MOULDING RH	Neu	1	\$	289.00	\$	+	289.00	
66	FRONT DOOR SIDE MIRROR RH	Ryis	1	\$	1,554.00	\$	+	1,554.00	
67	FRONT DOOR CHROME MOULDING	Neu	1	\$	189.00	\$	+	189.00	
68	FRONT DOOR HINGE RH	Neu	2	\$	217.00	\$	+	434.00	
69	Front wireharness	Neu Snapped	1	\$	617.00	\$	✓	617.00	
70	Front Support Lower	Best	1	\$	260.90	\$	✓	260.90	

		Subtotal :	\$	44,508.00
		Less 10%	\$	4,450.80
		Parts Total :	\$	40,057.20

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	FRONT NUMBER PLATE <i>Neu</i>	1	\$ 100.00	\$ + 100.00
2	FRONT BONNET INSULATOR CLIPS <i>Neu</i>	1	\$ 65.00	\$ + 65.00
3	FRONT FENDER INNER HOUSING SEALANT <i>Neu</i>	1	\$ 80.00	\$ + 80.00
4	FRONT FENDER INNER COWLING CLIPS SET <i>Neu</i>	1	\$ 65.00	\$ 30 65.00
5	SIDE SKIRT CLIP <i>Neu</i>	1	\$ 60.00	\$ 30 60.00
6	FRONT BUMPER CLIPS <i>Neu</i>	1	\$ 60.00	\$ 30 60.00
7	FRONT BUMPER UNDER COVER CLIP <i>Neu</i>	1	\$ 60.00	\$ + 60.00
8	FRONT SUPPORT TOP GARNISH CLIP <i>Neu</i>	1	\$ 65.00	\$ 20 65.00
9	FRONT SUPPORT PANEL SEALANT <i>Neu</i>	1	\$ 80.00	\$ + 80.00
10	FRONT GRILLE CLIP <i>Neu</i>	1	\$ 50.00	\$ 30 50.00
11	COOLANT <i>Neu</i>	1	\$ 150.00	\$ 40 150.00
12	FRONT SPORT TYRE <i>Neu</i>	1	\$ 450.00	\$ + 450.00
SPECIAL NETT				\$ 1,285.00

LABOUR		PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	1100	\$ 120 1,600.00
TO SPRAY PAINT AFFECTED AREA	1000	\$ 120 1,600.00
TUFF COAT		\$ 60 200.00
ADJUST AND FOCUS FRONT LED ADAPTIVE LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION	x	\$ 300 650.00
DISMENTLE AND REPLACE FRONT UNDER-CARRIAGE COMPONENTS.		\$ 220 600.00
REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS		\$ 60 150.00
REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST		\$ 60 150.00
CONDUCT FULL WHEEL ALIGNMENT		\$ 80 150.00
WIRING CHECK		\$ 30 100.00
REMOVE AND REPLACE FRONT DOOR MECHANISIM		\$ X 200.00
LABOUR TOTAL		\$ 5,400.00

Total Parts Cost	\$	41,342.20
Total Labour Cost	\$	5,400.00
Total Repair Cost	\$	46,742.20

APPROVED DETAILS

NO. OF WORKING DAYS

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

Adrian L
h/s 12/01/21

11 Days.

Total: 24912.98

h/s: 19.9K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: