



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883

Company GST Registration No : 201828067M

**VEHICLE INSPECTION ESTIMATE**

M/S : CHINA TAIPING INSURANCE (S) PTE LTD  
(MOTOR CLAIM DEPARTMENT)

Email claimsdept@sg.cntaiping.com

Justin.

Parts - (%)	
SN	
Labour	
Lump sum	
ERV	

Vehicle No: SLT 269U

Date: 12.01.2021

Veh. Model HYUNDAI ELANTRA AD

Reg. Date 14.10.2017

Chassis No : KMHD841CMJU551119

DOA : 27.12.2020

1	FRONT BONNET <i>Dented</i>	1		\$ 1,741.20	✓
2	FRONT BONNET INSULATOR <i>new</i>	1		\$ 245.20	+
3	FRONT BONNET INNER LOCK <i>new</i>	1		\$ 235.90	+
4	FRONT BONNET STOPPER <i>new</i>	4	38.50	\$ 154.00	+
5	FRONT BUMPER <i>Dented</i>	1	<del>474.50</del>	<del>586.30</del>	✓
6	FRONT BUMPER SIDE AIR GUIDE <i>Dented</i>	2	145.60	291.20	✓
7	FRONT BUMPER TOP SEAL(RUBBER) <i>new</i>	1		98.70	+
8	FRONT BUMPER LOWER BEAM <i>new</i>	1		186.50	+
9	FRONT BUMPER SIDE RETAINERS <i>new</i>	2	86.30	<del>172.60</del>	863
10	FRONT BUMPER BRACKETS <i>new</i>	2	75.80	<del>151.60</del>	758
11	FRONT BUMPER REINFORCEMENT <i>Dented</i>	1		385.50	✓
12	FRONT RADIATOR GRILLE <i>cracked</i>	1		385.50	✓
13	FRONT BUMPER NUMBER PLATE GARNISH <i>cracked</i>	1		45.20	✓
14	FRONT BUMPER SPONGE <i>cracked</i>	1		186.30	✓
15	FRONT BUMPER TOW COVER <i>new</i>	1		48.20	+
16	FRONT BUMPER LOWER LIP <i>new</i>	1		108.50	+
17	FRONT FOGLAMP COVER <i>cracked</i>	1		156.30	✓
18	FRONT ENGINE UNDERCOVER <i>new</i>	1		286.50	+
19	FRONT SUPPORT PANEL <i>new</i>	1		987.50	✓
20	FRONT SUPPORT PANEL TOP GARNISH <i>cracked</i>	1		224.60	✓
21	FRONT HEADLAMP LH <i>cracked</i>	1		1,248.60	✓
22	FRONT HEADLAMP BRACKET LH <i>new</i>	1		89.70	+

C/F

8,015.60



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883  
 Company GST Registration No : 201828067M

**VEHICLE INSPECTION ESTIMATE**

Vehicle No: SLT 269U

B/F

8,015.60

1	FRONT AIR CLEANER BOX <i>mc</i>	1		196.30	+
2	FRONT FENDER LH <i>mc</i>	1		489.60	+
3	FRONT FENDER INNER COWLING <i>mc</i>	1		156.30	+
4	FRONT CONDENSER	1		798.70	+
5	FRONT RADIATOR	1		145.60	+
6	FRONT RADIATOR TOP HOSE	1		799.80	+
				10,601.90	
				6288.90	
				5031.12	
				Less 20%	
				2,120.38	
				<u>8,481.52</u>	

**Special nett item**

1	FRONT BONNET CLIPS <i>mc</i>	1 set		50.00	+
2	FRONT BUMPER CLIPS <i>mc</i>	1 set		30.00	+
3	FRONT NUMBER PLATE WITH CASING <i>Detail</i>	1 set		30.00	+
4	SUPPORT TOP GARNISH CLIPS <i>mc</i>	1 set		30.00	+
5	FRONT GRILLE CLIPS <i>mc</i>	1 set		30.00	+
6	FRONT ENGINE UNDERCOVER CLIPS <i>mc</i>	1 set		30.00	+
7	FRONT FENDER INNER COWLING CLIPS <i>mc</i>	1 set		30.00	+
8	RADIATOR COOLANT <i>mc</i>	1 set		60.00	+

160

To remove and replace accident affected portion.	1,600.00	80
To respray accident affected portion.	1,800.00	90
To tuff coat affected areas.	150.00	+
To apply sealant and under coating to the affected areas.	180.00	+
To conduct wiring check.	80.00	30
To conduct water leak test.	120.00	+
To remove / install condenser and top up air con gas.	150.00	120
<b>12,851.52</b>		

*Admin Lj*  
*H/S 12/01/20*  
*06 days*  
*total: 6541.12*  
*L/S: 5.2K*