

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

FBR 7765L

at Workshop m/s

Euro Success

of

Insured:

SLC 8070L

Policy No.

Claims No.

CMTD2003578/RUC


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

\$12k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

392

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBR7765L

Yr Regn:

22/10/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha R15

c.c

155

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

2694

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MEIRG6717 L0030747

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

100-80 R17

R:

140-70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MRF

Front

Rear

R/Bal.

f

mm

R/Bal.

A

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

5/11/20

D.O.I.

11/1/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear, n/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27A 7/67 Nott 4833

23/1/21 n/s & 2050 confirmed with merjie (Red B 17749.20, 90%)
 25/1/21 @ 2.20pm revised to Ruth Chun by email.

Date/Time, File Pass to?

☐

Preli. Report

1) Mr Turner
☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

TP

Lump Sum / I.B.I. (\$

2050

EURO SUCCESS SERV PTE. LTD

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: FBR7765L

Model: YAMAHA R15 ABS MANUAL

not Authorized
Bar
11/1/21
d/s to 2050/
Telephone After rep.
4 days.

QTY	List Items	Price \$
1	REAR NUMBER PLATE <i>Buf</i>	30.00 <i>10 5.~</i>
1	FRONT FOOT REST L/H <i>cut 68</i>	185.00 <i>✓</i>
1	FRONT FOOT REST BRACKET <i>sent 105</i>	360.00 <i>✓</i>
1 set	FRONT <i>fairing cut 1020</i>	1750.00 <i>✓</i>
1 SET	FRONT FORK TUBE <i>~</i>	740.00 <i>X</i>
1	FRONT FORK OILSEAL <i>~</i>	80.00 <i>X</i>
1	FRONT FORK OIL <i>~</i>	20.00 <i>X</i>
1	FRONT STEEM STEERING BEARING <i>~</i>	185.00 <i>X</i>
1	FRONT HEAD LAMP <i>~</i>	275.00 <i>X</i>
1	FRONT SPEEDO METER <i>~</i>	2450.00 <i>X</i>
1	FRONT MIRROR <i>als 320 48</i>	68.00 <i>✓</i>
1	FRONT BRAKE LEVER <i>~</i>	65.00 <i>X</i>
1	FRONT CLUTCH LEVER <i>sent 62</i>	65.00 <i>✓</i>
1	FRONT HANDLE BAR <i>als sent 175</i>	180.00 <i>✓</i>
1 SET	FRONT HANDLE GRIP <i>~</i>	30.00 <i>X</i>
1 SET	FRONT HANDLE BAR BALANCER <i>cut 28</i>	35.00 <i>✓</i>
1	THROTTLE CABLE <i>~</i>	65.00 <i>X</i>
1	CRASH BAR <i>~</i>	290.00 <i>X</i>
1	REAR SPORT RIM <i>R</i>	1200.00 <i>X</i>
1	REAR L/H DISC <i>~</i>	350.00 <i>X</i>
1	REAR RIM SAP <i>~</i>	75.00 <i>X</i>
1	REAR RIM BEARING <i>~</i>	40.00 <i>X</i>
1	RADIATOR <i>~</i>	780.00 <i>X</i>
1	RADIATOR FAN <i>~</i>	185.00 <i>X</i>
1	RADIATOR SIDE COVER IN <i>~</i>	80.00 <i>X</i>
1	RADIATOR SIDE COVER OUT <i>~</i>	185.00 <i>X</i>
1	COOLENT <i>~</i>	30.00 <i>X</i>
1	SIGNAL FRONT <i>als cut 75</i>	110.00 <i>✓</i>
1	<i>gear knel sent 145</i>	180.00 <i>✓</i>
1	REAR FOOT REST R/H <i>~</i>	75.00 <i>X</i>
1	REAR FOOT REST L/H <i>cut 68</i>	75.00 <i>✓</i>
1	REAR BRAKE CALIPER <i>~</i>	750.00 <i>X</i>
1	REAR <i>taillamp 188</i>	650.00 <i>✓</i>
1	REAR <i>wheel top garnish 205</i>	250.00 <i>✓</i>
1	SEAT <i>Torn 80</i>	300.00 <i>✓</i>
1	REAR SHOCK ABSORBER L/H <i>~</i>	400.00 <i>X</i>
TOTAL		\$12,588.00
LESS 10%		\$1,688.80
TOTAL		\$15,199.20

Labour Charges

Transportation charges

100.00 35

To respray painting and ~~ETC~~

1300.00 200

To check front and rear electrical wiring

11 200.00 X

To press rear sport rim and fork

11 350.00 X

To remove,refix and realign front fork

11 450.00 X

To straighten,repair and realign chassis frame member

11 1000.00 X

Panel beating,cut,weld remove and replace above parts

1200.00 300

\$4,600.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$19,799.20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p-2267
102
2040.30
2585.30
202
2068