



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21000437/Uqd3q2 Date: 02/03/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLC 8070L	Veh. Inspected	FBR 7765L	
Policy No.	D20MTPV01007657	Coverage (\$)	0.00	
Claim No.	CMTD2003578/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	11/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA R15	c.c	155	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	ME1RG6717L0030747	Colour	GREY	
Odometer	2694 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	100-80 R17	MRF	8 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70 R17	MRF	8 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/12/2020	Inspection Date	11/01/2021	
Survey held at	EURO SUCCESS SERVICES PTE LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	