



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 11.01.2021
Emailed : 20.01.2021, 3.30pm
Date Survey : _____

VEHICLE NO : SMN 9507 T
MODEL : KIA STONIC 1.0 A
WIP : 27152

Material	:	\$	<u>4,047.20</u>
Labour	:	\$	<u>3,850.00</u>
Sub-Total	:	\$	<u>7,897.20</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>7,897.20</u>
GST 7%	:	\$	<u>552.80</u>
Grand Total	:	\$	<u>8,450.00</u>
Finalise By/Date	:	<u>LOI / 20/01/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 11/01/2021	Cust No/Name	LCV11001/TAY CHEE YONG (ZHENG ZHIYONG)
	Reg No/Reg Date	SMN9507T*ECB1/ 02/09/2019
	Date In/Mileage	11/01/2021/ 19286
	Chassis/Package	KNAD6811VK6297469 /KC17
	Engine No	G3LCKP027889
	Make/Model	KIA/STONIC 1.0 A BET
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	20/01/2021/ 14:49	BLC	260 / AiTing	27152			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 400.00
E PNT98000 RESPRAY ON FRONT BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 350.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 120.00
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, REPAIR TAILGATE, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 400.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR TO FACILITATE REPAIR								✓ 60.00
E PNT98000 RESPRAY ON REAR BUMPER, BOOL TID, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 700.00
A 90000001 REMOVE & REPLACE REAR EXHAUST MUFFLER, AND CENTRE EXHAUST PIPE								✓ 400.00
A 90000001 REMOVE & REPLACE REAR CAMERA								✓ 300.00
M SUNDRY SUPPLY C&C LOGO								✓ 40.00
M SUNDRY SUNDRIES								✓ 20.00
S SPECIALISTJOB SUPPLY & REPLACE BOTH FRONT & REAR LICENSE PLATE WITH FRAME (\$50 + \$50)								✓ 100.00
S SPECIALISTJOB VACUUM & TOP UP A/COND GAS								80.00
E PNT88000 REMOVE & REPLACE A/COND CONDENSER								100.00
E PNT88000 REPAIR REAR END PANEL								400.00



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 11/01/2021	Cust No/Name	LCV11001/TAY CHEE YONG (ZHENG ZHIYONG)
	Reg No/Reg Date	SMN9507T*ECB1/ 02/09/2019
	Date In/Mileage	11/01/2021/ 19286
	Chassis/Package	KNAD6811VK6297469 /KC17
	Engine No	G3LCKP027889
	Make/Model	KIA/STONIC 1.0 A BET
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	20/01/2021/ 14:49	BLC	260 / AiTing	27152			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT98000								350.00
RESPRAY ON REAR END PANEL → Supp.								
X	COVER-FR BUMPER UPR				1.00	✓ 476.00	20.00	380.80
X	LOGO ASSY-KIA SUB				1.00	✓ 51.00	20.00	40.80
X	EMBLEM-STONIC				1.00	✓ 26.00	20.00	20.80
X	EMBLEM-TURBO G.D.I				1.00	✓ 38.00	20.00	30.40
X	COVER-RR BUMPER LWR				1.00	✓ 366.00	20.00	292.80
X	SKID PLATE-RR BUMPER				1.00	✓ 122.00	20.00	97.60
X	MOULDING ASSY-RR BUMPER SIDE,L				1.00	✓ 152.00	20.00	121.60
X	STAY-RR BUMPER RH				1.00	✓ 55.00	20.00	44.00
X	STAY-RR BUMPER LH				1.00	✓ 55.00	20.00	44.00
X	BEAM-RR BUMPER				1.00	✓ 419.00	20.00	335.20
X	MUFFLER ASSY-REAR				1.00	✓ 665.00	20.00	532.00
X	MUFFLER ASSY-CENTER				1.00	? 362.00	20.00	289.60
X	RR CAMERA & TRUNK LID HDL ASSY				1.00	? 758.00	20.00	606.40
X	COVER-RR BUMPER SIDE UNDER				1.00	? 62.00	20.00	49.60
X	CAP-RR HOOK → Supp.				1.00	5.00	20.00	4.00
X	MOULDING-FRONT BUMPER A/INTAKE				1.00	? 61.00	20.00	48.80
X	ABSORBER-FRONT BUMPER ENERGY				1.00	? 98.00	20.00	78.40
X	GRILLE-FRONT BUMPER				1.00	? 96.00	20.00	76.80
X	BEAM COMPLETE-FR BUMPER				1.00	? 544.00	20.00	435.20
X	CONDENSER ASSY-COOLER → Supp.				1.00	648.00	20.00	518.40
Z TEXT								
AIG OD CLAIM.								
DOA : 11.01.21								
SURVEYOR STEVE LKK 11.01.21								
POLICY NO : 1900156670								

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	4,047.20	Nett	7,897.20
Labour	3,610.00	7% GST on	552.80
Standard Menu	0.00		
Specialist Job	180.00	Total Payable	8,450.00
Diagnostics Job	0.00		
Sundry/Others	60.00		
Total(w/o GST)	7,897.20		

This is not an official tax invoice.
This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SMN 9507 T**

<u>Materials</u>		<u>Cost (\$)</u>
1	Cap-RR hook	5.00
2	Condenser assy-cooler	648.00
Total Materials		653.00
Less 20% discount		130.60
Total after discount		522.40
<u>Labour</u>		<u>Cost (\$)</u>
1	Vacuum & Top up A/Cond gas	80.00
2	Remove & replace A/cond condenser	100.00
3	Repair rear end panel	400.00
4	Respray on rear end panel	350.00
Total labour		930.00
Total amount		1,452.40
7% GST		101.67
Grand total		<u>\$ 1,554.07</u>

Thank You.

Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240



HOME

Online



STONIC(YB CU../2019/G 1.0 T-G..

VCI



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



10/10

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
i-TPMS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0237

VCI Ver.

02.49

ECU Ver.

M-E-K-01-00-0178

OS Ver.

Android 10