



CYCLE &amp; CARRIAGE

CYCLE &amp; CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TAY CHEE YONG (ZHENG ZHIYONG)  3 FERVALE CLOSE #02-08 SINGAPORE 797486  Contact No	Cust No/Name	LCV11001/TAY CHEE YONG (ZHENG ZHIYONG)
	Reg No/Reg Date	SMN9507T*ECB1/ 02/09/201
	Date In/Mileage	/ 0
	Chassis No	KNAD6811VK6297469
	Engine No	G3LCKP027889
	Make/Model	KIA/STONIC 1.0 A BET
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV11001	CRDVCH	11/01/2021/ 11:08	BLC	442 / CocoLu	27152		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000		RENEW FRT BUMPER					430 800.00
E PNT98000		SPRAY PAINT FOR FRT BUMPER					350 700.00
M SUNDRY		FRT NUMBER PLATE WITH FRAME					50.00
A 90000001		CHECK WIRING & ELECTRICAL SYSTEM					30.00
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					120.00
E PNT88000		RENEW REAR BUMPER, REAR END PANEL, REPAIR TAILGATE					400 1600.00
E PNT88000		REMOVE & INSTALL PARKING SENSOR					60.00
E PNT98000		SPRAY PAINT FOR REAR BUMPER, REAR END PANEL, BOOLTID					700 1600.00
E PNT88000		REMOVE & INSTALL REAR COMPARTMENT TRIMS					300.00
A 90000001		RENEW REAR EXHASUT SYSTEM					400.00
A 90000001		RENEW REAR CAMERA					300.00
M SUNDRY		APPLY SEALANT FOR ACCIDENT PORTION					40.00
M SUNDRY		SUPPLY REAR NUMBER PLATE					50.00
M SUNDRY		C&C LOGO					40.00
M SUNDRY		Sundry					20.00
M COVER-FR BUMPER UPR				1.00	476.00	00.00	476.00
M COVER-FR BUMPER, LWR				1.00	367.00	00.00	367.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TAY CHEE YONG (ZHENG ZHIYONG)  3 FERNVALE CLOSE #02-08 SINGAPORE 797486  Contact No	Cust No/Name	LCV11001/TAY CHEE YONG (ZHENG ZHIYONG)
	Reg No/Reg Date	SMN9507T*ECB1/ 02/09/201
	Date In/Mileage	/ 0
	Chassis No	KNAD6811VK6297469
	Engine No	G3LCKP027889
	Make/Model	KIA/STONIC 1.0 A BET
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV11001	CRDVCH	11/01/2021/ 11:08	BLC	442 / CocoLu	27152
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M GRILLE-FRONT BUMPER		1.00	96.00	00.00	96.00
M SKID PLATE-FR BUMPER	X	1.00	55.00	00.00	55.00
M GRILLE ASSY-RADIATOR		1.00	324.00	00.00	324.00
M MOULDING-FRONT BUMPER A/INTAKE		1.00	61.00	00.00	61.00
M ABSORBER-FRONT BUMPER ENERGY		1.00	98.00	00.00	98.00
M STIFFNER-FR BPR LWR	X	1.00	123.00	00.00	123.00
M BRACKET-FR BUMPER SIDE,RH		1.00	13.00	00.00	13.00
M BRACKET-FR BUMPER SIDE,LH		1.00	13.00	00.00	13.00
M BEAM COMPLETE-FR BUMPER		1.00	544.00	00.00	544.00
M ORNAMENT-KIA NO.115	X	1.00	32.00	00.00	32.00
M LOGO ASSY-KIA SUB		1.00	51.00	00.00	51.00
M EMBLEM-STONIC	rec	1.00	26.00	00.00	26.00
M EMBLEM-TURBO G.D.I	rec	1.00	38.00	00.00	38.00
M LAMP ASSY-HEAD,RH		1.00	1845.00	00.00	1845.00
M LAMP ASSY-HEAD,LH		1.00	1845.00	00.00	1845.00
M COVER-RR BUMPER LWR	BR	1.00	366.00	00.00	366.00
M SKID PLATE-RR BUMPER	BR (Silva)	1.00	122.00	00.00	122.00
M MOULDING ASSY-RR BUMPER SIDE,R		1.00	152.00	00.00	152.00
M MOULDING ASSY-RR BUMPER SIDE,L		1.00	152.00	00.00	152.00
M LAMP ASSY-REAR FOG & R/REFL,RH		1.00	111.00	00.00	111.00
M LAMP ASSY-REAR FOG & R/REFL,LH		1.00	111.00	00.00	111.00
M COVER-RR BUMPER SIDE UNDER		1.00	62.00	00.00	62.00
M WIRING HARNESS-BWS EXT		1.00	245.00	00.00	245.00
M BRACKET-RR BEAM UPR MTG		2.00	7.00	00.00	14.00
M BRACKET-RR BEAM LWR MTG,RH		1.00	5.00	00.00	5.00
M BRACKET-RR BEAM LWR MTG,LH		1.00	7.00	00.00	7.00
M ANTENNA ASSY-SMARTKEY		1.00	32.00	00.00	32.00
M STAY-RR BUMPER RH	BT	1.00	55.00	00.00	55.00
M STAY-RR BUMPER LH	BT	1.00	55.00	00.00	55.00
M BEAM-RR BUMPER	BR	1.00	419.00	00.00	419.00
P ULTRASONIC SENSOR ASSY-BWS		2.00	189.00	00.00	378.00
P ULTRASONIC SENSOR ASSY-BWS		2.00	189.00	00.00	378.00
M PANEL ASSY-BACK	X R	1.00	345.00	00.00	345.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TAY CHEE YONG (ZHENG ZHIYONG)  3 FERNVALE CLOSE #02-08 SINGAPORE 797486  Contact No	Cust No/Name	LCV11001/TAY CHEE YONG (ZHENG ZHIYONG)
	Reg No/Reg Date	SMN9507T*ECB1/ 02/09/201
	Date In/Mileage	/ 0
	Chassis No	KNAD6811VK6297469
	Engine No	G3LCKP027889
	Make/Model	KIA/STONIC 1.0 A BET
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV11001	CRDVCH	11/01/2021/ 11:08	BLC	442 / CocoLu	27152			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
M	MUFFLER ASSY-REAR	✓ DD			1.00	665.00	00.00	665.00
M	MUFFLER ASSY-CENTER	✓ ?			1.00	362.00	00.00	362.00
M	RR CAMERA & TRUNK LID HDL ASSY	✓ CUT			1.00	758.00	00.00	758.00

# Estimate

Steve CLKK) 00- AM AL  
 11/1/21, 1.00pm Excers - ?  
 P/P  
 My Bal spy  
 7 days

Confirm &amp; accepted by

7% GST on	Nett 16911.00	16,911.00
		1183.77
Total Payable		18,094.77

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.