

:::::::::::::::::::

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K	ESTIMATE	GST Reg No : MR-8500111-			
Invoice Name & Address		Owner Name & Vehicle Info			
Ng Bee Hoon	Cust No/Name	/Ng Bee Hoon			
3 555 110011	Reg No/Reg Date	SFM9300K / 30/06/201			
BLK 354 YISHUN RING ROAD	Date In/Mileage				
#07-1778	Chassis No	KNACC81CVH5087831			
SINGAPORE 760354		G4LEHS158528			
Contact No Mobile: 93366655		KIA/NIRO 1.6 A			
		DN9 RICH ESPRESSO / WK SATURN BLACK			

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No			
CSM00081	Cash	11/01/2021/ 12:03	BLC	442 / CocoLu		27158			
CSM00081	Cash	Description of Goods			Qty	Unit Price	Disc%	Ar	nount
F DNTOOOO	committee for exercis	Description of Goods	S / Sel vice.	September 18 Committee of the Committee				400	1200.00
E PNT88000	AD DIMDE	R. REPAIR TAILGATE, F	REAR END F	ANEL 490XI				,	60.0
E PNT88000	MR BUMPE	N, KERRIK INICOMIC)	(2) (1)	× 1			9		00.0
	INSTALL	PARKING SENSOR						700	1050.0
DNTOROOO				-64 4 6				700	200011
SPRAY PA	ITN FOR I	REAR BUMPER, TAIGLATE	, REAR E	ND PANEL 350 X 1					50.0
SUNDRY									
	AR NUMBER	R PLATE WITH FRAME							30.0
90000001	1 2 200	TOTAL CUSTOM							
		ECTRICAL SYSTEM		6 1					120.
10028901	AUT D140	MOSTIC CHECK HISTNE 4	E CAN DE	ima		3		1	
TO CARRY	OUI DIAG	NOSTIC CHECKLUSING			11 (=	7)			
USING HI-	SCAN PRO		ال ا	1111111(21	66	ク			40.
SUNDRY C&C LOGO									
SUNDRY									20.
Sundry								/	406
COVER-RR	BUMPER.U	PR / BR			1.00		00.00		486.
COVER-RR	BUMPER L	WR CUT			1.00		00.00		392.
SKID PLAT		000 / /// .	LIAI		1.00		00.00		122. 27.
COVER-RR	BUMPER S	IDE UNDER, LH	MN		1.00		00.00		16.
PIECE-RR					1.00		00.00		16.
PIECE-RR I					1.00		00.00		27.
		IDE UNDER, RH X XX BUMPER SIDE, R	VM		1.00 1.00		00.00		20.
			VN		1.00		00.00		20.
			ÓŘ		1.00		00.00		104.
			/		1.00		00.00		27.
LAMP ASSY			A.I		1.00		00.00		27.
LAMP ASSY			/ • /		1.00		00.00		6.
BRACKET-RI		WR MTG X N/M			1.00	261.00			261.
BEAM-RR BI BRACKET-RI		- 1 V 1/1.1			1.00		00.00		6.
	K KAIL L						00.00		67.

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

	ESTIMATE	
Invoice Name & Address		Owner Name & Vehicle Info
Ng Bee Hoon	Cust No/Name	/Ng Bee Hoon SEM9300K / 30/06/201
BLK 354 YISHUN RING ROAD	Reg No/Reg Date Date In/Mileage	/ 0
#07-1778	Chassis No	KNACC81CVH5087831 G4LEHS158528
SINGAPORE 760354		VIA/NIRO 1.6 A
Contact No Mobile: 93366655	Colour/Trim	DN9 RICH ESPRESSO / WK SATURN BLACK

	Colour/Trim	DN9 RICH E	ST NESSE		
	Operator		WIP No		Carrier (Mr. 1994) (Page 14) (Mr. 1994) (Page 14) Ann albeight of the American Carrier (Mr. 1994)
Account No Terms Date/Time Printed CSE	442 / CocoLu		27158		
CSM00081 Cash 11/01/2021/ 12:03 BLC		Qty	Unit Price	Disc%	Amount
Description of Goods / Service M BRACKET-RR BEAM UPR MTG, LH / K N/N M EMBLEM-NIRO / N/C M LOGO-KIA / N/C M EMBLEM-ECO HYBRID / N/C	ces	1.00 1.00 1.00 1.00	6.00 25.00 42.00	00.00 00.00 00.00 00.00	6.00 25.00 42.00 29.00
		o∯ <i>©</i>)		

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

& accepted by all approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Nett 4296.00 7% GST on

> 4.596.72 Total Payable

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any auditional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewing of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

4,296.00

300.72