



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Ng Bee Hoon	Cust No/Name	/Ng Bee Hoon
BLK 354 YISHUN RING ROAD	Reg No/Reg Date	SFM9300K / 30/06/201
#07-1778	Date In/Mileage	/ 0
SINGAPORE 760354	Chassis No	KNACC81CVH5087831
Contact No Mobile: 93366655	Engine No	G4LEHS158528
	Make/Model	KIA/NIRO 1.6 A
	Colour/Trim	DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	11/01/2021/ 12:03	BLC	442 / CocoLu	27158			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1200.00
RENEW REAR BUMPER, REPAIR TAILGATE, REAR END PANEL								
E PNT88000								60.00
REMOVE & INSTALL PARKING SENSOR								
E PNT98000								1050.00
SPRAY PAINT FOR REAR BUMPER, TAILGATE , REAR END PANEL								
M SUNDRY								50.00
APPLY REAR NUMBER PLATE WITH FRAME								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								40.00
C&C LOGO								
M SUNDRY								20.00
Sundry								
M COVER-RR BUMPER,UPR					1.00	486.00	00.00	486.00
M COVER-RR BUMPER LWR					1.00	392.00	00.00	392.00
M SKID PLATE-RR BUMPER					1.00	122.00	00.00	122.00
M COVER-RR BUMPER SIDE UNDER,LH					1.00	27.00	00.00	27.00
M PIECE-RR BUMPER SIDE,LH					1.00	16.00	00.00	16.00
M PIECE-RR BUMPER SIDE,RH					1.00	16.00	00.00	16.00
M COVER-RR BUMPER SIDE UNDER,RH					1.00	27.00	00.00	27.00
M MOULDING ASSY-RR BUMPER SIDE,R					1.00	20.00	00.00	20.00
M MOULDING ASSY-RR BUMPER SIDE,L					1.00	20.00	00.00	20.00
M REFLECTOR/REFLEX ASSY-RR LH					1.00	104.00	00.00	104.00
M LAMP ASSY-LICENSE PLATE,LH					1.00	27.00	00.00	27.00
M LAMP ASSY-LICENSE PLATE,RH					1.00	27.00	00.00	27.00
M BRACKET-RR RAIL LWR MTG					1.00	6.00	00.00	6.00
M BEAM-RR BUMPER					1.00	261.00	00.00	261.00
M BRACKET-RR RAIL LWR MTG					1.00	6.00	00.00	6.00
M STAY-RR BUMPER LH					1.00	67.00	00.00	67.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Ng Bee Hoon BLK 354 YISHUN RING ROAD #07-1778 SINGAPORE 760354 Contact No Mobile: 93366655	Cust No/Name	/Ng Bee Hoon
	Reg No/Reg Date	SFM9300K / 30/06/201
	Date In/Mileage	/ 0
	Chassis No	KNACC81CVH5087831
	Engine No	G4LEHS158528
	Make/Model	KIA/NIRO 1.6 A
	Colour/Trim	DN9 RICH ESPRESSO / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	11/01/2021/ 12:03	BLC	442 / CocoLu	27158		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	BRACKET-RR BEAM UPR MTG,LH			1.00	6.00	00.00	6.00
M	EMBLEM-NIRO			1.00	25.00	00.00	25.00
M	LOGO-KIA			1.00	42.00	00.00	42.00
M	EMBLEM-ECO HYBRID			1.00	29.00	00.00	29.00

Estimate

Confirm & accepted by

	Nett	4,296.00
7% GST on	4296.00	300.72
Total Payable		4,596.72

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.