



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2102941
INV Date 27/04/2021
Reference CC4/LPC21000449/Ags3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMS 8374P
Insured Veh. GBD 2849K
Claim No. 20/21/21/VC05/024118
Policy No. Z20VC05004629
Accident Date 10/01/2021
Inspection Date 12/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CC4/LPC21000449/Ags3q2 Date: 27/04/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 2849K	Veh. Inspected	SMS 8374P
Policy No.	Z20VC05004629	Coverage (\$)	0.00
Claim No.	20/21/21/VC05/024118	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	11/01/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA FREED	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	GB71093694	Colour	GREY
Odometer	71877 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	185/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/65 R15	YOKOHAMA	6 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	10/01/2021	Inspection Date	12/01/2021
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 8374P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BONNET	DENTED	820.00	820.00
1	FRONT BONNET LOCK	NOT NECESSARY	160.00	-
1	FRONT BUMPER	DEFORMED	1,050.40	950.00
2	FRONT BUMPER SIDE RETAINER @\$58.40	NOT NECESSARY	116.80	-
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	50.00	-
1	FRONT BUMPER CENTRE GRILLE ASSY	CRACKED	890.00	740.00
1	FRONT BUMPER CENTRE GRILLE LOGO	NECESSARY	92.30	92.30
1	FRONT BUMPER REINFORCEMENT	BENT	450.00	296.00
2	FRONT BUMPER REINFORCEMENT BRACKET @\$80.00	NOT NECESSARY	160.00	-
1	HEADLAMP RH	CRACKED	1,988.50	1,740.00
1	HEADLAMP LOWER BRACKET RH	NOT NECESSARY	60.50	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	780.00	-
	LESS 20% DISCOUNT		-1,323.70	-927.66
			5,294.80	3,710.64
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	CRACKED	50.00	50.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	SET HEADLAMP CLIPS (SN)	NOT NECESSARY	20.00	-
			90.00	70.00
<u>LABOUR</u>				
	PANEL BEATING ,REMOVAL AND REPLACING PARTS.		1,400.00	400.00
	TO SPRAY PAINT AFFECTED AREA.		1,400.00	400.00
	TUFF COAT.	NOT NECESSARY	120.00	-
	WIRING CHECK .		90.00	30.00
	CONDUCT WATER LEAKAGE TEST .	NOT NECESSARY	50.00	-
	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS.	NOT NECESSARY	100.00	-

Report Ref No. CC4/LPC21000449/Ags3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.	NOT NECESSARY	80.00	-
			3,240.00	830.00
GRAND TOTAL			8,624.80	4,610.64
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,600.00

Report Ref No. CC4/LPC21000449/Ags3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMS 8374P

INSPECTION







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMS 8374P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

