

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

| | | | |
|--|-------------------------|--------------------|-------------|
| TO | : LONPAC | DATE | : 11-Jan-21 |
| ATTENTION | : MOTOR CLAIMS DEPT | JOB TYPE | : T/P CLAIM |
| ESTIMATE REPORT | : | | |
| <u>VEHICLE DETAILS</u> | | | |
| VEHICLE NO | : SMS8374P | | |
| MODEL | : HONDA FREED 1.5 | | |
| CHASSIS NO | | | |
| <u>ACCIDENT DETAILS</u> | DATE : 10-Jan-21 | <i>Cecilia.</i> | |
| | TIME : 13:30 | <i>GB71093694.</i> | |
| THIRD PARTY REQUESTOR / CONTACT | : JACK LI | | |

CLAIM DETAIL : PARTS

| S/N | DESCRIPTION | QTY | UNIT LIST PRICE | TOTAL LIST PRICE | |
|-----|--|-----|-----------------|------------------|---------|
| 1 | FRONT BONNET <i>Dental.</i> | 1 | \$ 820.00 | \$ 820.00 | - |
| 2 | FRONT BONNET LOCK <i>New</i> | 1 | \$ 160.00 | \$ 160.00 | + |
| 3 | FRONT BUMPER <i>Dental</i> | 1 | \$ 1,050.40 | \$ 1,050.40 | → 950. |
| 4 | FRONT BUMPER SIDE RETAINER <i>New Rec</i> | 2 | \$ 58.40 | \$ 116.80 | + |
| 5 | FRONT BUMPER TOWING COVER <i>New</i> | 1 | \$ 50.00 | \$ 50.00 | + |
| 6 | FRONT BUMPER CENTRE GRILLE ASSY <i>Cracked</i> | 1 | \$ 890.00 | \$ 890.00 | → 740. |
| 7 | FRONT BUMPER CENTRE GRILLE LOGO <i>New</i> | 1 | \$ 92.30 | \$ 92.30 | - |
| 8 | FRONT BUMPER REINFORCEMENT <i>Best</i> | 1 | \$ 450.00 | \$ <u>450.00</u> | → 296. |
| 9 | FRONT BUMPER REINFORCEMENT BRACKET <i>New</i> | 2 | \$ 80.00 | \$ 160.00 | + |
| 10 | HEADLAMP RH <i>Cracked</i> | 1 | \$ 1,988.50 | \$ 1,988.50 | → 1740. |
| 11 | HEADLAMP LOWER BRACKET RH <i>New</i> | 1 | \$ 60.50 | \$ 60.50 | + |
| 12 | FRONT SUPPORT PANEL <i>New</i> | 1 | \$ 780.00 | \$ 780.00 | + |

4638.30

TOTAL PRICE \$ 6,618.50

LESS 20% \$ 1,323.70

3710.64

SUB TOTAL PRICE \$ 5,294.80

SPECIAL NETT ITEMS

| S/N | DESCRIPTION | QTY | UNIT S/NETT | TOTAL S/NETT |
|--------------|-----------------------------------|-----|-------------|-----------------|
| 1 | FRONT NUMBER PLATE <i>changed</i> | 1 | \$ 50.00 | \$ 50.00 |
| 2 | FRONT BUMPER CLIPS(SET) <i>re</i> | 1 | \$ 20.00 | \$ 20.00 |
| 3 | HEADLAMP CLIPS(SET) <i>re re</i> | 1 | \$ 20.00 | \$ 20.00 |
| TOTAL | | | | \$ 90.00 |

70

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

| | | | | |
|---|---|------------------------|------------|--|
| 1 | PANEL BEATING, REMOVAL AND REPLACING PARTS | \$ 1,400.00 | <i>900</i> | |
| 2 | TO SPRAY PAINT AFFECTED AREA | \$ 1,400.00 | <i>400</i> | |
| 3 | TUFF COAT | \$ 120.00 | <i>x</i> | |
| 4 | WIRING CHECK | \$ 90.00 | <i>30</i> | |
| 5 | CONDUCT WATER LEAKAGE TEST | \$ 50.00 | <i>x</i> | |
| 6 | REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS | \$ 100.00 | <i>x</i> | |
| 7 | REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST | \$ 80.00 | <i>x</i> | |

830

TOTAL \$3,240.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,384.80
 TOTAL LABOUR COST : \$ 3,240.00
 TOTAL REPAIR COST : \$ 8,624.80

APPROVED DETAILS

SURVEYOR :
 CONTACT NO :
 PART BY PART / LUMP SUM :
 NO OF DAYS :

Admin Lj
1/s 12/01/21
 FAX : *04 Days*

total: 4610.64
1/s: 3.6k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: