



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2102650

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 15/04/2021
Reference CC6/CTI21000451/Aes3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SKC 246L
Insured Veh. GBF 6275D
Claim No. SNM20D205140/C02
Policy No. DMCVSNW00010352001
Accident Date 23/12/2020
Inspection Date 06/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21000451/Aes3q2 Date: 15/04/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 6275D	Veh. Inspected	SKC 246L	
Policy No.	DMCVSNW00010352001	Coverage (\$)	0.00	
Claim No.	SNM20D205140/C02	Excess (\$)	0.00	
Assign From		Assign Date	06/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	ZGE200006831	Colour	GREY	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/12/2020	Inspection Date	06/01/2021	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 246L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR R/H TAIL LAMP	CRACKED	374.45	374.45
2	REAR R/H TAIL LAMP CLIP @\$8.00	NOT NECESSARY	16.00	-
1	REAR R/H TAIL LAMP PANEL	NOT NECESSARY	678.50	-
1	REAR BUMPER	DEFORMED	481.90	481.90
1	REAR R/H BUMPER SIDE RETAINER	NECESSARY	121.25	121.25
8	REAR BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
1	REAR R/H BUMPER SIDE REFLECTOR	NOT NECESSARY	131.35	-
1	REAR BUMPER BRACKET	NOT NECESSARY	131.35	-
1	REAR BUMPER CENTER TOP RUBBER	NOT NECESSARY	141.40	-
1	REAR R/H FENDER	DENTED	1,217.30	1,217.30
1	REAR R/H FENDER GLASS	NOT NECESSARY	280.00	-
1	REAR R/H FENDER INNER TRIM BOARD	NOT NECESSARY	781.40	-
8	REAR R/H FENDER INNER TRIM BOARD CLIP @\$6.50	NOT NECESSARY	52.00	-
	LESS 25% DISCOUNT		-	-556.23
			4,458.90	1,668.67
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	350.00	-
1	REAR R/H FENDER GLASS SEAL (SN)	NECESSARY	70.00	40.00
			420.00	40.00
<u>LABOUR</u>				
	TO REMOVE & REFIT CUSHION & TRIM BOARD.		280.00	60.00
	TO REMOVE & REFIT REVERSE SENSOR .		100.00	50.00
	TO REMOVE & REFIT REAR FENDER GLASS .		120.00	60.00
	GUM.		60.00	30.00
	TO CHECK WIRING .		100.00	30.00
	TUFF KOTE.		150.00	40.00
	PANEL BEATING.		1,200.00	600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING .		1,000.00	600.00
			3,010.00	1,470.00
GRAND TOTAL			7,888.90	3,178.67
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CC6/CTI21000451/Aes3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKC 246L

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKC 246L

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

