

SmartOne Auto Pte. Ltd.

Co. Reg No: 201939368E

8 Kaki Bukit Avenue 4

#08-09 Premier @ Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

Email: smartoneauto@gmail.com



DATE : 14.01.21

TO : **BUDGET DIRECT** MOTOR CLAIMS DEPTS
VEHICLE NO : **YM6358P**
MODEL : **MIT-FE83BEOSRDEA**
DATE OF ACCIDENT : 08.01.21
TIME OF ACCIDENT : 18:55HRS

Veron.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Best</i>	1	\$ 796.00	\$ 796.00
2	TAIL LAMP RH <i>could RH</i>	2	\$ 275.00	\$ 550.00
3	REAR NUMBER PLATE LAMP <i>new</i>	1	\$ 85.00	\$ 85.00
4	REAR SIDE STOPPER RH <i>new</i>	2	\$ 25.00	\$ 50.00
5	CARGO BED END PANEL <i>new</i>	1	\$ 1,274.00	\$ 1,274.00
6	REAR CHASSIS CROSS MEMBER <i>new</i>	1	\$ 2,845.00	\$ 2,845.00

1071
803.25

TOTAL PRICE \$ 5,600.00
LESS 25% \$ 1,400.00
SUB TOTAL PRICE \$ 4,200.00

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 80.00	\$ 80.00
2	REAR BACK OPEN DOOR RH	1	\$ 2,800.00	\$ 2,800.00
3	REAR BOX BACK DOOR HINGE RH	2	\$ 180.00	\$ 360.00
4	REAR BOX BACK DOOR STAND HOLDER RH	1	\$ 40.00	\$ 40.00
5	REAR BOX BACK DOOR LOCK CATCH RH	1	\$ 200.00	\$ 200.00
6	REAR BOX BACK DOOR LOCK ROD RH	1	\$ 750.00	\$ 750.00
7	REAR BOX OPEN DOOR '60KM/H'	1	\$ 30.00	\$ 30.00
8	REAR STEP BRACKET (SPECIAL TYPE) <i>Best</i>	1	\$ 680.00	\$ 680.00
9	REAR SAFETY BAR (SPECIAL TYPE) <i>Best</i>	1	\$ 2,200.00	\$ 2,200.00
10	CARGO BED CHASSIS MEMBER (WOODEN) <i>could</i>	2	\$ 4,800.00	\$ 9,600.00
11	CARGO BED BOTTOM BEAM (WOODEN) <i>could</i>	4	\$ 850.00	\$ 3,400.00
12	CARGO BED U CLIP <i>new</i>	8	\$ 120.00	\$ 960.00

TOTAL \$ 21,100.00

3480

TO : **BUDGET DIRECT** MOTOR CLAIMS DEPTS
VEHICLE NO : **YM6358P**
MODEL : **MIT-FE83BEOSRDEA**

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 1,600.00	600
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,600.00	600
3	TO SPRAY TUFF COAT	\$ 250.00	60
4	WIRING, BULB CHECKING	\$ 80.00	30
5	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x
6	REMOVE AND REFIX REAR CARGO BED	\$ 2,800.00	500
7	REAR CHASSIS ALIGHMENT	\$ 250.00	x
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ **6,840.00** 1790

ESTIMATE REPORT

TOTAL PARTS COST : \$ 25,300.00
TOTAL LABOUR COST : \$ 6,840.00
TOTAL REPAIR COST : \$ 32,140.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER,YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR

MICHELLE

HP : 9856 4815

Adrian Lj

1/s 14/01/21

06 days

total 608325

4/s : 4.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: