



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMT 1939B

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | REAR BUMPER | TO REPAIR SEE LABOUR | 1,099.00 | - |
| 1 | BRACKET CENTER | SERVICEABLE | 5.40 | - |
| 1 | RETAINER LHS | SERVICEABLE | 41.00 | - |
| 4 | GROMMET, REAR BUMPER | NOT NECESSARY | 10.80 | - |
| 2 | RUBBER SEAL, REAR BUMPER | NOT NECESSARY | 27.40 | - |
| 4 | CLIP, REAR BUMPER | NOT NECESSARY | 14.80 | - |
| 2 | RIVET, REAR BUMPER | NOT NECESSARY | 18.40 | - |
| 6 | RIVET, REAR BUMPER | NOT NECESSARY | 48.00 | - |
| 6 | FASTENER, REAR BUMPER | NOT NECESSARY | 18.00 | - |
| 4 | TAPE PROTECTOR, REAR BUMPER | NOT NECESSARY | 18.80 | - |
| 1 | GASKET LHS, TAILLAMP | NOT NECESSARY | 46.00 | - |
| 1 | GASKET RHS, TAILLAMP | NOT NECESSARY | 46.00 | - |
| 1 | STONE GUARD RHS | NOT NECESSARY | 17.40 | - |
| | | | 1,411.00 | - |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | SUNDRIES (SN) | NECESSARY | 100.00 | 20.00 |
| | | | 100.00 | 20.00 |
| <u>LABOUR</u> | | | | |
| | TO REPLACE FRONT BUMPER. REPAIR REAR FENDER RH AND ALL AREAS AFFECTED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR BUMPER. | | 1,980.00 | 990.00 |
| | TO RESPRAY FRONT BUMPER AND REAR FENDER RH. | | 1,890.00 | 1,260.00 |
| | TO TRANSFER REVERSE SENSORS. | NOT NECESSARY | 330.00 | - |
| | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. | | 250.00 | 150.00 |
| | TO CARRY-OUT BODY CAVITY PRESERVATION. (INCLUDING NEW PARTS AND CAOUTCHOU) | NOT NECESSARY | 250.00 | - |
| | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. | | 350.00 | 180.00 |
| | | | 5,050.00 | 2,580.00 |
| GRAND TOTAL | | | 6,561.00 | 2,600.00 |



| | | | |
|-----------------------------|--|--|----------|
| RECOMMENDED COST OF REPAIRS | | | 2,600.00 |
|-----------------------------|--|--|----------|

Report Ref No. CS/GAI21000458/R1vd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.