



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

3 TEMASEK AVENUE  
#16-01 CENTENNIAL TOWER  
SINGAPORE 039190

Ref: CS/GAI21000458/R1vd3e2

Date: 25/03/2021

Code: GAI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SMU 3468A	<b>Veh. Inspected</b>	SMT 1939B
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CLMOMVP000001120	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	SHERY WONG	<b>Assign Date</b>	11/01/2021

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MAZDA 6 SEDAN 2.0 AT EX	<b>c.c</b>	1998
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2020
<b>Chassis No.</b>	JM6GL1072K0319406	<b>Colour</b>	BLACK
<b>Odometer</b>	18222 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	225/55 R17	BRIDGESTONE	6 mm
<b>L/H Front Tyre</b>	225/55 R17	BRIDGESTONE	6 mm
<b>R/H Rear Tyre</b>	225/55 R17	BRIDGESTONE	6 mm
<b>L/H Rear Tyre</b>	225/55 R17	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	06/01/2021	<b>Inspection Date</b>	15/01/2021
<b>Survey held at</b>	27A TANJONG PENJURU		
<b>Repairer</b>	TRANS EUROKARS PTE LTD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>4 Working Days</b>
--	-----------------------