



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737896

HP: 98888885

Estimation

Date:

Vehicle:

Make / Model:

Chassis:

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

12/1/2021

Acknowledged by Repairer: SMW6341B

Signature:

Date: TOYOTA PRIUS

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER <i>/cut</i>	1	\$ 658.00	\$ 658.00
2	REAR BUMPER SIDE RETAINER RH <i>X SVC</i>	1	\$ 112.00	\$ 112.00
3	REAR BUMPER BRACKET <i>X SVC</i>	2	\$ 114.00	\$ 228.00
4	REAR BUMPER LIP <i>/cut</i>	1	\$ 728.90	\$ 728.90
5	REAR BUMPER REFLECTOR RH <i>X SVC</i>	1	\$ 68.00	\$ 68.00
6	REAR FENDER RH <i>X SVC</i>	1	\$ 897.00	\$ 897.00
7	REAR FENDER COWLING RH <i>X SVC</i>	1	\$ 128.30	\$ 128.30
8	TAILLAMP RH <i>X SVC</i>	1	\$ 587.00	\$ 587.00
9	REAR TAILLAMP LOWER BRACKET RH <i>X SVC</i>	1	\$ 82.00	\$ 82.00
10	REAR WHEEL BEARING RH <i>X SVC</i>	1	\$ 298.00	\$ 298.00
11	REAR ABSORBER RH <i>X SVC</i>	1	\$ 387.00	\$ 387.00
12	AXLE <i>X SVC</i>	1	\$ 1,598.00	\$ 1,598.00
				\$ 5,772.20
			Less 20%	\$ 1,154.44
			Total	\$ 4,617.76
S/Nett items:				
1	REAR BUMPER CLIPS <i>/Nec.</i>	1	\$ 80.00	\$ 80.00
2	REAR REVERSE SENSOR <i>X SVC</i>	1	\$ 250.00	\$ 250.00
3	REAR WHEEL HUB COVER RH <i>/SCR</i>	1	\$ 100.00	\$ 100.00
4	REAR FENDER COWLING CLIPS SET <i>X SVC</i>	1	\$ 50.00	\$ 50.00
				\$ 480.00
Labour to:				
1	TO CHECK REAR ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	TO REMOVE AND RENEW REVERSE SENSOR	1	\$ 150.00	\$ 150.00
3	REMOVE AND RENEW REAR UNDERCARRIAGE	1	\$ 400.00	\$ 400.00
4	CONDUCT WHEEL ALIGNMENT	1	\$ 150.00	\$ 150.00
5	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
6	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00
7	PANEL BEATING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00
				\$ 2,180.00
<i>Repair dy - 2 dys.</i> <i>LIS</i> <i>After paint photo</i>			Parts Replacement Amount	\$ 5,097.76
			Total Amount for Labour	\$ 2,180.00
			Total Amount	\$ 7,277.76

Sun Pin (Hdw)
12/01/2020
TP Photo photo

810
130
660
1,600

1,600
-20%
1,280

LIS
\$1,300

2 dys