

# CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

04/01/2021

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

TP ALG.

Jasper.

Accident date: 01/01/2021

Estimated repair cost for vehicle no: SLX4578E HONDA CIVIC IMA 1.3L CVT 08'

CHASSIS: MRHFC5650JT001052 JHMFD36209J201699.

| S/n | Qty | Items                                                 | U/price  | Amount             |
|-----|-----|-------------------------------------------------------|----------|--------------------|
| 1   | 1   | Front Bonnet <i>Dented</i>                            |          | \$581.30 ✓         |
| 2   | 2   | Front Bonnet Hinge <i>Bent</i>                        | \$32.00  | \$64.00 ✓          |
| 3   | 1   | Front Bonnet Insulator                                |          | \$187.60 ✓         |
| 4   | 10  | Front Bonnet Insulator Clips <i>10</i>                | \$6.50   | \$65.00 ✓          |
| 5   | 1   | Front Bonnet Rubber <i>At</i>                         |          | \$48.10 ✓          |
| 6   | 1   | Front Bonnet Lock <i>Damaged</i>                      |          | \$84.50 ✓          |
| 7   | 1   | Front Grille <i>Cracked</i>                           |          | \$181.50 ✓         |
| 8   | 1   | Front Grille Top Cover <i>Dented</i>                  |          | \$23.00 ✓          |
| 9   | 1   | Front Grille Chrome <i>Cracked</i>                    |          | \$193.20 ✓         |
| 10  | 1   | Front Grille Emblem Logo <i>in</i>                    |          | \$27.40 ✓          |
| 11  | 6   | Front Grille Clip <i>in</i>                           | \$6.50   | \$39.00 20 ✓       |
| 12  | 1   | Front Grille Lower <i>New</i>                         |          | \$96.20 X ✓        |
| 13  | 1   | Front Number Plate <i>Cracked</i>                     |          | \$50.00 ✓          |
| 14  | 1   | Front Number Plate Garnish <i>Cracked</i>             |          | \$80.00 ✓          |
| 15  | 2   | Front Headlamp <i>Cracked</i>                         | \$639.80 | \$1,279.60 ✓       |
| 16  | 2   | Front Headlamp Lower Bracket <i>Bent</i>              | \$29.00  | \$58.00 ✓          |
| 17  | 1   | Front Bumper <i>Dented</i>                            |          | \$579.50 ✓         |
| 18  | 10  | Front Bumper Clip <i>in</i>                           | \$6.50   | \$65.00 30 ✓       |
| 19  | 2   | Front Bumper Side Retainer <i>in</i>                  | \$25.00  | \$50.00 ✓          |
| 20  | 1   | Front Bumper Lower Grille <i>Dented</i>               |          | \$96.20 ✓          |
| 21  | 2   | Front Bumper Fog Lamp Cover <i>New</i>                | \$38.20  | \$76.40 X ✓        |
| 22  | 1   | Front Bumper Reinforcement <i>Dishd</i>               |          | \$377.90 ✓         |
| 23  | 2   | Front Fender <i>LH Buckled</i>                        | \$568.00 | \$1,136.00 X 568 ✓ |
| 24  | 1   | Front Support Panel <i>Buckled</i>                    |          | \$574.50 ✓         |
| 25  | 1   | Front Air Con Condenser <i>Dishd</i>                  |          | \$704.40 ✓         |
| 26  | 1   | Front Air-Con Condenser Fan Motor Assy <i>Cracked</i> |          | \$464.00 ✓         |
| 27  | 1   | Front Air-Con Condenser Section Pipe <i>3 Bent</i>    |          | \$130.00 ✓         |
| 28  | 1   | Front Air-Con Condenser Discharge Pipe                |          | \$180.00 ✓         |
| 29  | 1   | Front Radiator <i>Bent</i>                            |          | \$1,100.50 ✓       |
| 30  | 1   | Front Radiator Fan Motor Assy <i>Cracked</i>          |          | \$438.10 ✓         |

798370

6386.96

Subtotal :- \$9,030.90

**Labour charges**

To remove & refit air-con condenser, radiator, fan motor & top up gas

\$120.00 ✓

To check wiring

~~\$100.00~~ 30

Towing fee

~~\$150.00~~ 60

Tuff kote

2750

~~\$150.00~~ 40

Towing

~~\$150.00~~ X

Panel beating

~~\$1,200.00~~ 900

Spray painting

~~\$1,200.00~~ 1000

Subtotal :- \$3,070.00

Total:- \$12,100.90

total: 8536.96

4/s: 6.8k.  
07 Day

6.8k. 07 Day

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: