

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

HP: 92712214

Acknowledged by Repairer

Signature:

Date:

25 KAKI BUKIT ROAD4
03-65/67/68 SYNERGY @KB
Singapore 417800

ERKZ PTE LTD

25 KAKI BUKIT ROAD4 #03-65/67/68 SYNERGY @ KB Singapore 417800
TEL: (65) 63844844 FAX: (65) 63834944

24th Nov 2020

TP ALG.

Xiao Tong.

Accident date: 19th Nov 2020

Estimated repair cost for vehicle no: SLH3075H Honda Vezel 1.5

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Dislud</i>		\$821.10	✓
2	2	Rear Boot Lid Hinges <i>new</i>	\$112.00	\$224.00	+
3	1	Rear boot lid emble logo <i>new</i>		\$55.00	+
4	1	Rear boot lid Vezel logo <i>new</i>		\$38.10	✓
5	2	Rear Boot Lid side reflector <i>Atto LH ut</i>	\$325.10	\$650.20	325.10
6	1	Rear boot lid inner rubber <i>at</i>		\$185.20	✓
7	1	Rear Boot Lid Inner Lock <i>Disc</i>		\$284.20	✓
8	1	Rear Boot Lid Number Plate		\$50.00	+
9	2	Rear Boot Lid Number Plate Lamp <i>for</i>	\$61.10	\$122.20	+
10	1	Rear Boot Lid center moulding		\$255.30	+
11	10	Rear Boot Lid Inner Trim board clips <i>new</i>	\$5.00	\$50.00	30
12	1	Rear Boot Lid Inner Trim board <i>Amel</i>		\$382.20	✓
13	2	Rear tail lamp <i>new</i>	\$388.20	\$776.40	+
14	1	Rear end panel <i>Repair</i>		\$420.00	+
15	1	Rear End Panel Top Garnish <i>Delud</i>		\$188.00	✓
16	1	Rear Bumper <i>Delud</i>		\$745.30	✓
17	2	Rear Bumper Side Bracket <i>new</i>	\$68.00	\$136.00	✓
18	1	Rear Bumper reverse sensor <i>Disc</i>		\$250.00	200 (SN)
19	2	Rear Bumper reverse camera <i>new</i>		\$0.00	+
20	2	Rear side Bumper <i>Repair</i>	\$225.00	\$450.00	+
21	8	Rear bumper clips <i>new</i>	\$5.00	\$40.00	+
23	1	Rear Exhaust aluminium cover <i>new</i>		\$95.00	✓
24	1	Rear windscreen moulding <i>new</i>		\$158.00	✓
25	1	Rear spare tire panel lower cover <i>new</i>		\$428.00	+
26	2	Rear spare tire panel lower pump <i>new</i>		\$580.00	+
27	1	Rear spare tire panel sealant		\$200.00	+

Subtotal :- \$7,584.20

Labour charges

To Remove & refix cushion

To Remove & refix rear windscreen

Gum

To Remove & refix reverse Sensor

Tuff kote

To Check Wiring System

Panel beating

Spray painting

3388.20
2710.56

S.N: 200

~~\$120.00~~ 60

\$120.00 ✓

\$50.00 ✓

~~\$120.00~~ 50

~~\$120.00~~ 40

~~\$60.00~~ 30

~~\$800.00~~ 600

~~\$800.00~~ 600

Subtotal :-

\$2,190.00

Total:-

\$9,774.20

Total: 4460.56

H/S: 3.5K

Admin Lg
H/S 05/01/21
04 Days