



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /SZE TAKLOON Reg No/Reg Date SMG8934L*KC17/ 03/01/201 Date In/Mileage 13/01/2021/ 0 Chassis No KNAF3416MK5018263 Engine No G4FGJH709098 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	11/01/2021/ 13:36	QUK	282 / Kevin Leong	27192
Description of Goods / Services					Qty Unit Price Disc% Amount

E PNT88000	REPLACE FRT RH DOOR PANEL & AFFECTED AREA	400	800.00		
E PNT98000	PAINT WORK ON FRT RH DOOR PANEL		120.00		
E PNT88000	TRANSFER FRT RH DOOR ATTACHMENT TO NEW PANEL		30.00		
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM		120.00		
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	20	50.00		
M SUNDRY	SUNDRIES	1.00	1277.00	20.00	1021.60
M PANEL ASSY-FRONT DOOR, RH		1.00	37.00	20.00	29.60
M MOULDING ASSY-FRT DR FRAME, RH		1.00	64.00	20.00	51.20
M W/STRIP ASSY-FR DR BELT O/S RH		1.00	102.00	20.00	81.60
M W/STRIP ASSY-FR DR SIDE RH		1.00	43.00	20.00	34.40
M W/STRIP-FR DR BELT I/S RH		1.00	13.00	20.00	10.40
M BLACK TAPE-FR DR RR, RH					

* Sound Proof Door Fmt RH
(Owner request)

Steve CLKK)
OD-NH AntL
Excess - ?
13/1/21, 4-40 pm
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Confirmed & accepted by
Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

Nett 2,698.80
188.92
7% GST on 2698.80
Total Payable 2,887.72

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.