

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/SZE TAKLOON
	Reg No/Reg Date	SMG8934L*KC17/ 03/01/201
	Date In/Mileage	13/01/2021/ 0
	Chassis No	KNAF3416MK5018263
	Engine No	G4FGJH709098
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	11/01/2021/ 13:36	QUK	282 / Kevin Leong	27192			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E	PNT88000	REPLACE FRT RH DOOR PANEL & AFFECTED AREA						800.00
E	PNT98000	PAINT WORK ON FRT RH DOOR PANEL						350.00
E	PNT88000	TRANSFER FRT RH DOOR ATTACHMENT TO NEW PANEL						120.00
A	54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM						30.00
A	10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST						120.00
M	SUNDRY	SUNDRIES						50.00
M	PANEL ASSY-FRONT DOOR,RH				1.00	1277.00	20.00	1021.60
M	MOULDING ASSY-FRT DR FRAME,RH				1.00	37.00	20.00	29.60
M	W/STRIP ASSY-FR DR BELT O/S RH				1.00	64.00	20.00	51.20
M	W/STRIP ASSY-FR DR SIDE RH				1.00	102.00	20.00	81.60
M	W/STRIP-FR DR BELT I/S RH				1.00	43.00	20.00	34.40
M	BLACK TAPE-FR DR RR,RH				1.00	13.00	20.00	10.40

Confirm & accepted by

	Nett	2,698.80
7% GST on	2698.80	188.92
Total Payable		2,887.72

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.