ASS. REC. BY: CS/ASM	1000499/KV	
Kenneth	SIGNMENT	
From: Date:	Veh No: CB 7559 n	Yr Regn: 04, 0,5
Estimated Cost:	Type: M.Car / M.Cycle / Busy Van / Lorry	Taxi / Prima Manual
OD TP WS I TP RES I OD RES I EVA I INV I MV	Truck / Traller or	riaxi/ Prime Mover/
To Inspect Vehicle No:	-(n)	20-
at Workshop m/s Yee Avt,		VC: Insured / Std / NI / NA
of	- / -	
Insured: SMT 4350D		/Radio: Insured / Std / NI / NA
Policy No.	Eng/No:	
Claims No. S1M03090	Gen. Cond: Good Fair / Poor / Burnt	257 070 235
Sum Insured; Excess:		
(Client's Record)	Steering: Inorder / Jammed / Leaked / Burn	
Make of Veh:	Brake: Ingreder / Jammed / Leaked / Burn	nt or
	Modi: MI S/RIm / STD A/RIm or	0
(Policy Condition)	Tyre Size: F:	95R15X8
Remark: The veh had commenced Its N/S O/S	R:	
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA IMIC	OHTSU / PIR / SUMI /
Ball or Market Value: \$30-35/c	TOYO/YOKO or	
IDAC Accident Rport: Consistent? : Yes or No		ear 0
GIA / PR Seen: Consistent?: Yes or No	A	Bal. mm
Est. Repairs: 12 days Res.: Yes or No		Bal. of mm
Lum Sum: 20 % 3 Val.: Yes or No	The conference of the conference who are the conference of the con	011 12/1/2021
70 70 70 70 70 70	Survey held at	
CA / REV / REP. / 24 HRS	Des. of Damages : Frt   Rear   O/S   N/S	U/C / Rooftop or
Date:Person Contacted: Vehicle: IN / OUT	& Pm	
Date / Time   Action / Instruction	The U/C / Chassis frame / Body Struct	ure affected due to collision.
		Control to the Second S
814 61 Ry 810,450 Certains	13/4/21 (Red 13, 796 L	ta, 5790)
	13,410	(e 37V)
		A ser reference and the residence of the service of the service service of the se
		W Miles W
		The second secon
		And a statement of the
		Name of the Control o
Date/Time, File Pass to? Prell. Report Da	rys Of Repair:	
1) : Final Report Re		ey Fee:
COLOR TENO, FIRE ROYOUTH TO Y	or and one of the company is selected.	orta6on:
and Fee:	011 1 12	RS. SI
	: Interview (\$ ), Forty	manufacture was proportion when
Report Format: SMART Claum	Tech Invs (\$ ) Others	the managering of the same
Lump Sum / I.B.I: (5 101 450 2	Weekend (\$ )	

S32121190005 / STA Inspection Pte Ltd[575627] ENTRY DATE & TIME: 09/01/2021 12:34 (SGT) SUBMITTED BY: Mohamad Farez Bin Jalil VERSION: 1 (09/01/2021 12:34 (SGT))

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

09/01/2021 12:34 (SGT) 08/01/2021 11:45 (SGT) Near 7000 Ang Mo Kio Ave 5, Singapore 569877 ALONG ANG MO KIO AVENUE 5 (BESIDE AMS GROUP) Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

CB7559M

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No **Email Address** 

HANG XIANG TRANSPORT SERVICES 5XXXX578D

mlts\_256@yahoo.com.sg (Phone) +65-96818651

Alternative Phone No

Mobile Phone No

(Office) +65-96818651

VEHICLE PARTICULARS

Manufacturer Model

Nissan

Urvan

Variant

Exact purpose for which vehicle was being used at time of

Employment

Are you claiming under your own insurance policy for repair to your vehicle?

No - Claiming third party Commercial vehicle

INSURANCE COMPANY

Vehicle Category

Name of Insurance Company

Liberty Insurance ThirdPartyFireTheft

Type of Coverage Fleet Policy

Policy Number

SI20V04945 /VBS /R02

Cover Note Number

DRIVER

Name of Driver

Occupation

NRIC No Date Of Birth CHUA JOO KOON VINCENT SXXXX216I 27/03/1964 Outdoor

05/03/1985 Date Of Driving Pass 35 YEARS AND 10 MONTHS Driving experience Gender (Phone) +65-97844961 Mobile Number Alt. Phone Number rcjk.rc@gmail.com Email Address APT BLK 321C ANCHORVALE DRIVE Address #12-32 SINGAPORE Address complement 543321 Postcode No Is the driver the policyholder? If No, Relationship of the Driver with the Insured **Employee** Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Chain Collision Type of Accident Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 3 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT PLEASE REFER TO ATTACHED ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number SMT4350D Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Private car Name of Driver Contact Number

Insurance Company Name


Address complement

Address

Nature Of Damage	-
Details of property damaged in accident	
No. Of Passenger (Including Driver)	

### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number Vehicle Manufacturer	GBC805E Hyundai
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	White
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



#### SKETCH PLAN

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Ai So

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: NRIC/FIN No.



160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com Registration No.: 201719251W GST No: 201719251W

AXA Insurance Pte Ltd M/S:

8 Shenton Way #24-01 AXA Tower Singapore 068811.

ATTN: Motor Claim Department

Not Im...

L/Sup & Date.

Policy No:
Veh Reg No:
Make/Model:
Chassis No:
Engine No:
Reg. Date:

ES2100004

11 Jan 2021

**CB7559M** 

NISSAN URVAN 3.0 M JN1TG4E25Z0702355

ZD30046762

20/04/2005

Claim Type: Accident Date:

Your Ref No:

Third Party 08/01/2021

TP Veh Reg No:

SMT4350D

Estimate Repair Cost to Vehicle No :CB7559M

	Description	U/Price	Quantity	List Price	Amount
	-			<u>S\$</u>	<u>S\$</u>
	Net Price			B	255N-
1	FRONT NUMBER PLATE	60.00	1 PC	60.00	
2	REAR NUMBER PLATE	60.00	1 PC	00.00	
3	REAR REVERSE SENSORS	300.00	1 PC	CM 300.00	2001N
				420.00	420.00
	Spare Parts			Biolin	
4	FRONT BUMPER	660.50	1 PC	Buz/em 660.50	
5	FRONT BUMPER BEAM	290.10	1 PC	290.10	7
6	FRONT BUMPER CLIPS	40.00	1 SET	Ne 40.00	
7	FRONT BUMPER SIDE RETAINER - LH	40.10	1 PC	In 40.10	X
8	FRONT BUMPER SIDE RETAINER - RH	40.10	1 PC	ام 40.10	X
9	HEAD LAMP - LH	450.45	1 PC	450.45	X
10	HEAD LAMP - RH	450.45	1 PC	450.45	X
11	FRONT GRILLE	365.10	1 PC	365.10	×
12	FRONT GRILLE LOGO	85.60	1 PC	£ 85.60	
13	FRONT BUMPER FOG LAMP COVER - RH	195.15	1 PC	na 195.15	
14	FRONT BUMPER FOG LAMP - RH	235.15	1 PC	235.15	
15	FRONT PANEL	896.15	1 PC	R 896.15	
16	FRONT PANEL STICKER	180.00	1 PC	Na 180.00	
17	REAR BODY INNER PANEL - RH	389.15	1 PC	389.15	
18	REAR BODY PANEL - RH	1,988.15	1 PC	1,988.15	
19	REAR BUMPER	850.15	1 PC	<b>B</b> 850.15	
20	REAR BUMPER BRACKET - LH	50.35	1 PC	<b>R</b> 50.35	
21	REAR BUMPER BRACKET - RH	50.35	1 PC	50.35	
22	REAR BUMPER CLIPS	40.00	1 SET	ne 40.00	
23	REAR BUMPER SIDE RETAINER - LH	40.35	1 PC	ens 40.35	
24	REAR BUMPER SIDE RETAINER - RH	40.35	1 PC	CM 40.35	
25	REAR DUST COVER - LH	48.50	1 PC	48.50	
26	REAR END INNER PANEL	300.05	1 PC	<b>B</b> <sub>1</sub> 300.05	
27	REAR END PANEL	350.85	1 PC	<b>13</b> 350.85	
28	REAR FLOOR BOARD INSULATOR	180.05	1 PC	180.05	
29	REAR FLOOR BOARD PANEL	1,240.05	1 PC	1,240.05	
30	EXHAUST MOUNTING	70.10	1 PC	Pm 70.10	
31	REAR EXHAUST MUFFLER	584.35	1 PC	584.35	
32	REAR NUMBER PLATE LAMP - LH	60.10	1 PC	5n 60.10	
33	REAR NUMBER PLATE LAMP - RH	60.10	1 PC	00.10	
34	REAR WINDSCREEN MOULDINGS	108.50	1 PC	108.50	
35	REAR WIPER ARM	73.10	1 PC	<i>S</i> 73.10	X



160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722 Tel: 6457 5768 Fax: 62.52 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S: AXA Insurance Pte Ltd

8 Shenton Way #24-01 AXA Tower

Singapore 068811.

ATTN: Motor Claim Department

Your Ref No:

Claim Type:

Third Party 08/01/2021

Accident Date: TP Veh Reg No:

SMT4350D

**Estimate No:** 

ES2100004

Date:

11 Jan 2021

Policy No:

Veh Reg No:

CB7559M

Make/Model:

NISSAN URVAN 3.0 M

Chassis No:

JN1TG4E25Z0702355

Engine No:

ZD30046762

Reg. Date:

20/04/2005

Estimate Repair Cost to Vehicle No :CB7559M

	Description		Quantity	List Price	
	•			S\$ 33 10	
36	REAR WIPER BLADE	33.10	1 PC	33.10	
37	REAR WIPER MOTOR	385.10	1 PC	363.10	
38	SPARE WHEEL CARRIER	220.05	1 PC	220.05	
39	SPARE WHEEL HOLDER	80.10	1 PC	80.10	
40	SPEED LIMIT STICKER '60KM'	20.00	1 PC	0	125a
41	REAR TAILGATE	1,360.35	1 PC	1,360.35	•
42	REAR TAILGATE SHOCK ABSORBER - LH	240.10	1 PC	240.10	
43	REAR TAILGATE SHOCK ABSORBER - RH	240.10	1 PC	240.10	-
44	REAR TAILGATE INNER HOLDER	80.00	1 PC	80.00	
45	REAR TAILGATE INNER TRIM BOARD	355.05	1 PC	355.05	
46	REAR TAILGATE LOWER LOCK	30.05	1 PC	30.05	?
47	REAR TAILGATE OUTER HANDLE	92.00	1 PC	92.00	
48	REAR TAILGATE STICKER 'PULL OPEN'	20.00	1 PC	ne no 20.00	
49	REAR TAILGATE STICKER 'AWC'	20.00	1 PC		125a
50	REAR TAILGATE STICKER 'EMERGENCY DOOR'	20.00	1 PC	Mec 20.00	
51	REAR TAILGATE TOP LOCK	250.05	1 PC	7n 250.05	
52	REAR TAILGATE WEATHERSTRIP	180.75	1 PC	180.75	7
53	TAIL LAMP LH	642.00	1 PC	642.00	
54	TAIL LAMP RH	642.00	1 PC	642.00	
55	REAR TAIL GATE STICKER (BODY)	350.00	1 PC	Nec 350.00	1205A-
56	REAR STEP GARNISH	285.15	1 PC	285.15	7
57	REAR STEP PANEL	420.15	1 PC	420.15	7
58	REAR STEP GARNISH CLIP	72.00	1 SET	72.00	?
59	REAR TAILGATE GARNISH - CENTRE	318.15	1 PC	318.15	
60	SIDE BODY PANEL STICKER - RH	650.00	1 PC	Me 650.00	250sa
	101			17,459.70	17,459.70
	Labour				
61	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	2,400.00	1 JOB	2,400.00	16000
62	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	2,200.00	1 JOB	2,200.00	16001 14001 901
63	TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	220.00	1 JOB	220.00	901
64	TO REMOVE/REFIX REAR WINDSCREEN TO FACILITATE REPAIRS.	200.00	1 JOB	200.00	,
65	TO REMOVE/TRANSFER TAILGATE COMPONENTS.	180.00	1 JOB	180.00	601
66	TO REMOVE/RENEW EXHAUST MUFFLER.	80.00	1 JOB	80.00	-
67	TOWING FEE	120.00	1 JOB	120.00	
13 /	TOWINGTEE				201



160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031 Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S: AXA Insurance Pte Ltd

> 8 Shenton Way #24-01 AXA Tower

Singapore 068811.

ATTN: Motor Claim Department

Your Ref No:

Claim Type:

Third Party

Accident Date: TP Veh Reg No: 08/01/2021

SMT4350D

**Estimate No:** 

ES2100004

Date:

11 Jan 2021

Policy No:

Veh Reg No:

**CB7559M** 

Make/Model:

NISSAN URVAN 3.0 M

Chassis No:

JN1TG4E25Z0702355

Engine No:

ZD30046762

Reg. Date:

20/04/2005

#### Estimate Repair Cost to Vehicle No :CB7559M

Description	U/Price	Quantity	List Price	Amount
1		•	S\$	S\$
			5,450.00	5,450.00
			Total	S\$ 23,329.70
		Add GS	ST @ 7%	1,633.08
		Total Amoun	t Payable	S\$ 24,962.78

TOTAL: SINGAPORE DOLLAR TWENTY FOUR THOUSAND NINE HUNDRED SIXTY TWO AND CENTS SEVENTY EIGHT ONLY

For Yee Auto Pte Ltd

AUTHOR SED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## AUTO PTE LT

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031 Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S:

AXA Insurance Pte Ltd

8 Shenton Way

#24-01 AXA Tower

Singapore 068811.

ATTN: Motor Claim Department

Your Ref No:

Claim Type:

Third Party

Accident Date: TP Veh Reg No:

08/01/2021 SMT4350D

Not Nother Estimate No: Besury Afte Paint Veh Reg No:
Make/Model:
12 day, Chassis No:

ES2100004 11 Jan 2021

**CB7559M** 

NISSAN URVAN 3.0 M JN1TG4E25Z0702355

Engine No:

ZD30046762

Reg. Date:

20/04/2005

Estimate Repair Cost to Vehicle No : CB7559M

	Description	U/Price	Quantity	List Price	Amount
				<u>S\$</u>	SS
	Net Price			B	255N-
1	FRONT NUMBER PLATE	60.00	1 PC	60.00	
2	REAR NUMBER PLATE	60.00	1 PC	Net 60.00	25 sa
3	REAR REVERSE SENSORS	300.00	1 PC	<b>CM</b> 300.00 420.00	2005N-420.00
	Spare Parts			Buz/ent 660.50	
4	FRONT BUMPER 621.00	660.50	110	10	
5	FRONT BUMPER BEAM	290.10	1 PC	290.10	7
6	FRONT BUMPER CLIPS	40.00	1 SET	Mc 40.00	
7	FRONT BUMPER SIDE RETAINER - LH	40.10	1 PC	1n 40.10	0.00
8	FRONT BUMPER SIDE RETAINER - RH	40.10	1 PC	40.10	
9	HEAD LAMP - LH	450.45	1 PC	450.45	
10	HEAD LAMP - RH	450.45	1 PC	450.45	
11	FRONT GRILLE	365.10	1 PC	365.10	
12	FRONT GRILLE LOGO	85.60	1 PC	<b>&amp;</b> 85.60	X
13	FRONT BUMPER FOG LAMP COVER - RH	195.15	1 PC	no 195.15	
14	FRONT BUMPER FOG LAMP - RH	235.15	1 PC	235.15	
15	FRONT PANEL	896.15	1 PC	R 896.15	
16	FRONT PANEL STICKER	180.00	1 PC	180.00	
17	REAR BODY INNER PANEL - RH	389.15	1 PC	<b>M</b> 389.15	
18	REAR BODY PANEL - RH	1,988.15	1 PC	1,988.15	
19	REAR BUMPER 632.70	850.15	1 PC	<b>B</b> 850.15	
20	REAR BUMPER BRACKET - LH	50.35	1 PC	<b>R</b> 50.35	
21	REAR BUMPER BRACKET - RH	50.35	1 PC	<b>B</b> 50.35	
22	REAR BUMPER CLIPS	40.00	1 SET	na 40.00	
23	REAR BUMPER SIDE RETAINER - LH	40.35	1 PC	cns 40.35	_
24	REAR BUMPER SIDE RETAINER - RH	40.35	1 PC	CM 40.35	
25	REAR DUST COVER - LH	48.50	1 PC	Sa 48.50	
26	REAR END INNER PANEL 194.80	300.05	1 PC	By 300.05	
27	REAR END PANEL	350.85	1 PC	Ry 350.85	A.*
28	REAR FLOOR BOARD INSULATOR	180.05	1 PC	Sm 180.05	
29	REAR FLOOR BOARD PANEL	1,240.05	1 PC	1,240.05	X
30	EXHAUST MOUNTING	70.10	1 PC	<i>f</i> 70.10	
31	REAR EXHAUST MUFFLER	584.35		<b>3</b> 584.35	
32	REAR NUMBER PLATE LAMP - LH	60.10	1 PC	60.10	
33	REAR NUMBER PLATE LAMP - RH	60.10	1 PC	Sa 60.10	
34	REAR WINDSCREEN MOULDINGS	108.50	1 PC	Ma 108.50	
35	REAR WIPER ARM	73.10	1 PC	Sm 73.10	X



160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S: AXA Insurance Pte Ltd

> 8 Shenton Way Date: #24-01 AXA Tower

Singapore 068811.

ATTN: Motor Claim Department

Your Ref No:

Claim Type: Third Party

TP Veh Reg No: SMT4350D

08/01/2021 Accident Date:

**Estimate No:** 

ES2100004

11 Jan 2021

Policy No:

Veh Reg No:

**CB7559M** 

Make/Model:

NISSAN URVAN 3.0 M

Chassis No: Engine No:

JN1TG4E25Z0702355 ZD30046762

Reg. Date:

20/04/2005

#### Estimate Repair Cost to Vehicle No: CB7559M

	Description	U/Price	Quantity	List Price		Amount
				Pag.	<u>S\$</u>	<u>S\$</u>
36	REAR WIPER BLADE	33.10	1 PC	In	33.10	
37	REAR WIPER MOTOR  SPARE WHEEL CARRIER 185-20  Misla	385.10	1 PC	A	385.10	-1
38	SPARE WHEEL CARRIER 103-20 min	220.05	1 PC	n	220.05	7
39	SPARE WHEEL HOLDER	80.10	1 PC	M	80.10	
40	SPEED LIMIT STICKER '60KM'	20.00	1 PC	1		125a
41	REAR TAILGATE	1,360.35	1 PC		1,360.35	_
42	REAR TAILGATE SHOCK ABSORBER - LH	240.10	1 PC	m	240.10	
43	REAR TAILGATE SHOCK ABSORBER - RH	240.10	1 PC	R	240.10	
44	REAR TAILGATE INNER HOLDER	80.00	1 PC		80.00	*
45	REAR TAILGATE INNER TRIM BOARD 286.90	355.05	1 PC	cm	355.05	2
46	REAR TAILGATE LOWER LOCK	30.05	1 PC	nd van se	30.05	
47	REAR TAILGATE OUTER HANDLE	92.00	IPC	4	92.00	122
48	REAR TAILGATE STICKER 'PULL OPEN'	20.00	IPC		20.00	2012
49	REAR TAILGATE STICKER 'AWC'	20.00	1 PC	ME		125a
50	REAR TAILGATE STICKER 'EMERGENCY DOOR'	20.00	1 PC	7	20.00	125a
51	REAR TAILGATE TOP LOCK  90.37	250.05	1 PC	67	250.05	
52	REAR TAILGATE WEATHERSTRIP	180.75	1 PC	mgcm	180.75	750Wn-
53	TAIL LAMP LH 252.30	642.00	1 PC	4	642.00	?
54	TAIL LAMP RH 252.30	642.00	1 PC	Nec	642.00	120sm
55	REAR TAIL GATE STICKER (BODY)	350.00	1 PC		350.00	12051
56	REAR STEP GARNISH	285.15	1 PC	017	200110	7
57	REAR STEP PANEL	420.15	1 PC	By	420.15	7
58	REAR STEP GARNISH CLIP	72.00	1 SET	Ma	72.00	1
59	REAR TAILGATE GARNISH - CENTRE	318.15	1 PC	RI	318.15	250sa
60	SIDE BODY PANEL STICKER - RH	650.00	1 PC	m	650.00	
	108			1	7,459.70	17,459.70
	Labour					
61	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	2,400.00	1 JOB		2,400.00	16001 14001
62	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	2,200.00	1 JOB		2,200.00	14001
63	TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	220.00	1 JOB		220.00	701
64	TO REMOVE/REFIX REAR WINDSCREEN TO FACILITATE REPAIRS.	200.00	1 JOB		200.00	
65	TO REMOVE/TRANSFER TAILGATE COMPONENTS.	180.00	1 JOB		180.00	
66	TO REMOVE/RENEW EXHAUST MUFFLER.	80.00	1 JOB		80.00	
67	TOWING FEE	120.00	1 JOB		120.00	
68	TO CHECK WIRING FUNCTIONS.	50.00	1 JOB		50.00	201



160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S: AXA Insurance Pte Ltd

8 Shenton Way

#24-01 AXA Tower

Singapore 068811.

ATTN: Motor Claim Department

Your Ref No:

Claim Type:

Third Party

Accident Date:

08/01/2021

TP Veh Reg No:

SMT4350D

Estimate Repair Cost to Vehicle No : CB7559M

**Estimate No:** 

ES2100004

Date:

11 Jan 2021

Policy No:

Veh Reg No:

CB7559M

Make/Model:

NISSAN URVAN 3.0 M

Chassis No:

JN1TG4E25Z0702355

Engine No:

ZD30046762

Reg. Date:

20/04/2005

Amount	List Price	Quantity	U/Price	Description
S\$	<u>S\$</u>			
5,450.00	5,450.00			
S\$ 23,329.70	Total	2111 42	24,	
1,633.08	ST @ 7%	Add GS		
S\$ 24,962.78	nt Payable	Total Amount		

TOTAL: SINGAPORE DOLLAR TWENTY FOUR THOUSAND NINE HUNDRED SIXTY TWO AND CENTS SEVENTY EIGHT ONLY

For Yee Auto Pte Ltd

SIGNATURE



160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity: Singapore 575722 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S: AXA Insurance Pte Ltd

8 Shenton Way

#24-01 AXA Tower

Singapore 068811.

ATTN: Motor Claim Department

Your Ref No:

Claim Type:

Third Party

Accident Date:

08/01/2021

TP Veh Reg No:

SMT4350D

**Estimate No:** 

ES2100004

Date:

12 Jan 2021

Policy No:

**CB7559M** 

Veh Reg No: Make/Model:

NISSAN URVAN 3.0 M

Chassis No:

JN1TG4E25Z0702355

Engine No:

ZD30046762

Reg. Date:

20/04/2005

### Estimate Repair Cost to Vehicle No : CB7559M

	Description		U/Price	Quantity	Lis	st Price	A	mount
	•					<u>S\$</u>		<u>S\$</u>
			Supplementary Parts to Repa	ir				
	Spare Parts				0 1/0		,	
1	REAR BODY PANEL INNER TRIM	M - RH	485.15	1 SET		485.15		
2	FRONT SIDE LAMP - LH		195.15	1 PC	5cm	195.15	X	
3	REAR TAILGATE INNER LOCK O	COVER	90.85	1 PC	Oct	90.85	-	
4	REAR CARPET BEAM		85.60	1 PC	Dit	85.60		
						856.75		856.75
					Tota	1	S\$	856.75
				GS	T Amoun	t	S	\$ 59.97
				Total Amour	nt Payable	2	S\$	916.72

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE