



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD Nissan (CB7559M)
Date of Loss	8 January 2021
Time of Loss	12.00
Loss Description	SMT4350D (INSD) > CB7559M >V
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="0"/>
Nett Loss Amount	\$0.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details



Vehicle Registration#	CB7559M	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>20/04/2005</div> <div></div>
Mileage	<div>400095</div>	Age of Vehicle	15

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2005</div>
Make	TPVD	<div>NISSAN</div>
		<div></div>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	CHUA JOO KOON VINCENT	<div></div>
Date of Birth		<div>dd/mm/yyyy</div> <div></div>

Model CATEGORY	Nissan POLICY INFORMATION	URVAN 3.0 M ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="JN1TG4E25Z0702355"/>
Engine No		<input type="text" value="ZD30046762"/>
Engine Capacity		<input type="text" value="2953"/>
Sum Insured		<input type="text" value="0"/>
Market Value		<input type="text" value="0"/>

CATEGORY Age	FNOL INFORMATION 0	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Unknown	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	TBC	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

12/01/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver
Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="10"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts












Add











Approve











Deny










Submit All









	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		FRONT BUMPER	Buckled	0	621	No		10			558.9	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER BEAM	Bent	0	290.1	No		10			261.09	Reviewing
<input type="checkbox"/>		0	1		SET FRONT BUMPER CLIPS	Necessary	0	40	No		10			36	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER SIDE RETAINER - LH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT BUMPER SIDE RETAINER - RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		HEAD LAMP - LH	Serviceable	0	0	No		10			0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		HEAD LAMP - RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT GRILLE	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT GRILLE LOGO	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT BUMPER FOG LAMP COVER - RH	Dented	0	195.15	No		10			175.64	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER FOG LAMP - RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT PANEL	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT PANEL STICKER	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR BODY INNER PANEL - RH	Bent	0	389.15	No		10			350.24	Reviewing
<input type="checkbox"/>		0	1		REAR BODY PANEL - RH	Bent	0	1793.4	No		10			1614.06	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER	Bent	0	632.7	No		10			569.43	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER BRACKET - LH	Bent	0	50.35	No		10			45.32	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR BUMPER BRACKET - RH	Bent	0	50.35	No		10			45.32	Reviewing
<input type="checkbox"/>		0	1		SET REAR BUMPER CLIPS	Necessary	0	40	No		10			36	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER SIDE RETAINER - LH	Cracked	0	40.35	No		10			36.32	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER SIDE RETAINER - RH	Cracked	0	40.35	No		10			36.32	Reviewing
<input type="checkbox"/>		0	1		REAR DUST COVER - LH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR END INNER PANEL	Bent	0	194.8	No		10			175.32	Reviewing
<input type="checkbox"/>		0	1		REAR END PANEL	Bent	0	350.85	No		10			315.77	Reviewing
<input type="checkbox"/>		0	1		REAR FLOOR BOARD INSULATOR	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR FLOOR BOARD PANEL	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		EXHAUST MOUNTING	Serviceable	0	0	No		10			0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR EXHAUST MUFFLER	Bent	0	584.35	No		10			525.92	Reviewing
<input type="checkbox"/>		0	1		REAR NUMBER PLATE LAMP - LH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR NUMBER PLATE LAMP - RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR WINDSCREEN MOULDINGS	Necessary	0	108.5	No		10			97.65	Reviewing
<input type="checkbox"/>		0	1		REAR WIPER ARM	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR WIPER BLADE	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR WIPER MOTOR	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		SPARE WHEEL CARRIER	Bent	0	185.2	No		10			166.68	Reviewing
<input type="checkbox"/>		0	1		SPARE WHEEL HOLDER	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR TAILGATE	Bent	0	1360.35	No		10			1224.32	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR TAILGATE SHOCK ABSORBER - LH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR TAILGATE SHOCK ABSORBER - RH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR TAILGATE INNER HOLDER	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR TAILGATE INNER TRIM BOARD	Cracked	0	280.9	No		10			252.81	Reviewing
<input type="checkbox"/>		0	1		REAR TAILGATE LOWER LOCK	Dented	0	30.05	No		10			27.05	Reviewing
<input type="checkbox"/>		0	1		REAR TAILGATE OUTER HANDLE	Damaged	0	92	No		10			82.8	Reviewing
<input type="checkbox"/>		0	1		REAR TAILGATE TOP LOCK	Damaged	0	250.05	No		10			225.05	Reviewing
<input type="checkbox"/>		0	1		TAIL LAMP LH	Cracked	0	252.3	No		10			227.07	Reviewing
<input type="checkbox"/>		0	1		TAIL LAMP RH	Cracked	0	252.3	No		10			227.07	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR STEP GARNISH	Damaged	0	285.15	No		10			256.64	Reviewing
<input type="checkbox"/>		0	1		REAR STEP PANEL	Bent	0	420.15	No		10			378.14	Reviewing
<input type="checkbox"/>		0	1		SET REAR STEP GARNISH CLIP	Necessary	0	72	No		10			64.8	Reviewing
<input type="checkbox"/>		0	1		REAR TAILGATE GARNISH - CENTRE	Dented	0	318.15	No		10			286.34	Reviewing
<input type="checkbox"/>		0	1		SET REAR BODY PANEL INNER TRIM - RH	Dented	0	485.15	No		10			436.64	Reviewing
<input type="checkbox"/>		0	1		FRONT SIDE LAMP - LH	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR TAILGATE INNER LOCK COVER	Dented	0	90.85	No		10			81.77	Reviewing
<input type="checkbox"/>		0	1		REAR CARPET BEAM	Damaged	0	85.6	No		10			77.04	Reviewing

Labour









Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
------	-------	-------------------------	-----------	------------------------	------------------------	-----------------------	-----------------------	-----------------	---------

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY	0	1600	0	0	Reviewing	
<input type="checkbox"/>		0		TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	0	1400	0	0	Reviewing	
<input type="checkbox"/>		0		TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL	0	90	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE / REFIX REAR WINDSCREEN TO FACILITATE REPAIRS	0	120	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE / TRANSFER TAILGATE COMPONENTS	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE / RENEW EXHAUST MUFFLER	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		TOWING FEE	0	50	0	0	Reviewing	
<input type="checkbox"/>		0		TO CHECK WIRING FUNCTION	0	20	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary













Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 12 DAYS	Reviewing		0		
<input type="checkbox"/>		0	FRONT NUMBER PLATE	Reviewing		25	BENT	
<input type="checkbox"/>		0	REAR NUMBER PLATE	Reviewing		25	DENTED	
<input type="checkbox"/>		0	REAR REVERSE SENSORS	Reviewing		200	CRACKED	

<input type="checkbox"/>	EDIT 	SR NO	NAME LIMIT STICKER '60KM'	ACTION Reviewing	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT NECESSARY	REMOVE 
<input type="checkbox"/>		0	REAR TAILGATE STICKER 'PULL OPEN'	Reviewing		12	NECESSARY	
<input type="checkbox"/>		0	REAR TAILGATE STICKER 'AWC'	Reviewing		12	NECESSARY	
<input type="checkbox"/>		0	REAR TAILGATE STICKER 'EMERGENCY DOOR'	Reviewing		12	NECESSARY	
<input type="checkbox"/>		0	REAR TAILGATE WEATHERSTRIP (@\$180.75) (50%)	Reviewing		90.37	CUT	
<input type="checkbox"/>		0	REAR TAILGATE STICKER (BODY)	Reviewing		120	NECESSARY	

SIDE BODY

		SERIAL NO	SIDE BODY NAME	BODY STICKER	REVISION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	NECESSARY COMMENT	DELETE
				- RH			250		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00		Adjusted Claim Amount		\$13,051.89	
CATEGORY		ESTIMATE		ADJUSTED			
Spare Parts		\$0.00		\$8,893.52			
Labour		\$0.00		\$3,400.00			
Miscellaneous		\$0.00		\$758.37			

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	FINAL LUMP SUM	Reviewing	10450		



Submit for Review