ASS. REC. BY:	21000.506/kg
MP MARTL	
From:	SSIGNMENT
Estimated Cost:	Veh No: 4814 5296/4/Yr Regn: 06, 18
OD IN WS I TP RES I OD RES I EVA I INV I MY	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
To Inspect Vehicle No:	Truck / Trailer or
at Workshop m/s	Make: Me Vito 11400, c.c 2143
of	Colour Red AC: Insured / Std / NI / NA
Insured:	Sp.Reading 93437 T/Radio: Insured / Std / NI / NA Eng/No:
Policy No. 99993880	
Claims No. 6168884530SG	C/No: WDF 44760323352154 Gen. Cond: Good Fair Poor Burnt
Sum Insured: Excess: 1400	Steering: Inorder Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: NII / S/RIm / STDA/RIM or
	Tyre Size: F: 215/60R16
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYOTYOKO or Achilles
Bal. or Market Value: 8 83/6	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. F mm R/Bal. 6 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal.
Est. Repairs: 2 days Res.: Yes or No	O.O.A. 17/12/20 D.O.I. 12/1/202
Lum Sum: 1.B.1% 3 Val.: Yes or No	Survey held at
CA I REV I REP. I 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date:Person Contacted: Vehicle: IN / OUT	MS body
- Joseff Contactod	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
13/01/21@11.45am revert to AIG via Merimen.	
14/01/21@12.52pm Kok Chong informed C/A via N	ferimen.
15/01/21@8.59am Informed Candy C/A & ex:\$1400	
Kenneth confirmed final fig \$2036.80 (Re	d ¢1507 '420/'\
Kerineth commined in an hig \$2030.00 (Re	34 \$1307, 4376)
Contraction of the second of t	and the application of the second of the sec
Date/Time, File Pass to? : Prell. Report D	ave Of Paral
n — — —	ays Of Repair: 2
Cuto/Fine, File Return to?	Survey No. of Trip: Survey Fee:
	Transportativi
Add Fee:	: Site Insp (\$)_s-Rssi
	Intendeur /s
Report Format: MER-OD	
	Tech Invs (\$

ASS. REC. BY:	21000.506/kg
Kenneth	ASSIGNMENT
From:	
Estimated Cost:	Veh No: 4811 5296 Myr Regn: 06, 18
OD I WS / TP RES / OD RES / EVA / INV / MY	Type: M.Car / M.Cycle / Bus / Van / Lony / Taxl / Prime Mover /
To Inspect Vehicle No:	Truck / Trailer or
	Make: Me Vito 11400:00 2143
of Tong Luci	- Contract of the American Contract NA
Insured:	Sp.Reading 53437 T/Radio: Insured / Std / N1 / NA
Policy No.	Eng/No: U/D/= 447/1.2222=================================
Claims No.	C/No: WDF 44760:323352154 Gen. Cond: 9600/Fair/Poor/Burnt
Sum Insured: Excess:	Steering: Inorder Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nill / S/Rim / STD A/Rim or
Enter ale Process	Tyre Size: F: 215160R16
(Policy Condition)	R:
Remark: The veh had commenced its repair at the time of inspection.	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
- 0	TOYOTYOKO or Achilles
Bal. or Market Value: 8 83/c	Fron! Rear
IDAC Accident Rport: Consistent? : Yes or No GIA / PR Seen: Consistent? : Yes or No	R/Bal mm R/Bal mm
GIA / PR Seen: Consistent?: Yes or No Est. Repairs: days Res.: Yes or No	L/Bal. 4 mm L/Bal. 6 mm
Lum Sum: 1.B./% 3 Val.: Yes or No	O.O.A. 17/12/20 D.O.I. 12/1/2021
CA I REY I REP. 1 24 HRS	Survey held at
Vehicle: IN	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date:Person Contacted:	1 1000
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
	7 17
	The state of the s
	* 187
Data/Tima, File Pass to?	The Difference of the Control of the
Freil. Report	Days Of Repair:
; Final Report	Postura M. Andrews
Cute/Time, File Return to?	
7) Add F	ee: Site Insp (\$
•]_S+RSSI
Report Format:	: Interview (\$), Fire 35
Lump Sum / I.B.I: (S	Tech Invs (\$) Others



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

NO

PAGE: 1

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

ATTN: MOTOR CLAIM DEPT

SINGAPORE 079120

Pering B4 paing

FAX: 6415 3723 2days

ESTIMATE

: QUOT202101-000012(00)

DATE : 12/01/2021 : 999995580 **POLICY NO** VEH REG NO : GBH5296P

MÁKE/MODEL : MERCEDES BENZ VITO 114 CDI PANEL VAN LONG AT ABS 5DR

: WDF44760323352154 **CHASSIS NO**

: 65195034276730 **ENGINE NO**

: 2018 REG. DATE

YOUR REF NO

TEL: 6419 3000

: OWN DAMAGE **CLAIM TYPE** ACCIDENT DATE : 17/12/2020

Estimate Repair Cost to Vehicle No: GBH5296P

Description		Quantity		Unit Price		Amount	
2000.				<u>s\$</u>		<u>s\$</u>	
PARTS		NEW YORK		4 000 00	R.	200 00	
	Attack Washington	a X 1		30AX 236423			
		1			MESTA .		
Sliding door outer handle (short) - LH		1			1101		
Sliding door inner trimboard - LH		1		115.00		115.00	
Sliding door inner trimboard clips - LH		10		5.50		55.00	
		to the second		Add 10%		100	
					(税)	1,713.80)
ABOUR					100		
transfer LH damaged sliding door inteterior n	nechanism to new	1		150.00			
check and rectify wiring system		1		80.00	Kulais	80.0	C
nel, including replacement of parts and align v		1		800.00		6	•
		16		WaterWestern Council.		2	
putty and spray paint on affected		1	. "	800.00		800.0)(
						1,830.0)
		d)		TOTAL	S	3,543.8	3
	The state of the s		ADD (SST @ 7%		248.	C
			GRA	ND TOTAL	S	3.791.	8
	Sliding door - LH Sliding door outer handle (long) - LH Sliding door outer handle (short) - LH Sliding door inner trimboard - LH Sliding door inner trimboard clips - LH Sliding door inner trimboard clips - LH Stransfer LH damaged sliding door inteterior nor check and rectify wiring system panel beat and straighten LH rear fender, LH	PARTS Sliding door - LH Sliding door outer handle (long) - LH Sliding door outer handle (short) - LH Sliding door inner trimboard - LH Sliding door inner trimboard clips - LH Sliding door inner trimboard - LH	PARTS Silding door - LH Silding door outer handle (long) - LH Silding door outer handle (short) - LH Silding door inner trimboard - LH Silding door inner trimboard - LH Silding door inner trimboard clips - LH 10 ABOUR Transfer LH damaged sliding door inteterior mechanism to new or check and rectify wiring system 1 panel beat and straighten LH rear fender, LH running board nel, including replacement of parts and align where necessary, refit and adjust the same	PARTS Siding door - LH Siding door outer handle (long) - LH Siding door outer handle (short) - LH Siding door inner trimboard - LH Siding door inner trimboard - LH Siding door inner trimboard clips - LH Siding door inner trimboard - LH Siding	PARTS Silding door - LH Silding door outer handle (long) - LH Silding door outer handle (short) - LH Silding door inner trimboard - LH Silding door inner trimboard - LH Silding door inner trimboard clips - LH Silding door inner trimboard - LH	PARTS Siding door - LH Siding door outer handle (long) - LH Siding door outer handle (short) - LH Siding door outer handle (short) - LH Siding door inner trimboard - LH Siding door outer handle (long) -	PARTS Sididing door - LH 1 1,280.00 1,280.00 1,280.00 1,280.00 1,280.00 1,280.00 1,280.00 1,280.00 1,280.00 1,280.00 1,558.00 1,558.00 1,558.00 1,713.80 1,

SINGAPORE DOLLAR THREE THOUSAND SEVEN HUNDRED NINETY-ONE AND CENTS EIGHTY-SEVEN ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
 This Form must be <u>completed</u> by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies,

 5. Any false reporting may be referred to the Police for Investigation.

 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission **Date of Accident Exact Location of Accident** Additional Location Information Country/State of Loss

05/01/2021 19:45 (SGT) 17/12/2020 16:30 (SGT) Singapore 10. EUNOS ROAD 8, CARPARK Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

GBH5296P

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No **Email Address** Mobile Phone No. Alternative Phone No.

Yes DAIMLER FLEET MANAGEMENT SINGAPORE PTE, LTD. 1XXXXX778Z faizal.mohamed@daimler.com (Phone) +65-68498118 (Office) +65-68498118

VEHICLE PARTICULARS

Manufacturer Model Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category

Employment

Mercedes

Vito

Commercial vehicle

INSURANCE COMPANY

Name of Insurance Company Type of Coverage Fleet Policy Policy Number Cover Note Number

AIG

Comprehensive

Yes

999995580

DRIVER

Name of Driver NRIC No Date Of Birth Occupation

DEIDRI ESABEL SIM CHUAN SXXXX154Z 09/01/1994 Indoor

Accident report SA0A2115000B

Page 1 of 17

03/04/2017 **Date Of Driving Pass** 3 YEARS AND 8 MONTHS Driving experience Female Gender (Phone) +65-83800838 Mobile Number Alt. Phone Number faizal.mohamed@daimler.com Email Address HDB Pasir Ris, 145 Pasir Ris Street 11 Address Address complement #04-79 510145 Postcode Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collided into Property Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 Name PASSENGER 1 Gender Female DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON THE DATE AND TIME MENTIONED I WAS DRIVING ALONG THE SAID MENTIONED CARPARK, WHEN THE LEFT SIDE OF MY VEHICLE ACCIDENTALLY GRAZED AGAINST ONE OF THE WALL PILLAR THERE. NO ONE WAS INJURED, STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No Was there any audio recorded? **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number

Vehicle Manufacturer

14-32-C6Z5

-					
DE	a	AR	A	TIC	N

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time: Oriver's Signature (If driver is not the policyholder) VERIFY BY AIAX MARS (ARC)
REPORTING OFFICER
HASHIM BIN KAMARI

Reporting Centre Personnel's Signature