

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0023/2021/NS
DATE : 11-Jan-21
WIP : 65456

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian

We took 13 days exclude 2 Sundays

Parts - Germany jb 17 Mar 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR SOH BOON KEONG(SU WENQIANG)
ADDRESS : 7 SOON LEE STREET
#02-40
SINGAPORE 627608
TELEPHONE : HP +65 91442625
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070006564
VEHICLE NO : **SKF 5525 H**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 17/1/2020
ENGINE NO : CVK 087755
CHASSIS NO : WAUZZZF48KA117072
MILEAGE : 25670KM
DATE IN : 5-Jan-21
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Jan-21
PLACE OF ACCIDENT : 5 LORONG BAKAR BATU CARPARK

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKF 5525 H

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND RENEW BONNET. REPAIR LHS A-PILLAR.	\$ 1,400.00	\$ 750.00
2	TO DISMANTLE BOTH FRONT DOOR PANEL TRIMS, REMOVE AND REINSTALL BOTH WING MIRROR ASSY. RENEW DAMAGED TRIMS AND WINDOW GLASSES.	S/N \$ 800.00	\$ 280.00
3	TO RESPRAY BONNET, LHS A-PILLAR AND BOTH FRONT DOORS.	\$ 3,200.00	\$ 1,650.00
4	TO RENEW FRONT WINDSCREEN.	S/N \$ 480.00	\$ 480.00
5	TO REMOVE AND REINSTALL BOTH FRONT SEATS FOR GLASS SHARD REMOVAL. INSPECT DASHBOARD AND CENTRE CONSOLE TRIMS FOR DAMAGES. AND RENEW IF NECESSARY.	S/N \$ 1,050.00	nil
SUB TOTAL LABOUR CHARGES		: \$ 6,930.00	\$ 3,160.00

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKF 5525 H

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 3,160.00
6	TO CARRY OUT INTERIOR AND EXTERIOR GROOMING INCLUSIVE OF VACUUM GLASS SPLINTERS AND CLEAN UP GLASS.	S/N	\$ 500.00	\$ 500.00
7	TO CARRY OUT WATER LEAKAGE TEST.	S/N	\$ 150.00	\$ 150.00
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	\$ 192.00
9	TO ARRANGE TOWING FROM ACCIDENT SCENE.		\$ 280.00	
10	TO REAPPLY PAINT COATING TO AFFECTED AREA.		\$ 400.00	\$ 300.00
TOTAL LABOUR CHARGES		:	\$ 8,452.00	\$ 4,302.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 5525 H

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	BONNET		\$ 2,763.00	\$ 2,210.40
2	BONNET IMPACT PROTECTION - CENTRE		\$ 27.00	\$ 21.52
3	BONNET IMPACT PROTECTION - LH		\$ 28.00	\$ 21.84
4	BONNET IMPACT PROTECTION - RH		\$ 27.00	\$ 21.52
5	PLENUM CHAMBER COVER		\$ 96.00	
6	AERO WIPER ARM - LH/RH	2	\$ 240.00	
7	AERO DYNAMIC WIPER BLADES SET		\$ 102.00	\$ 82.40
8	WATER DEFLECTOR STRIP - LH/RH	2	\$ 132.00	\$ 106.88
9	FRONT WINDSCREEN		\$ 1,125.00	\$ 900.00
10	RAIN SENSOR GEL FOIL		\$ 132.00	\$ 105.20
11	RETAINING SPRING		\$ 20.00	
12	INTERIOR MIRROR SPRING CLIP		\$ 21.00	
13	PRIMER		\$ 19.00	\$ 14.96
14	A-PILLAR TRIM - LH/RH	2	\$ 404.00	\$ 323.20
15	WINDSCREEN DEFROSTER NOZZLE GRILLE		\$ 122.00	
16	WINDSCREEN DEFROSTER NOZZLE		\$ 166.00	
17	DASHBOARD VENT TRIM - RH		\$ 424.00	
18	DASHBOARD VENT TRIM - LH		\$ 929.00	
19	DASHBOARD TRIM - LH		\$ 687.00	
20	DASHBOARD TRIM - RH		\$ 375.00	
SUB TOTAL SPARE PARTS		:	\$ 7,839.00	\$ 3,807.92

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKF 5525 H

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
	<i>c/f</i>		\$ 3,807.92
21 CENTRE CONSOLE TRIM INSERT		\$ 367.00	
22 CENTRE CONSOLE TRIM COVER FRAME		\$ 566.00	
23 WINDOW GUIDE - LH		\$ 446.00	
24 TRIM STRIP WINDOW GUIDE	2	\$ 254.00	\$ 202.80
25 CORNER TRIM - LH		\$ 45.00	\$ 35.84
26 WINDOW SLOT SEAL - LH		\$ 303.00	
27 WINDOW GUIDE TRIM STRIP		\$ 254.00	
28 FRONT DOOR WINDOW - RH		\$ 286.00	
29 FRONT WINDSCREEN SEALANT		\$ 200.00	\$ 200.00
30 FRONT WINDSCREEN IU BRACKET		\$ 26.00	\$ 26.00
31 SUNDRIES		\$ 300.00	\$ 3.20
TOTAL SPARE PARTS	:	\$ 10,886.00	\$ 4,275.76
TOTAL LABOUR CHARGES	:	\$ 8,452.00	\$ 4,302.00
GRAND TOTAL	:	\$ 19,338.00	\$ 8,577.76

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

bl-18/02/21



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0023/2021/NS 19/1/2021 CHANG 1 of 1 SKF 5525 H AUDI A4 SEDAN 2.0 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Labours</u>				
1	TO REMOVE CENTER CONSOLE, INSTRUMENT S/N PANELS AND CLUSTER. RENEW DASHBOARD AND TRANSER AIRBAG AND ALL FITTINS.	\$ 2,800.00		
<u>Parts</u>				
1	DASHBOARD	\$ 5,289.00		
GRAND TOTAL		\$ 8,089.00	nil	

For Premium Automobiles Pte Ltd

 Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LAOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT