## Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way

#09-16

Singapore 079120

LKK Auto Consultants Pte Ltd From:

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Date: 12 Jan 2021

### **Preliminary Advice**

Vehicle No : SKF5525H Accident Date : 04/01/2021 Make Policy No. : 2070006564 : AUDI A4 Assignment Date : 12/01/2021 **Excess** : S\$0.00 Date of Inspection : 11/01/2021 Est. Duration of Repair : 8

: PREMIUM AUTOMOBILES PTE LTD (UBI) Inspection At

55 UBI ROAD 1 SINGAPORE 408699

# Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,338.00
Revised Amount	:S\$	8,755.00
Check Items (Estimated)	:S\$	5,927.00
Total	:S\$	14,682.00

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	130,000.00
COE / PARF Rebate	:S\$	62,854.00
Salvage Value	:S\$	
Margin for Repair	:S\$	67,146.00

#### Remarks

( X	( )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(	)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
(	)	Other comments :