

A T AUTO CONSULTANT

113 Teck Whye Lane #05-650 Singapore 680113
 : 8386 8989
 Reg. No. : 53368526E

te of Estimate: 11.01.2021
 icle No: SLD1751X
 ner: PRAVEAN GANESH
 e of Accident: 08.01.2021
 ke & Model: Honda Vezel
 ssis No : RU11117163

IMATE FOR ACCIDENT VEHICLE NO SLD1751X

1	1 Tailgate	953
2	1 Tailgate moulding	165
3	1 Tailgate reflector RH	
4	1 Tailgate lock	
5	1 Tailgate striker	
6	1 Tailgate inner trim	
7	1 Tailgate windscreen seal	
8	1 Tailgate weatherstrip	148.50
9	1 Tailgate emblem "VEZEL"	
10	1 Rear corner apron garnish RH	235.10
11	1 Rear bumper	563.20
12	2 Rear bumper side retainer LH/RH	@ \$48
13	1 Rear bumper reflector RH	
14	1 Rear end panel	411.90
15	1 Rear end panel top garnish	166.80
16	1 Taillamp RH	
17	1 Remote key buzzer	
18	1 Remote key buzzer bracket	
19	1 Exhaust system	

SUB TOTAL
 LESS 20 %
 DISCOUNTED SUB TOTAL

EM

1set Rear bumper clips	
3pcs Rear end panel top garnish clips	@ \$5.00
1set Reverse sensor	
1set Reverse camera	

SUB TOTAL
 LESS 0 %
 DISCOUNTED SUB TOTAL

Panel beating for replace and repair affected parts	
Spray painting on accident areas	
Wiring charges	
Remove/refix reverse sensor	
Remove/refix reverse camera	
Transfer tailgate glass	
Transfer tailgate component	
Apply undercoating to above affected areas	

SUB TOTAL (LABOUR)

SUB TOTAL (S.NETT ITEM)

Not Authoized
 11 Pm B. 48501
 Penny After Pain
 8days

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary Item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Al	\$1,098.00	✓
me	\$269.00	✓
in	\$386.00	X
Red	\$238.00	✓
n	\$85.00	X
n	\$299.00	X
me	\$85.00	✓
GT	\$286.00	508in
me	\$58.00	✓
Red	\$276.00	2
me	\$986.00	✓
in	\$96.00	X
mgm	\$151.00	✓
BT	\$588.00	7
mgm	\$252.00	7
in	\$586.00	X
CR	\$88.00	2
in	\$18.00	7
n	\$960.00	X
	\$6,805.00	
	\$1,007.07	
	\$5,797.93	

me	\$50.00	✓
me	\$15.00	2
Red	\$320.00	200in
in	\$350.00	X
	\$735.00	
	\$0.00	
	\$735.00	

	\$1,000.00	600l
	\$800.00	450l
	\$100.00	15l
	\$100.00	50l
nn	\$100.00	X
	\$180.00	120l
	\$150.00	60l
	\$120.00	30l
	\$2,550.00	

\$735.00

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113

HP: 8386 8989

Co. Reg. No. : 53368526E

Date of Estimate: 11.01.2021

Vehicle No: SLD1751X

Owner: PRAVEAN GANESH

Date of Accident: 08.01.2021

Make & Model: Honda Vezel

Chassis No : RU11117163

SUPPLEMENTARY ESTIMATE FOR ACCIDENT VEHICLE NO SLD1751X

PARTS

- | | | |
|---|---|---------------------------------|
| 1 | 1 | Rear spare tyre floor panel |
| 2 | 1 | Rear spare tyre floor tow panel |
| 3 | 1 | Rear floor compartment tool box |
| 4 | 1 | Rear floor lower garnish |

SUB TOTAL
LESS 20 %
DISCOUNTED SUB TOTAL

<i>PR</i>	\$789.20	<i>✓</i>
<i>PR</i>	\$145.80	<i>✓</i>
<i>CM</i>	\$239.50	<i>✓</i>
<i>CM</i>	\$223.50	<i>✓</i>
	<u>\$1,398.00</u>	
	<u>\$327.20</u>	
	<u>\$1,070.80</u>	

BOUR

- | | |
|---|---|
| 1 | Panel beating for replace of rear floor panel |
| 2 | Apply sealant undercoating for rear floor panel |

SUB TOTAL (LABOUR)

\$900.00	<i>Good</i>
\$120.00	<i>3rd</i>
<u>\$1,020.00</u>	