

ASSIGNMENT

21000510/kg
 VEH No: SLD 1751X Yr Regn: 001
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Vezel
 Colour: m. Black
 Chassis No: 68143
 C.C. 1496
 Insured / Std / NI / NA
 T/Radio: Insured / Std / NI / NA
 1117163

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
 HP: 8386 8989
 Co. Reg. No.: 53368526E

Date of Estimate: 11.01.2021
 Vehicle No: SLD1751X
 Owner: PRAVEAN GANESH
 Date of Accident: 08.01.2021
 Make & Model: Honda Vezel
 Chassis No: RU11117163

ESTIMATE FOR ACCIDENT VEHICLE NO SLD1751X

PARTS

1	1 Tailgate	953
2	1 Tailgate moulding	165
3	1 Tailgate reflector RH	
4	1 Tailgate lock	
5	1 Tailgate striker	
6	1 Tailgate inner trim	
7	1 Tailgate windscreen seal	
8	1 Tailgate weatherstrip	148.50
9	1 Tailgate emblem "VEZEL"	
10	1 Rear corner apron garnish RH	235.10
11	1 Rear bumper	563.20
12	2 Rear bumper side retainer LH/RH	
13	1 Rear bumper reflector RH	
14	1 Rear end panel	411.90
15	1 Rear end panel top garnish	166.80
16	1 Taillamp RH	
17	1 Remote key buzzer	
18	1 Remote key buzzer bracket	
19	1 Exhaust system	

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

@ \$48

SUB TOTAL
 LESS 20 %
 DISCOUNTED SUB TOTAL

S. NETT ITEM

1	1set Rear bumper clips	
2	3pcs Rear end panel top garnish clips	
3	1set Reverse sensor	
4	1set Reverse camera	

SUB TOTAL
 LESS 0 %
 DISCOUNTED SUB TOTAL

LABOUR

1	Panel beating for replace and repair affected parts	
2	Spray painting on accident areas	
3	Wiring charges	
4	Remove/refix reverse sensor	
5	Remove/refix reverse camera	
6	Transfer tailgate glass	
7	Transfer tailgate component	
8	Apply undercoating to above affected areas	

SUB TOTAL (LABOUR)

SUB TOTAL (S.NETT ITEM)

Page 1 of 2

Not Authorized

11 Rm B 3500h
 Penny After Pain
 5days

As	\$1,098.00	✓
me	\$269.00	✓
me	\$386.00	X
Red	\$238.00	✓
me	\$85.00	X
me	\$299.00	X
me	\$85.00	✓
me	\$286.00	501.50
me	\$58.00	✓
Red	\$276.00	✓
me	\$986.00	✓
me	\$96.00	X
me	\$151.00	✓
me	\$588.00	✓
me	\$252.00	✓
me	\$586.00	X
me	\$88.00	✓
me	\$18.00	✓
me	\$960.00	X
	\$6,805.00	
	\$1,007.07	
	\$5,797.93	

me	\$50.00	✓
me	\$15.00	✓
Red	\$320.00	200.00
me	\$350.00	X
	\$735.00	
	\$0.00	
	\$735.00	

	\$1,000.00	600
	\$800.00	450
	\$100.00	150
	\$100.00	50
me	\$100.00	X
	\$180.00	120
	\$150.00	60
	\$120.00	30
	\$2,550.00	

\$735.00