



not Authorized

date  
2/5 @ 2500  
Hdys.  
When plus after rep.

**NINETEEN AUTOWERKS PTE LTD**

Blk 13 Kaki Bukit Road 4 #01-05  
Bartley Biz Centre, Singapore 417807  
Tel: (65) 9270 5882  
nineteenautowerks@gmail.com

Date : 12-Jan-21

Registration no. : SLC1260B / Mazda 2 Sedan 1.5L SP.6EAT

DOA : 9-Jan-21

Estimate No. : 19A029\_SLC1260B\_MAZDA2

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Bootlid	11	982.00	X
2	1	Bootlid logo	11	128.00	X
3	1	Bootlid emblem " MAZDA 2 "	11	115.50	X
4	1	Bootlid emblem " SKYACTIV "	11	116.00	X
5	2	Bootlid reflector @ SGD 392.00	11	784.00	X
6	1	Bootlid inner trim	11	214.50	X
7	1	Bootlid inner lock	11	286.40	X
8	1	Bootlid lock switch	11	117.80	X
9	1	Bootlid lock sensor	11	168.70	X
10	1	Bootlid weatherstrip	11	285.70	X
11	2	Rear number plate lamp @ SGD 72.00	11	144.00	X
12	1	Rear bumper	100/100	896.00	/
15	1	Rear bumper lower >complete.		376.00	X
13	2	Rear bumper side retainer @ SGD 128.30	11	256.60	X
14	2	Rear bumper reflector @ SGD 64.70	11	129.40	X
15	1	Rear bumper lower cover	11	127.00	X
16	1	Rear end panel	100 600.50	829.00	/
17	1	Rear end panel top garnish	11	227.00	/
18	2	Taillamp @ SGD 697.50	11	1395.00	X
18	2	Taillamp lower bracket @ SGD 94.20	11	188.40	X
20	1	Rear fender inner shield @ SGD 152.00	11	304.00	X
20	1	Rear fender inner trim @ SGD 224.00	11	448.00	X
21	1	Exhaust pipe assy	11	896.00	X
				9415.00	
			Less 20%	1883.00	
				7532.00	



**NINETEEN**  
AUTOWERKS

**NINETEEN AUTOWERKS PTE LTD**

Blk 13 Kaki Bukit Road 4 #01-05  
Bartley Biz Centre, Singapore 417807  
Tel: (65) 9270 5882  
nineteenautowerks@gmail.com

Date : 12-Jan-21

Registration no. : SLC1260B / Mazda 2 Sedan 1.5L SP.6EAT

DOA : 9-Jan-21

Estmate No. : 19A029\_SLC1260B\_MAZDA2

S/N	Qty	Item	Amount
-----	-----	------	--------

SPECIAL NETT ITEMS

1	1	Sundries	11	60.00	X
2	1	Bootlid sealant	11	100.00	X
3	2set	Bootlid reflector clips @ SGD 20.00	11	40.00	X
4	2	Bootlid reflector seal @ SGD 30.00	11	60.00	X
5	1set	Bootlid inner trim clips	11	35.00	X
6	1set	Rear bumper clip	net	80.00	50
7	2set	Taillamp clip @ SGD 25.00	11	50.00	X
8	2	Taillamp seal @ SGD 35.00	11	70.00	X
9	1set	Rear end panel top garnish clips	11	30.00	X
10	1	Rear end panel sealant	net	100.00	50
11	2set	Rear fender inner shield clips @ SGD 45.00	11	90.00	X
12	2set	Rear fender inner trim clips @ SGD 55.00	11	110.00	X
13	1set	Reverse sensor c/w control module	15 hours	300.00	200
				1125.00	
<b>Parts Total</b>				<b>8657.00</b>	

LABOUR & MISC CHARGES

1	1	Panel beating and strenghten parts on accident area.		1800.00	600
2	1	Check wiring system after disconnect and connect.		80.00	20
3	1	R&R interior upholstery.		200.00	80
4	1	R&R bootlid component.	11	100.00	X
5	1	R&R exhaust pipe.	11	300.00	X
6	1	R&R reverse sensor and check		100.00	50
7	1	To apply undercoating for rust roofing.	Repainted	200.00	X
8	1	Spray painting on accident area.		1500.00	700
<b>Labour Total</b>				<b>4280.00</b>	

**Total Parts and Labour Cost of Repair**

12937.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1723-50  
202  
P-1378.80  
S-12300-00  
1450-00  
3,288.80  
207  
2507

Page 2 of 5