

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000527/QQD3E2

Date: 27/01/2021

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00025842001

**Claimant Vehicle
No :** SBS6827T

**Insured Vehicle
No :** GBH3248S

Date of Loss: 03/01/2021

Nature of Claim: TP

Claim
No: SNM21D200170/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS6827T**

Make & Model: MERCEDES-BENZ CITARO O530, 6.4 D (A)

Engine No: 902926C1068979

Reg. Date: 02/01/2015 (Man. Year: 2014)

Chassis No: WEB62808323125487

Colour: Multi-colour

Odometer: 4019562 km

Engine Capacity: 6374 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5 (D)

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6/6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	750.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	750.00	750.00	0.00	0.00

INSPECTION

Date of Assignment: 12/01/2021

Date Inspected: 12/01/2021

Inspected At:

SBS Transit Ltd (YCK)
3 Yio Chu Kang Crescent
Singapore 786010

Estimated Period of Repair: 2.0 days

Adjuster: OI SUN PIN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Jan 2021)	
Parts:	N/A	MERCEDES-BENZ CITARO O530 6.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS6827T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRONT WINDSCREEN-REPLACE WIPER-REPAIR FRONT CENTER SERVICE HATCH COVER-SPRAY PAINTING FRONT CENTER SERVICE HATCH COVER	New	750.00	750.00
Gross Labour Cost (\$\$)			750.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >